



Service Bulletin

File in Section: -

Bulletin No.: PI0373A

Date: October, 2012

PRELIMINARY INFORMATION

Subject: Power Foldaway Mirror Glass Shakes, Flutters at Normal Driving Speeds

Models: 2013 and Prior GM Passenger Cars and Light Duty Trucks
Equipped with Power Foldaway Mirrors

This bulletin is being revised to add the 2012 and 2013 model years. Please discard PI0373.

Condition/Concern

Some customers may comment that the outside power foldaway mirror glass shakes or flutters while driving at normal speeds. Customer may also comment that the mirror(s) will not stay in the unfolded position.

This condition may be caused by the mirror(s) being manually folded and/or unfolded or the mirror(s) being obstructed while (power) folding.

Recommendation/Instructions

Note: For full size trucks, refer to the latest version of Corporate Bulletin Number 06-08-64-027 for additional vehicle specific information.

Follow the procedure below to correct this condition:

Fold and unfold the mirrors one time using the mirror controls to reset them to their normal position. A popping noise may be heard during the resetting of the power foldaway mirrors. This sound is normal after a manual folding operation.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
B9798*	Relearn Power Folding Mirrors and Road Test	0.3 hr

*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.