

Blown No. 5 Fuse in Under-Dash Fuse/Relay Box; Engine Starting and/or Multiple Electrical Issues

AFFECTED VEHICLES

2013–16 Accord L4 (EX-L and above), 2013–16 Accord V6, 2014-15 Accord Hybrid, and 2014 Accord Plug-In

Do you have a vehicle in your shop for any or all of these issues?

- The No. 5 METER (10 A) fuse in the under-dash fuse/relay box is blown.
- The engine cranks, but it won't start.
- The engine starts, then stops.
- The instrument panel is blank.
- The rearview mirror won't automatically dim.

We're aware of these issues and currently have them under investigation.

One common problem that can cause any one of them is damage in the roof wire harness. Unplug the connector from the rearview mirror, carefully pull back the harness sheathing, and check if any of the wires are cut or are pulled out from the connector. If so, replace the harness.