

Technical Information

Service

43/12 ENU **WC35**

WC35 - Checking Relays for Engine-Compartment Blower (Workshop Campaign)

Vehicle Type: 911 Carrera (991)/911 Carrera S (991) - Cabriolet

Model Year: 2012

Concerns: Relay for engine-compartment blower

Revision 1: July 3, 2012, "or equivalent" was added to the Deutronic Battery Charging Computer listed under

"Tools".

Information: This is to inform you of a voluntary Workshop Campaign on the above-mentioned vehicles. There is the

> possibility that the relay for setting 1 of the engine-compartment blower is not inserted correctly in the relay carrier on the affected vehicles. If the relay is not inserted correctly, the function of setting 1 of the engine-compartment blower cannot be guaranteed and the driver will see a warning to this effect in the multi-function display. To remedy the situation, check that the engine-compartment blower relay is seated

correctly in the relay carrier.

Affected The VIN(s) can be checked by using PIWIS Vehicle Information link to verify if the campaign affects the Vehicles:

vehicle. This Campaign is scope specific to the VIN! Failure to verify in PIWIS may result in an improper

repair.

Parts Info: Only required if the flat plugs of the relay are damaged:

> 999.657.014.90 ⇒ Relay for engine-compartment blower As many as required

> > (max. 2)

Tools: PIWIS Tester II 9818

Deutronic Battery Charging Computer DBL1600-14 1391 or equivalent

Work See Attachment "A".

Procedure:

9

Service

WC35 ENU **43/12**

Technical Information


Administrative Procedure:

See Attachment "B".



Information

The engine-compartment blower relays to be checked are in relay carrier 2 close to the right convertible top mechanism, between the roll-over protection system frame and the engine bulkhead \Rightarrow *Installation position of relays for engine-compartment blower*.



Installation position of relays for engine-compartment blower

Attachment "A": Work Procedure

Check relays for engine-compartment blower.

1 Release relay carrier ⇒ Workshop Manual '9790IN Loosening and securing relay carrier - section on "Removing"'.

43/12 ENU WC35

2 Remove both engine-compartment blower relays \Rightarrow Figure 1 -2- from the relay carrier \Rightarrow Figure 1 -2-.




Figure 1

Check both engine-compartment blower relays.
If one of the flat plugs on the relay is bent ⇒ Figure 2
-arrow-, the relay must be replaced.




Figure 2

If a flat plug is bent, check the **plug sockets** in the relay carrier \Rightarrow Figure 3 -arrow - for **deformation** and bend them into shape again using a suitable tool if necessary.




Figure 3

Service

WC35 ENU **43/12**

Technical Information

- 4 Press both engine-compartment blower relays ⇒ Figure 4-1- into the defined slot on the relay carrier ⇒ Figure 4-2- and check that they are seated correctly.
- 5 Secure relay carrier ⇒ Workshop Manual '9790IN Loosening and securing relay carrier section on "Installing"'




Figure 4


Procedure:

Perform on-board diagnosis on relays for engine compartment purge fan.

1 Preliminary work.

- 1.1 Connect a battery charger with a current rating of **at least 40 A**.
 - First connect the positive cable of the charger to the positive terminal of the battery and then connect the negative cable of the charger to the ground point for jump-lead starting \Rightarrow External power connection.
- 1.2 PIWIS Tester II 9818 must be connected to the vehicle communication module (VCI). Then, connect the communication module to the vehicle and switch on the PIWIS Tester.
- 1.3 On the PIWIS Tester start screen, call up the ⇒ 'Diagnostics' menu and select the vehicle type.

The diagnostic application is then started and the control unit selection screen is populated.



External power connection

2 Perform drive links test on engine compartment purge fan setting 1 and setting 2.

- 2.1 In the control unit selection screen \Rightarrow ***Overview**' menu), select "DME" control unit and press F12 to confirm your selection.
- 2.2 Skip the question as to whether you want to create a vehicle analysis log (VAL) by pressing F11 .
- 2.3 Once the DME control unit has been found, select the \Rightarrow 'Drive links/checks' menu.
- 2.4 Select the \Rightarrow 'Drive links' function and press F12 to confirm.

Technical Information

Service

9

43/12 ENU WC35

- 2.5 Select drive link ⇒'Engine compartment purge fan setting 1 (Low)' and press F12 to confirm your selection.
- 2.6 Start drive link for engine compartment purge fan setting 1 (Low)' by pressing F8 ("Execute").
 - Both engine compartment purge fans are activated and the value '100%' appears in the 'Results' field. Activation of the engine compartment purge fan is signalled acoustically.
- Once the test is completed successfully, replace the value '100%' with the value '0%' and continue by pressing F8 to stop the activation of the drive links.
- 2.8 As soon as the drive links test on engine compartment purge fan setting 1 (Low) has been completed, press F11 to go back and perform the drive links test on **engine compartment purge fan setting 2 (High)** in accordance with Steps 2.5 to 2.7.
- 2.9 Once the drive links test is completed successfully, press **F11** to return to the control unit selection screen (⇒ 'Overview' menu).

3 Read out and erase fault memories.

- 3.1 In the control unit selection screen (⇒ 'Overview' menu), press F7 to call up the Additional menu
- 3.2 Select the function ⇒ 'Read all fault memories and erase if required' and press (>>) to confirm.

The fault memories of the control units are read out.

- Once you have read out the fault memories, erase the fault memory entries by pressing F8.
- 3.4 Press F12 ("Yes") in response to the question as to whether you really want to erase all fault memory entries.

The faults stored in the fault memories of the various control units are deleted.



Information

If control units are found to have faults, which cannot be erased and are not associated with checking the engine-compartment blower relay, these faults must be found and corrected. This work **cannot** be invoiced under the workshop campaign number.

3.5 Once you have erased the fault memories, select the ⇒ 'Overview' menu and press << to return to the control unit selection screen.

4 Subsequent work.

- 4.1 Switch off ignition.
- 4.2 Disconnect the PIWIS Tester from the vehicle.
- 4.3 Switch off and disconnect the battery charger.

Technical Information

Labor time: 60 TU

5 Enter the workshop campaign in the Warranty and Maintenance booklet.

Attachment "B" Administrative Procedure - Workshop Campaign WC35

Warranty claims should be submitted via WWS/PQIS.

Note: Open campaigns can be checked by using the PIWIS Vehicle Information link.

Labor, parts, and sublet will be automatically inserted when Technician is selected in WWS/POIS.

Invoicing

Scope 1: Only valid for the 911 Carrera (991)/911 Carrera S (991) - Coupé - see Technical Information for

this vehicle type.

Scope 2: Checking relays for engine-compartment blower – 911 Carrera (991)/911 Carrera S (991) - Cabriolet

Working time:

Checking relays for engine-compartment blower

Includes: Moving convertible top to service position

Removing and installing rear cover

Removing and installing trim panel for convertible top

compartment

Loosening and securing relay carrier

Connecting and disconnecting battery charger Connecting and disconnecting PIWIS Tester

Performing drive links test on engine compartment purge

fan

Reading out and erasing fault memories

Parts required (only if necessary):

999.657.014.90 Relay for engine-compartment blower 2 ea.

Invoicing: \Rightarrow Damage code WC35 066 000 1

References: ⇒ Workshop Manual '6101IN Convertible-top service position'

- ⇒ Workshop Manual '705319 Removing and installing rear cover'
- ⇒ Workshop Manual '700819 Removing and installing trim panel for convertible top compartment'

43/12 ENU WC35

⇒ Workshop Manual '9790IN Loosening and securing relay carrier'

Important Notice: Porsche Cars N.A Technical Bulletins are intended for use by professional technicians, not a "Do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Special tools may be required to perform certain operations identified in these bulletins. Use of tools and procedures other than those recommended in these bulletins may be detrimental to the safe operation of your vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safety. If a condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Porsche Dealer for information on whether your vehicle may benefit from the information. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify correct part numbers.

Dealership	Service Manager	Shop Foreman	Service Technician		
Distribution	0 0 1 1 1 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1	 ·		 	
Routing	Asst. Manager	 Warranty Admin.	 Service Technician	 	

Dr. Ing. h.c., F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayenne®, Cayenne®, Tiptronic®, VarioCam®, PCM®, 911®, 45®, FOUR, UNCOMPROMISED.® and the model numbers and distinctive shapes of Porsche's automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Some vehicles may be shown with non-U.S. equipment. Porsche recommends seat belt usage and observance of traffic laws at all times.