

<b>Technical Service Bulletin Number</b>
--

TSB170031
-----------



## Technical Service Bulletin

### Subject

---

Fault Code 6255 Present With No Other Fault Codes

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

#### Product Affected

- B6.7 CM2350 B121B
- ISB6.7 CM2350 B101
- ISL9 CM2350 L101
- ISX12 CM2350 X102
- ISX15 CM2350 X101
- L9 CM2350 L116B
- X15 CM2350 X114B
- X15 CM2350 X116B

#### Issue

Symptom:

- **Only** Fault Code 6255 present (active).

Root Cause:

- Engine control module (ECM) calibration code issue.

## Resolution

- Calibrate ECM using a January 2017, or later, INCAL™ DVD. Reference ECM Calibration Revision History on QuickServe™ Online for more information.
- See corresponding Service Manual. Reference Procedure 019-032 in Section 19.
- If any fault codes other than Fault Code 6255 are active, troubleshoot fault codes using corresponding troubleshooting tree.

## Document History

---

Date	Details
2017-3-17	Module Created

---

**Last Modified: 28-Mar-2017**

---

Copyright © 2000-2010 Cummins Inc. All rights reserved.