# **Technical Service Bulletin**

Topic Steering rack noise during extended city drive				
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)			
Brand	Bentley			
Transaction No.	2046733/2			
Level	EH			
Status	Released for publishing			
Release date	Mar 8, 2017			

### New customer code

Object of complaint	Complaint type	Position
Chassis -> Steering, steering assist -> Steer	Noises, vibrations -> Noise	

### New workshop code

Object of complaint	Complaint type	Position
Chassis -> Steering -> Steering gear -> Electromechanical steering torque	Component, automotive fluids -> Installed	
sensor	incorrectly	

# Vehicle data

## **Bentayga**

### Sales types

Туре	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	E		*	*	*

#### Chassis numbers

Manufacturer	Filler	Туре	Filler	MY	Factory	From	То	<b>Prod from</b>	Prod to
SJA	***	**	*	*	*	000001	013900		

# **Documents**

Document name master.xml

ï

Transaction No.: **2046733/2**Release date: Mar 8, 2017

#### **Condition**

Steering grinding noise after vehicle driven for extended period in city conditions

#### **Technical Background**

Steering rack internal torque sensor defective

#### **Production Solution**

Redesigned torque sensor

#### **Service**

In the event of the above customer complaint, then check the steering rack part number. A steering rack with part number 4N1423053E and a generation code of 06S or lower is suspect and should therefore be changed if the symptom detailed in this TPI has been reported by the owner.

**Note:** Steering racks with part number 4N1423053F irrespective of generation code are considered 'good' and therefore not associated with this TPI symptom



Figure 1

The example figure 1 details the steering rack part number and code on the body of the unit. In this example the part number is 4N1423053E and generation code is 07S this generation code is higher than 06S therefore this part would not have to be replaced in respect to the symptom detailed in this TPI

**Note:** The above references left hand drive part numbers there is the potential for this failure to occur on right hand drive cars in that instance the suspect steering rack part number would 4N2423053E 06S or lower