

TECHNICAL BULLETIN

K430NAS1

02 NOV 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-17

Service Action: Roof Opening Panel Air Deflector Springs Displaced

AFFECTED VEHICLE RANGE:

F-PACE (X761)

Model Year: 2017
VIN: 045409-062601 Vehicles With: Roof Opening Panel
Assembly Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

Situation: An issue has been identified on a limited number of vehicles within the listed Affected Vehicle Range where the roof opening glass panel cannot be closed and/or the wind deflector spring may become displaced.

Action: Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Service Instruction detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:



NOTE: Order only the expected percentage demand of parts identified.

| DESCRIPTION | PART No./SUNDRY CODE | QTY./VALUE | EXPECTED % of VEHICLES REQUIRING PARTS |
|-------------|----------------------|------------|--|
| Seal | T2H26120 | 2 | 100 |

SPECIAL TOOLS:

Refer to Workshop Manual/Service Instruction for any required special tools.

WARRANTY:



NOTE: Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code **K430** together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.


This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 October 2018** closure date must be submitted or payment within 30 calendar days of completion of the repair.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

| PROGRAM CODE | OPTION CODE | DESCRIPTION | SRO | TIME (HOURS) | PARTS/SUNDRY CODE | QTY./VALUE |
|--------------|-------------|---|----------------------|--------------|-------------------|------------|
| K430 | B | Install the edge finisher on the roof opening panel | 76.82.62 | 0.10 | T2H26120 | 2 |
| K430 | C | Install the edge finisher on the roof opening panel Drive in/drive out | 76.82.62 10.10.10 | 0.10 0.20 | T2H26120 - | 2 - |


Normal Warranty policies and procedures apply.

SERVICE INSTRUCTION:

1. Switch the ignition ON (engine not running).
2. Open the roof opening panel to its fully open position.
3. Switch the ignition OFF.
4.  **NOTE: Left-side shown; right-side similar.**

 **NOTE: Parts shown removed for clarity.**

Locate the area shown.



5. Cut and discard 20 mm from the rubber seal.



E193537

6.  **NOTE: Right-side shown; left-side similar.**


 **NOTE: Seal length: 60 mm.**

Install the rubber seal



7.  **NOTE: Right-side shown; left-side similar.**

Visually check that the rubber seal is installed correctly as shown.



- 8.** Repeat steps 4-7 to the other side.
- 9.** Switch the ignition ON (engine not running).
- 10.** Close the roof opening panel.
- 11.** Switch the ignition OFF.