



Service Bulletin

File in Section: 06 - Engine

Bulletin No.: 07-06-04-025K

Date: November, 2014

INFORMATION

Subject: Information on Clicking/Ticking Sound/Noise Heard During Cold Start

Models: 2009-2015 Buick Enclave
 2010-2015 Buick LaCrosse
 2008-2011 Cadillac STS
 2008-2015 Cadillac CTS
 2010-2015 Cadillac SRX
 2013-2015 Cadillac ATS, XTS
 2009-2015 Chevrolet Traverse
 2010-2015 Chevrolet Camaro, Captiva, Equinox
 2011-2015 Chevrolet Caprice PPV
 2012-2015 Chevrolet Impala Limited
 2014-2015 Chevrolet Impala
 2015 Chevrolet Colorado
 2009-2015 GMC Acadia
 2010-2015 GMC Terrain
 2015 GMC Canyon
 2009-2010 Saturn OUTLOOK
 Equipped with 3.0L or 3.6L VVT Direct Injection V6 Engine (VINs G, D, 5, V, Y, 3 – RPOs LF1, LFW, LLT, LFX)

This bulletin has been revised to add the 2015 Colorado and Canyon. Please discard Corporate Bulletin Number 07-06-04-025J.

Do This	Don't Do This
Inform the customer that this is normal operation of the high pressure fuel pump and injectors.	DO NOT replace the high pressure fuel pump and/or injectors.

The 3.0L and 3.6L SIDI engines use a direct injection fuel system that operates at very high fuel pressures. A direct injection fuel system produces a rapid clicking and ticking sound that can be heard from the engine compartment. The sound is more evident when outside around the vehicle or when the hood is open. The sound is more noticeable during idle and is more frequent during a cold start, but lessens once the engine is warm.

The rapid ticking noise on cold start up is the fuel pump (located on the rear of the left cylinder head) building up high fuel pressure. When the engine warm-up is completed, the high pressure fuel pump will continue to tick at a lower rate of approximately one tick per second during idle. The clicking sound is the fuel injectors pulsing on and off under higher fuel pressures. This sound is a normal characteristic of Direct Injection Fuel high pressure fuel system.

DO NOT attempt to repair or replace any parts for this kind of clicking or ticking concern. The clicking or ticking sound is not indicative of any concerns with the engine or the vehicle. You may wish to give the customer a copy of this bulletin.