

LTB01042NAS1

TECHNICAL BULLETIN

10 MAY 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

310-01C: Fuel Tank and Lines

SUBJECT/CONCERN:

Fuel Filler Hose Delamination

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Discovery Sport (LC)	2015-2017	500429-669157	Halewood	GTDi 2.0L Petrol/GTDi 2.0L Petrol - SULEV

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The fuel tank may be difficult to fill with fuel.

CAUSE:

This may be caused by the fuel filler hose being delaminated internally.

ACTION:

Should a Customer express this concern, follow the Workshop Procedure below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY:
LR104413	Fuel filler hose	1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Fuel pipe - Renew	19.40.12	0.3	34	LR104307


NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

-
- 1 Remove the rear right wheel and tire (see TOPIx Workshop Manual section 204-04: Wheels and Tires - Removal and Installation).
-


2



E166421

Remove the rear right splash shield.

3



Remove the fuel pipe trim.


4

WARNING:

Be prepared to collect escaping fuel.

NOTE:

Do not discard the existing top hose fastener.



Remove the fuel pipe.


5

WARNING:

Be prepared to collect escaping fuel.

NOTE:


Install using the existing top hose fastener.



Install the new fuel pipe.

- Torque: **3.2Nm**.
-

6



Install the fuel pipe trim.

- Torque: **7Nm**.

