

LTB01018NAS1

# TECHNICAL BULLETIN

05 DEC 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

---

---

**SECTION:**

307-01

**SUBJECT/CONCERN:**

Delay/Hesitation In Transmission Gear Selection

**AFFECTED VEHICLE RANGE:**

<b>MODEL:</b>	<b>MODEL YEAR:</b>	<b>VIN:</b>	<b>ASSEMBLY PLANT:</b>	<b>APPLICABILITY:</b>
Discovery Sport (LC)	2015 Onwards	501001 Onwards	Halewood	GTDi 2.0L Petrol - SULEV, Vehicles With: 9HP48 9-Speed Automatic Transmission - AWD
Range Rover Evoque (LV)	2015 Onwards	955857 Onwards	Halewood	GTDi 2.0L Petrol - SULEV, Vehicles With: 9HP48 9-Speed Automatic Transmission - AWD

**MARKETS:**

NAS

**CONDITION SUMMARY:****SITUATION:**

Vehicle acceleration may be interrupted by a delay/hesitation in transmission gear selection. A four-second delay in acceleration occurs when a fifth-gear downshift is requested when the accelerator pedal is

in the depressed position at low vehicle speeds, during warm up when the ambient temperature is 39°F / 4°C and lower.

**CAUSE:**

This may be caused by incorrect ball valve operation in the transmission valve block.

**ACTION:**

Should a Customer express this concern, follow the Service Instruction below.

---

**PARTS:**

**NOTE:**

**The transmission Valve Block may also be referred to as Valve Body Assembly or Hydraulic Control Unit.**

PART NUMBER	DESCRIPTION	QUANTITY:
LR086164	Valve - Hydraulic Control Unit	1
LR023288	Transmission Fluid	2
LR049876	Service Kit	1

---

**TOOLS:**

Refer to Workshop Manual for any required special tools.

---

**WARRANTY:**

**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Valve body assembly - Renew - Discovery Sport (L550)	44.40.01	1.7	42	LR086164 / LR023288 / LR049876
Valve body assembly - Renew - Range Rover Evoque (L538)	44.40.01	1.9	42	LR086164 / LR023288 / LR049876

**NOTE:**

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

---

- 1 Remove and discard the valve block (see TOPIx Workshop Manual section: 307-01 Automatic Transmission/Transaxle - Main Control Valve Body).
- 2 Install a new valve block (see TOPIx Workshop Manual section: 307-01 Automatic Transmission/Transaxle - Main Control Valve Body).

