



ABOVE & BEYOND

## SERVICE ACTION Q627: NO SERVICE INTERVAL REQUIRED MESSAGE DISPLAYED IN THE MESSAGE CENTER

## SERVICE BULLETIN

12-JAN-17

No.: SGI17-03

SEC.: GENERAL  
INFORMATION

MKT.: CAN / USA

### DESCRIPTION OF ISSUE

A potential issue has been identified on certain vehicles within the listed Affected Vehicle Range where no service interval required message is displayed in the message center when an engine service is required after covering the appropriate distance/time in service.

### AFFECTED VEHICLES

Discovery Sport (L550)

Model Year: ..... 2015-2017

VIN: ..... 501001-627258

Visit the InfoTrail website for a list of affected unsold vehicles (as of 11 January 2017).

### ACTION TO BE TAKEN

Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the rework action.

Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin Q627NAS, *Service Action: No Service Interval Required Message Displayed in the Message Center*, for detailed repair instructions.

### PARTS

No parts required.

### TOOLS

Refer to the Technical Bulletin noted above for any required tools.

### WARRANTY

**NOTE: check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.**

At the time of confirming a booking for vehicle repair, ensure that all outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **30 December2018** expiry date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NO. / SUNDRY CODE	QTY. / VALUE
Q627	B	CCF update	86.90.24	0.20	-	-
Q627	C	CCF update	86.90.24	0.20	-	-
		Drive in/drive out	02.02.02	0.20	-	-
Q627	D	CCF update	86.90.24	0.20	-	-
		Disengage/engage transit	86.90.89.47	0.10	-	-
Q627	E	CCF update	86.90.24	0.20	-	-
		Disengage/engage transit	86.90.89.47	0.10	-	-
		Drive in/drive out	02.02.02	0.20	-	-

*Normal Warranty policies and procedures apply.*