

## Technical Information

Service 233/15 ENU WF23 2

### WF23 - Removing Water Drain Valves On Air Cleaner Housing (Workshop Campaign)


Vehicle Type:	911 Turbo Cabriolet (991)/911 Turbo S Cabriolet (991)					
Model Year:	2014					
Concerns:	Water drain valves on air cleaner housing					
Information:	This is to inform you of a voluntary Workshop Campaign on the above-mentioned vehicles. In certain environmental conditions, e.g. during heavy rain, there is a possibility that water can get int the air cleaner housing via the engine compartment lid on the affected vehicles. Depending how much water has leaked in, the water may not be able to drain away quickly enough thro the water drain valves provided for this purpose.					
	As a result, there is a possibility that the air cleaner will age prematurely because of the increased wet and dry phases. This can cause reduced filter throughput and the customer may notice reduced engine power as a result.					
Action Required:	Remove water drain valves on the air cleaner housing to guarantee that the water that has leaked in ca drain away fully.					
Affected Vehicles:	The VIN(s) can be checked by using PIWIS Vehicle Information link to verify if the campaign affects the vehicle. This campaign is scope specific to the VIN! Failure to verify in PIWIS may result in an improper repair. This campaign affects 336 vehicles in North America.					
Tools:	<ul> <li>Torque wrench, 2 – 10 Nm (1.5 – 7.5 ftlb.), e.g.V.A.G 1783 - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.)</li> <li>Torque wrench, 6 – 50 Nm (4.5 – 37 ftlb.), e.g. V.A.G 1331 - Torque wrench, 6-50 Nm (4.5-37 ftlb.)</li> <li>Plastic wedge</li> </ul>					
Work Procedure:	See Attachment "A".					
Claim Submission:	See Attachment "B".					
Attachment "A":	Work Procedure					
	1 Remove engine-compartment blower $\Rightarrow$ Workshop Manual '198119 Removing and installing engine- compartment blower'.					

- 2 Remove tail lights  $\Rightarrow$  Workshop Manual '943119 Removing and installing tail light'.
- 3 Remove rear spoiler  $\Rightarrow$  Workshop Manual '665819 Removing and installing rear spoiler (Turbo)'.
- 4 Remove air cleaner housing ⇒ Workshop Manual '242519 Removing and installing air cleaner housing'.

# i Information

The fastening pins  $\Rightarrow$  Fastening pins for water drain valves -1- for the water drain valves  $\Rightarrow$  Fastening pins for water drain valves -2- can break off and fall into the air cleaner housing if the water drain valves are not pulled off carefully.

If this happens, the **air cleaner housing must be opened** and the broken **fastening pins** must be removed from the air cleaner**housing**.




Fastening pins for water drain valves

5 Remove all **four** water drain valves on the underside of the air cleaner housing ⇒ *Removing water drain valves* -top-.

To do this, pull each water drain valve  $\Rightarrow$  *Removing* water drain valves -2- out carefully until the fastening pin  $\Rightarrow$  *Removing water drain valves* -1- comes away from the air cleaner housing.

- 6 Install air cleaner housing ⇒ Workshop Manual '242519 Removing and installing air cleaner housing'.
- 7 Install rear spoiler  $\Rightarrow$  Workshop Manual '665819 Removing and installing rear spoiler (Turbo)'.
- 8 Install tail lights  $\Rightarrow$  Workshop Manual '943119 Removing and installing tail light'.



- Install engine-compartment blower  $\Rightarrow$  Workshop Manual '198119 Removing and installing engine-compartment blower'.
- 10 Enter the workshop campaign in the Warranty and Maintenance booklet.

9

Technical Information	Service	2
	33/15 ENU WF23	

Attachment "B": Claim Submission - Workshop Campaign WF23

Warranty claims should be submitted via WWS/PQIS.

Open campaigns may be checked by using either the PIWIS Vehicle Information system or through PQIS Job Creation.

Labor, parts, and sublet will be automatically inserted when Technician is selected in WWS/PQIS. If necessary, the required part numbers will need to be manually entered into warranty system by the dealer administrator.



#### Information

The specified working time was determined specifically for carrying out this campaign and may differ from the working times published in the Labor Operation List in PIWIS.

#### Working time:

Removing water drain valves on the air cleaner housingIncludes:Removing and installing engine-compartment blowerRemoving and installing tail lightsRemoving and installing rear spoilerRemoving and installing air cleaner housing

#### $\Rightarrow$ Damage code WF23 066 000 1

References:

 $\Rightarrow$  Workshop Manual '198119 Removing and installing engine-compartment blower'

- $\Rightarrow$  Workshop Manual '242519 Removing and installing air cleaner housing'
- $\Rightarrow$  Workshop Manual '665819 Removing and installing rear spoiler (Turbo)'
- $\Rightarrow$  Workshop Manual '943119 Removing and installing tail light'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. If a particular condition is described, do not assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your authorized Porsche Dealer for the latest information about whether a particular technical bulletin applies to your vehicle. Part numbers listed in these bulletins are for reference only. Always check with your authorized Porsche dealer to verify the current and correct part numbers. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

Dealership	Service Manager	Shop Foreman	Service Technician	 	 
Distribution Routing	Asst. Manager	Warranty Admin.	Service Technician	 	 

Dr. Ing. h.c. F. Porsche AG is the owner of numerous trademarks, both registered and unregistered, including without limitation the Porsche Crest®, Porsche®, Boxster®, Carrera®, Cayenne®, Cayman®, Macan®, Panamera®, Speedster®, Spyder®, 918 Spyder®, Tiptronic®, VarioCam®, PCM®, PDL®, 911®, RS®, 4S®, FOUR, UNCOMPROMISED®, and the model numbers and the distinctive shapes of the Porsche automobiles such as, the federally registered 911 and Boxster automobiles. The third party trademarks contained herein are the properties of their respective owners. Porsche Cars North America, Inc. believes the specifications to be correct at the time of printing. Specifications, performance standards, standard equipment, options, and other elements shown are subject to change without notice. Some options may be unavailable when a car is built. Some vehicles may be shown with non-U.S. equipment. The information contained herein is for internal authorized Porsche dealer use only and cannot be copied or distributed. Porsche recommends seat belt usage and observance of traffic laws at all times.

**AfterSales** 

#### 2015© Porsche Cars North America, Inc.

Apr 21, 2015 Page 3 of 3

Labor time: 109 TU