

Subject: SYMPTOM TROUBLESHOOTING TABLE [MAZDA CONNECT]	Service Alert No.: SA-065/17
	Last Issued: 08/10/2017

DESCRIPTION

Use the symptom troubleshooting tables below to diagnose MAZDA CONNECT concerns.

REPAIR PROCEDURE

MAZDA CONNECT Symptom Troubleshooting Table Sections

Audio System
Bluetooth®
Center Display
DTC
i-ACTIVESENSE
Maintenance Monitor
Navigation
Noise
Reboot / Frozen Screen / Slow Response
USB / Aux
Voice Command

Audio System

Symptom	Solution	Link
Cannot perform CMU data retrieval	In order to do a CMU data retrieval for the new MAZDA CONNECT software, make sure to use version 31	SA-048/17
Contact information cannot be loaded correctly from phones other than iPhone	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Favorites disappear	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Pandora Radio issues	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Some menu of music source selection is grayed out	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Text information of HD radio is not displayed when switching music source	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17
No audio sound	Go to Workshop Manual troubleshooting NO SOUND OUTPUT IN ALL MODES [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
No CD sound	Go to Workshop Manual troubleshooting NO CD SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM

Bluetooth®

Symptom	Solution	Link
Bluetooth® device disconnects	Install latest software update Version 59.00.502 or later to improve symptom.	09-017/17
Bluetooth® connection error with internet radio applications	Install latest software update Version 59.00.502 or later to minimize symptom.	09-017/17
Bluetooth® pairing procedure	Go to Workshop Manual troubleshooting Bluetooth® PAIRING PROCEDURE	WSM
Bluetooth® shows connected but no sound	Go to Workshop Manual troubleshooting NO Bluetooth® AUDIO AND INTERNET RADIO SOUND [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
Bluetooth® phone compatibility	Go to Mazdausa.com	MUSA
iPhone disconnects	Install latest software update Version 59.00.502 or later to improve symptom.	09-017/17
iPhone name not displayed	Install latest software update Version 59.00.502 or later to fix symptom.	09-017/17
Paired BT device will not connect. Removing the paired BT device from the vehicle (but not the vehicle from the phone) results in an endless "Deleting" message.	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
SMS text message function does not show in center display	SMS (Short Message Service) messages received by paired phones (Android and iPhone 5 iOS 7.0	MT-021/15

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	or higher) can be downloaded, displayed, and played (text to voice)	
When using the call button on the cell phone to make a call, the call sound is short	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17
Wrong phone connected	MAZDA CONNECT bluetooth will connect all profiles to devices in order of priority if the last device is not available.	SA-063/17
Cannot pair smart phone	Go to Workshop Manual troubleshooting Bluetooth® PAIRING NOT POSSIBLE [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
No audio sound from Bluetooth®	Go to Workshop Manual troubleshooting NO Bluetooth® AUDIO AND INTERNET RADIO SOUND [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
Smart phone does not reconnect	Go to Workshop Manual troubleshooting AUTOMATIC Bluetooth® CONNECTION NOT POSSIBLE	WSM

Center Display

Symptom	Solution	Link
Hot temperature warning message	"Display is too Hot. Screen performance may be decreased until it cools" warning message displays when screen temperature is above 176 degrees Fahrenheit (80 degrees Celsius). This is a normal screen protection function.	MT-015/17
Warning guidances are displayed both for LDWS and HBC (CX-3 with LDWS and without HBC only)	Install latest software update Version 59.00.330 or later to fix symptom.	09-017/17
Rear view monitor does not show up on screen	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17
Rear view monitor is blurry	This may be caused by an aftermarket accessory device. Some aftermarket electrical devices (e.g., an accessory cell phone charger) may create excessive electrical noise. The noise may interrupt some of the vehicle electrical systems.	MT-026/16
Rear view monitor is inoperative	Go to Workshop Manual troubleshooting REAR MOUNT CAMERA IMAGE NOT OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

DTC

Symptom	Solution	Link
DTC U0323 (PCM) / U0423 (ABS) / U3000 (IC) CANNOT be deleted when the TPMS warning light flashes and/or the TCS/DSC indicator lights are illuminated.	This can happen if the ignition is turned OFF within 20 seconds after the ignition is turned ON in one of the following two situations. 1. The "ROOM" fuse (Engine compartment) is NOT installed when battery level is low. 2. The CMU (Connectivity Master Unit) is NOT connected.	MT-002/16
DTC U0100:00 [CONNECTIVITY MASTER UNIT] (communication error with PCM) is stored in memory	Install latest software update Version 59.00.330 or later to fix symptom.	09-017/17
1. U3000:98 2. U3000:04 3. U3000:09 4. U3000:42 5. U3000:98 6. C1001:92 7. C1001:97	1. If DTC U3000:98 is set by itself or with U3000:04, advise the customer to park the vehicle in the shade as much as possible. If the light does not reset automatically as soon as the cabin cools, pull over to a safe location and turn the ignition off and then back on, this should reset the system. Mazda is aware of this concern and is working on a repair. This notification will be updated once a repair is available. 2. If any DTC from the list (the cell to the left) are set in the FSC(except as noted in STEP 1), contact Hotline for further instructions.	SA-064/17

i-ACTIVESENSE

Symptom	Solution	Link
SCBS Unavailable or LDWS Unavailable message may be displayed	Install latest software update Version 59.00.441 or later to fix symptom.	09-017/17
SCBS, LDWS, HBC warning lights on in hot weather	Combination of warning lights may include: 1. SCBS 2. LDWS 3. HBC Instrument Cluster Multi-Information Display warning messages may include: 1. Forward Smart City Brake Support Malfunction 2. Smart Brake System Malfunction 3. Front Camera Sensor System Malfunction	SA-064/17

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	<p>MAZDA CONNECT center display warning messages may include:</p> <ol style="list-style-type: none"> 1. High Beam Control [HBC] / Lane-keep Assist System [LAS] Malfunction. Have the vehicle checked by a dealer if this indicator stays On. 2. Smart City Brake Support [SCBS] Malfunction. Have the vehicle checked by a dealer immediately. 	
Active Driving Display shows different speed limit	Some customers may complain that when driving a vehicle equipped with Traffic Sign Recognition System (TSR), the Active Driving Display (AD-Display) shows a speed limit different from the actual electronic traffic signs. For example, The AD-Display shows 55 mph instead of 65 mph actually displayed on the electronic traffic sign. This may be a normal condition.	MT-002/17

Maintenance Monitor

Symptom	Solution	Link
Improper OFF selection in the Setting Interval menu under Oil Change (CX-9 only).	Install latest software update Version 59.00.330 or later to fix symptom.	09-017/17
Resetting with "Fixed" data will not reset "Flexible" data. (CX-9 only).	Install latest software update Version 59.00.330 or later to fix symptom.	09-017/17

Navigation

Symptom	Solution	Link
Navigation or other screens freeze or reboot	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Navigation or other screen turn black, freeze or reboot	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Navigation does not allow to set certain cities as destination	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Navigation does not announce voice guidance for street names	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17
Navigation turns to a black screen remaining the task bar	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17
Navigation - How to update maps	Mazda Toolbox is a free PC application to update navigation map for MAZDA CONNECT which can be downloaded from the MyMazda.com Website and installed.	MT-003/16
Every time the navigation is turned on, the vehicle position	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

starts from the location (dealer) where the CMU was updated from version 55.00.650 to 55.00.750		
Some street names in Canada are not displayed	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Turn -by-turn navigation guidance does not display on on the active driving display (for vehicles with 55.00.750)	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17
Vehicle current position is not accurate enough	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
Invalid SD Card	When installing a navigation SD card, confirm that the card is unlocked. Also, Mazda Does Not Recommend swapping navigation system SD cards from one vehicle to another for testing. If swapped, the SD card that is installed into the other vehicle becomes "linked" to the VIN of that vehicle.	MT-003/17
Wrong speed limits shown in country information	Fix is pending	MT-032/16
Navigation and/or Sirius XM radio is inoperative	Some lower trim models equipped with the MAZDA CONNECT Infotainment System are NOT equipped with Navigation or SIRIUS XM Radio. Customers may add a Mazda Navigation system accessory; however, SIRIUS XM radio cannot be added.	MT-007/15
Navigation map is not displayed	Go to Workshop Manual troubleshooting MAP IS NOT DISPLAYED [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
No Navigation voice guidance	Go to Workshop Manual troubleshooting NO NAVIGATION GUIDANCE VOICE OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM

Noise

Symptom	Solution	Link
Noise from inside front door panel when playing the audio system	Unusual noise coming from inside the front door panel when playing the audio system. This is caused by the damper coming off the speaker frame due to corrosion on the speaker back frame. To correct the issue, a plating process was added at the supplier beginning on November 13, 2015.	09-012/17

Reboot / Frozen Screen / Slow Response

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Symptom	Solution	Link
Reboots constantly	1) Disconnect the negative battery cable for 5 minutes. 2) Reconnect the negative battery cable and recheck the system. If the system now works properly, update it to the latest software version and retest. Return the vehicle to the customer if everything is working correctly.	SA
Shuts down and does not reboot	Some vehicles may experience the Mazda Connect infotainment system shutting down within a few minutes after the ignition is turned on, and will not reboot. It will only reboot after the ignition is turned off and then on again. This is caused by an internal malfunction of the connectivity master unit (CMU) hardware.	09-044/15
Slow start up	Install latest software update Version 59.00.502 or later to improve symptom.	09-017/17
Slow operational response	Install latest software update Version 59.00.502 or later to improve symptom.	09-017/17
Unexpected reboots and blank or frozen screens	Install latest software update Version 59.00.502 or later to minimize symptom.	09-017/17
Blank screen	Go to Workshop Manual troubleshooting IMAGE NOT OUTPUT IN ALL MODES [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]].	WSM

USB / Aux

Symptom	Solution	Link
USB audio device slow response	Install latest software update Version 59.00.502 or later to improve symptom.	09-017/17
Smart Phone will not charge when connected to the USB port	The vehicle's USB port allows data transfer between a customer's device and the vehicle's infotainment system. Some devices may exceed the maximum electric current produced by the USB port. The device may not operate or charge when connected.	MT-022/15
System does not recognize USB/SD card	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17
USB device fails to start playing, resume or display music information. BT audio device fails when starting to play, resume or connect	Install latest software update Version 55.00.760 or later to minimize symptom.	09-017/17

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-065/17	Last Issued: 08/10/2017
-------------------------------------	--------------------------------

No audio sound from USB	Go to Workshop Manual troubleshooting NO USB AUDIO SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
No audio sound from Aux	Go to Workshop Manual troubleshooting NO AUX AUDIO SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM

Voice Command

Symptom	Solution	Link
Voice Command does not recognize command	Go to Workshop Manual troubleshooting VOICE OPERATION NOT POSSIBLE [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	WSM
When asking for current location with voice command "Where am I?", the system responds with "Your location is comma."	Install latest software update Version 55.00.760 or later to fix symptom.	09-017/17

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.