Technical Service Bulletin

#### 94 Vehicle lights malfunction message in instrument cluster display (DTC 03280 or 01800)

94 15 64 2017806/11 March 4, 2015. Supersedes Technical Service Bulletin Group 94 number 15-60 dated February 12, 2015 for reasons listed below.

Audi

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3	2015 - 2016	All	Not Applicable
A4	2009 - 2016	All	Not Applicable
A5	2008 - 2016	All	Not Applicable
A5 Cabriolet	2010 - 2016	All	Not Applicable
A6	2012 - 2016	All	Not Applicable
A7	2012 - 2016	All	Not Applicable
A8	2011 - 2016	All	Not Applicable
TT	2011 - 2015	All	Not Applicable
Q3	2015 - 2016	All	Not Applicable

### Condition

REVISION HISTORY				
Revision	Date	Purpose		
11	-	Revised header data (Added Q3 and TT)		
10	2/12/2015	Revised header data (Added model year; added A3) Revised <i>Technical Background</i> (Added picture for clarity)		
9	1/23/2014	Revised title Revised header data (Added model years)		

• The light bulb warning light is displayed in the instrument cluster with the following message: "Vehicle lights: malfunction".

- One or both of the following DTCs is stored in the vehicle electrical system control module, J519 (address word 09):
  - DTC 03280 (Light switch position implausible signal)
  - DTC 01800 (Light switch E1, no signal/communication)
- Exterior lights are functioning properly.

<sup>© 2015</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Audi

# Technical Service Bulletin

# **Technical Background**

If the headlight switch is moved to an intermediate position and remains there (Figure 1), the light bulb warning light and the error message appear after approximately ten seconds (Figure 2).



*Figure 1.* A headlight switch in an intermediate position.



*Figure 2.* The warning light and error message in the instrument cluster display.

Once displayed, the message turns off after approximately five seconds. The light bulb warning light turns off only after the headlight switch is turned to a defined position, and the status of **DTC 03280** or **DTC 01800** are changed to sporadic.

After 40 driving cycles without an implausible signal detected, the DTCs are automatically cleared.

### **Production Solution**

Not applicable.

### Service

Determine if the above situation applies to the vehicle, and explain the background to the customer. Replacing parts does not change the behavior.

Page 2 of 3

<sup>© 2015</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



#### Warranty

This TSB is informational only and not applicable to any Audi warranty.

## **Additional Information**

All parts and service references provided in this TSB (2017806) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2015 Audi of America, Inc.

Page 3 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.