



Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Jetta Wagon	2009-2010	2.0L TDI (CBEA,CJAA)	All	All	All
(A6) Golf, Jetta, Jetta SportWagen, (A7) Golf	2010-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All
Passat	2012-2015	2.0L TDI (CKRA, CVCA)	All	All	All
Beetle, Beetle Convertible	2012-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All

Condition

28 14 04 September 24, 2014 2037386 Supersedes Technical Bulletin V281403 dated July 11, 2014 to include model year 2015 applicability.

MIL ON - Glow Plug Pressure Sensor Faults Stored in ECM Fault Memory

DTC	Description
P13CE	Sensor for internal pressure of cylinder 1 Electrical error
P13CF	Sensor for internal pressure of cylinder 1 Short circuit to ground
P13D0	Sensor for internal pressure of cylinder 1 Implausible signal
P13D1	Sensor for internal pressure of cylinder 2 Electrical error
P13D2	Sensor for internal pressure of cylinder 2 Short circuit to ground
P13D3	Sensor for internal pressure of cylinder 2 Implausible signal

Technical Bulletin

P13D4	Sensor for internal pressure of cylinder 3 Electrical error
P13D5	Sensor for internal pressure of cylinder 3 Short circuit to ground
P13D6	Sensor for internal pressure of cylinder 3 Implausible signal
P13D7	Sensor for internal pressure of cylinder 4 Electrical error
P13D8	Sensor for internal pressure of cylinder 4 Short circuit to ground
P13D9	Sensor for internal pressure of cylinder 4 Implausible signal
P13E0	Sensor for internal pressure of cylinder 1 Malfunction
P13E1	Sensor for internal pressure of cylinder 2 Malfunction
P13E2	Sensor for internal pressure of cylinder 3 Malfunction
P13E3	Sensor for internal pressure of cylinder 4 Malfunction

Technical Background

When diagnosing MIL ON with glow plug pressure sensor DTC's it important to perform diagnosis prior to replacing the glow plug.

Production Solution

Implemented into production.

Technical Bulletin

Service

Step 1:

When diagnosing a glow plug pressure sensor DTC, before replacing the glow plug, first check for loose connections. You can check for any loose connections by performing a push or pull test of the connectors. If on a push test, a click can be felt or on a pull test, the connector comes off very easily, the connection is most likely the cause. Properly seat the connector, clear any DTCs, and test drive the vehicle. **DO NOT replace the glow plug if a loose connection is found and no faults return after test drive. If fault returns, continue to step 2.**

Step 2:

A check of the glow plug can be performed by swapping the glow plug from the affected cylinder with the glow plug from an adjacent cylinder without a fault.



Note:

Ensure when re-securing the connector that connector is fully seated.

After swapping the glow plug(s), perform a test drive of the vehicle to attempt to duplicate the DTC.



Note:

It may take two drive cycles for the MIL to illuminate.

If after swapping the glow plug, the DTC follows the glow plug, there is a faulty glow plug. Replace the glow plug. **If the DTC stays in the same cylinder after swapping the glow plug continue to step 3.**

Step 3: Glow plug wiring harness and connectors should be checked.

While checking the harness you can monitor MVB 141 or in UDS equipped vehicles monitor the Maximal_Cylinder_Pressure_Cylinder_X values for each cylinder while manipulating the harness and connectors, watching for changes in the readings. If the harness is found to be at fault, replace the harness.



Technical Bulletin

Warranty

Step 1

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta, Jetta Wagon (A5)	2009-2010	2.0L TDI (CBEA,CJAA)	All	All	All
(A6) Golf, Jetta, Jetta SportWagen, (A7) Golf	2010-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All
Passat	2012-2015	2.0L TDI (CKRA, CVCA)	All	All	All
Beetle, Beetle Convertible	2012-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All
SAGA Coding					
Claim Type:	Use applicable Claim Type ¹⁾				
Service Number:	Damage Code	HST		Damage Location (Depends on Service No.)	
9752	0028	--		Use applicable when indicated in ElsaWeb (L/R)	
Parts Manufacturer	Golf, Passat		WVO ²⁾		
	Jetta, Jetta Sportwagen, Beetle, Beetle Convertible		3ME ²⁾		
Labor Operation ³⁾ : Engine Wiring Harness Connection Repair			97524199 = 10 TU		



Technical Bulletin

Causal Part: Select Labor operation		97524199
Diagnostic Time ⁴⁾		
GFF Time expenditure	01500000 = 20 TU max.	YES
Road Test	01210004 = 10 TU	YES
Technical Diagnosis (Includes wiring checks)	01320000 = 30 TU max.	YES
Claim Comment: Input "As per Technical Bulletin 2037386" in comment section of Warranty Claim.		
<p>¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p>²⁾ Code per warranty vendor code policy.</p> <p>³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p>⁴⁾ Documentation required per Warranty Policies and Procedures Manual.</p>		

OR

Step 2

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta, Jetta Wagon (A5)	2009-2010	2.0L TDI (CBEA,CJAA)	All	All	All
(A6) Golf, Jetta, Jetta SportWagen, (A7) Golf	2010-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All
Passat	2012-2015	2.0L TDI (CKRA, CVCA)	All	All	All
Beetle, Beetle Convertible	2012-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All



Technical Bulletin

SAGA Coding			
Claim Type:	Use applicable Claim Type ¹⁾		
Service Number:	Damage Code	HST	Damage Location (Depends on Service No.)
2884	0040	--	Use applicable when indicated in ElsaWeb (L/R)
Parts Manufacturer	Jetta, Jetta Sportwagen, Beetle, Beetle Convertible, Passat, Golf	BEO ²⁾	
Passat			
Labor Operation ³⁾ : Glow plug removed+reinstalled		28841933 = 40 TU	
OR			
Labor Operation ³⁾ : 4 Glow plugs removed+reinstalled		28842033 = 50 TU	
Jetta, Jetta Sportwagen, Golf, Beetle, Beetle Convertible			
Labor Operation ³⁾ : Glow plug removed+reinstalled		28841933 = 50 TU	
OR			
Labor Operation ³⁾ : 4 Glow plugs removed+reinstalled		28842033 = 70 TU	
2015 Golf			
Labor Operation ³⁾ : Glow plug removed+reinstalled		28841905 = 30 TU	
OR			
Labor Operation ³⁾ : 4 Glow plugs removed+reinstalled		28842005 = 40 TU	
Causal Part: Glow Plug		03L 905 061G	
Diagnostic Time ⁴⁾			



Technical Bulletin

GFF Time expenditure	01500000 = 40 TU max.	YES
Road Test	01210004 = 10 TU	YES
Technical Diagnosis (Includes additional drive cycles)	01320000 = 90 TU max.	YES
Claim Comment: Input "As per Technical Bulletin 2037386" in comment section of Warranty Claim.		
<p>¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p>²⁾ Code per warranty vendor code policy.</p> <p>³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p>⁴⁾ Documentation required per Warranty Policies and Procedures Manual.</p>		

OR

Step 3

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta, Jetta Wagon (A5)	2009-2010	2.0L TDI (CBEA,CJAA)	All	All	All
(A6) Golf, Jetta, Jetta SportWagen, (A7) Golf	2010-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All
Passat	2012-2015	2.0L TDI (CKRA, CVCA)	All	All	All
Beetle, Beetle Convertible	2012-2015	2.0L TDI (CJAA, CRUA, CVCA)	All	All	All
SAGA Coding					



Technical Bulletin

Claim Type:	Use applicable Claim Type ¹⁾		
Service Number:	Damage Code	HST	Damage Location (Depends on Service No.)
9752	0040	--	Use applicable when indicated in ElsaWeb (L/R)
Parts Manufacturer	Golf, Passat	WVO ²⁾	
	Jetta, Jetta Sportwagen, Beetle, Beetle Convertible,	3ME ²⁾	
Passat			
Labor Operation ³⁾ : Remove and Install Engine Wiring Harness (CKRA)		97521933 = 290 TU	
Labor Operation ³⁾ : Remove and Install Engine Wiring Harness (Gen 3 CVCA)		97521905 = 420 TU	
Jetta, Jetta Sportwagen, Golf, Beetle, Beetle Convertible			
Labor Operation ³⁾ : Remove and Install Engine Wiring Harness		97521933 = 330 TU	
2015 Golf			
Labor Operation ³⁾ : Remove and Install Engine Wiring Harness (Gen 3)		97521905 = 290 TU	
Causal Part: Engine Harness		03L 971 *** (See ETKA)	
Diagnostic Time ⁴⁾			
GFF Time expenditure	01500000 = 60 TU max.	YES	
Road Test	01210004 = 10 TU	YES	
Technical Diagnosis (Includes wiring harness checks)	01320000 = 120 TU max.	YES	
Claim Comment: Input "As per Technical Bulletin 2037386" in comment section of Warranty Claim.			
¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only			



Technical Bulletin

- ²⁾ Code per warranty vendor code policy.
- ³⁾ Labor Time Units (TUs) are subject to change with ELSA updates.
- ⁴⁾ Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

Part No:	Part Description	Quantity
03L 905 061G	Glow Plug	As required
03L 971 *** (See ETKA)	Engine Harness	As required

Tool Description	Tool No:
Midtronics Battery Tester/Charger	InCharge 940 (INC-940) or GRX3000VAS
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with ODIS Service with: current online updates

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.