

9003199

11/09/2016

MY 11, 12, 13, 14

WK, WD

GPOP - Issue Review System

Part Number: 05057980A\$, 05057981A\$, 05057982A\$, 05057983A\$, 68140623A\$, 68193248A\$, 68140624A\$, 68164515A\$, 06506539A\$, 06510677A\$, 1NJ74DX9A\$, 1NJ74LC5A\$, 1NJ74LU5A\$, 1NJ74XTWA\$, 5MT24DX9A\$, 5MT24HL9A\$, 5MT24LC5A\$, 5MT24LU5A\$, 5MT24XTWA\$, 5MT243X9A\$, 5RB57DX9A\$, 5RB57HL9A\$, 5RB57LC5A\$, 5RB57LU5A\$, 5RB57XTWA\$, 5SW66DX9A\$, 5SW66XTWA\$, 5YQ07DX9A\$, 5YQ07HL9A\$, 5YQ07XTWA\$, 5YQ08DX9A\$, 5YQ08HL9A\$, 5YQ08XTWA\$, 5YQ09DX9A\$, 5YQ09HL9A\$, 5YQ09XTWA\$, 5YQ10DX9A\$, 5YQ10HL9A\$, 5YQ10XTWA\$, 55057322A\$, 55057323A\$, 55057324A\$, 55057325A\$, 55057358A\$, 55057378A\$, 55057379A\$, 68140621A\$, 68140622A\$

Part Description: Steering Column

Issue Description: If vehicle comes in for steering column replacement, verify column installed. Go to Info Column in Star Parts and open the flow chart to determine which column is installed. If column is Daimler, verify that a replacement Daimler column is in stock and use for replacement. If no Daimler column is in stock, replacement must use Presta column (which require a number of other components to be replaced). For more information and details on PN's, see W-Series Flowchart in Star Parts. Contact parts specifying for assistance regarding correct part numbers, for technical assistance contact Star.~

UPDATE: 11/9/2016 ~

If the new bearing does not fit through the double dash, you need to replace the lower double dash panel to the latest level. Please see the updated flowchart in StarParts for the correct replacement panel. ~

~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.