

Solution K76992557 Friday, November 3, 2017 4:45:06 PM CET

Solution

Title (customer effect)	Chassis Experiencing High soot Accumulation, Abnormal (Too High, Too Low) Regeneration Temperatures Following An Aftertreatment Hydrocarbon Injector (AHI, 7 ^t ^h Injector) Nozzle Replacment Procedure
Cause	Incorrect part number (P/N) AHI nozzle (7 th Injector) could have possibly been installed.
Solution	Model Year (MY) US17 changes to the AHI system have been made. MY US17 has been

updated to a High flow nozzle.

- The low flow nozzle has been used for North American heavy duty engines since 2011. All US17 11L and 13L engines will now use the high flow nozzle (16L engines will continue to use the low flow nozzle).
- The AHI nozzle tip of the low flow and the high flow nozzle is different in appearance. Other than this difference, the two nozzles are visually the same.







Solution visibility	Dealer distribution	
Function(s)/component(s) affected		
Function affected	engine, exhaust	
Function Group		
Function Group	258 emissions after-treatment	
Customer effect		
Main customer effect	soot, regeneration, temperature, calibration/programming/pairing/missing operation, diagnostics/methodology, efficiency/abnormal behavior	
Fluid implicated	fuel	
Conditions		
Vehicle operating mode	when driving, when stationary	
Frequency of occurrence of problem	always	
Administration		
Author	A241298	
Last modified by	RU4469V	
Creation date	18-10-2017 16:10	
Date of last update	31-10-2017 14:10	
Status	Published	
NA_MACK_Vehicle_R	ange	
NA_MACK_Vehicle_Ran ge	Cabover, LR, LEU, MRU, Conventional, CHU, CXU, GU	
NA_VOLVO_Vehicle_f	Range	
NA_VOLVO_Vehicle_Ra	Conventional, VNX, VNL, VNM, VHD, VAH	
Engine family		
Engine family	Volvo, 11L Engine, 13L Engine, Mack, MP7, MP8	
Emission Standard		
Emission Standard	2018, OBD2017, US17 GHG, US14 CNG, US16, US15, US10, US13 OBD, US14 GHG	