



Countries: UNITED STATES, MEXICO Document ID: IK1201363  
 Availability: ISIS, IsSIR Revision: 2  
 Major System: ENGINES Created: 3/23/2017  
 Current Language: English Last Modified: 6/27/2017  
 Other Languages: NONE Author: Marcelo Sahagun  
 Viewed: 412

[Less Info](#)

Hide Details Coding Information

Copy Link	Copy Relative Link	Bookmark <a href="#">View My Bookmarks</a>	Add to Favorites	Print	Provide Feedback	Helpful 5	Not Helpful 1
-----------	--------------------	---	------------------	-------	------------------	--------------	------------------

Title: CPA Injector Misfire Detection

Applies To: EPA 2004-2006 DT 466/570-- EPA 2007-2009 MF DT/9/10-- EPA 2010-2013 MF DT/9/10-- EPA 2014-2017 N9/ N10

## CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

10/23/2017- Included 04 and 07 emission diag steps  
 05/16/2017 - Initial Article Release

## DESCRIPTION:

This document describes the process for utilizing the CPA Injector Misfire Detection

### CPA Injector Misfire Detection Apply To:

Emission Year	Emission Model	Description
2004-2006	DT 466/ 570	
2007-2009	MF DT/ 9/ 10	
2010-2013	MF DT/ 9/ 10	2013 HD OBD engines must have calibration level EER5 or later in order to perform Full Load to Highway Speed Test. Ignore 637-10 code if found in engine after CPA used
2014-2017	N9/ N10	

**Note: ALL previous MaxxForce 7 injector diagnostic tests should follow the Base Engine Analysis Module (BEAM) IDLE Test**

### Software Release:

Version	Change Description	Release Date
2.0.0.148	Warranty Authorization Code (WAC) for 2 injectors in Injector Misfire Detection	09/25/2013
1.0.0.329	MED Duty Injector Misfire Detection Launch	03/20/2012

Software must always be current. Refer to the [CPA Resource Article](#)

## SYMPTOMS/ FAULT CODE(s)

Follow the FCAP/ Fault Code Diagnostics/ Symptom Based Diagnostics from the appropriate Engine Diagnostic Manual.

DTC/Light	Description
SPN and FMI dependent on Engine Model	Description dependent on Engine Model
Symptom	Description
Engine Misfire	
Rough Idle	
Low Power	

Engine Model	Diagnostic Fault Codes (Status Active or Inactive)	Diagnostics to Perform
EPA 2007 Maxxforce DT/ 9/ 10	<ul style="list-style-type: none"> <li>• 8001-6, 8002-6, 8003-6, 8004-6, 8005-6, 8003-6-Injector Closed Coil-Open Circuit</li> <li>• 8001-5, 8002-5, 8003-5, 8004-5, 8005-5, 8003-5-Injector Open Coil-Open Circuit</li> <li>• 8001-4, 8002-4, 8003-4, 8004-4, 8005-4, 8003-4-Injector Open Coil-Short Circuit</li> <li>• 8001-3, 8002-3, 8003-3, 8004-3, 8005-3, 8003-3-Injector Close Coil-Short Circuit</li> <li>• 8151-5-Bank A Injector Open Coil Short</li> <li>• 8151-6-Bank A Injector Close Coil Short</li> <li>• 8152-5-Bank B Injector Open Coil Short</li> <li>• 8152-6-Bank B-Injector Close Coil Short</li> </ul>	1. Perform Injector Misfire Detection
EPA 2007 Maxxforce DT/ 9/ 10	<ul style="list-style-type: none"> <li>• 8001, 8002, 8003, 8004, 8005, 8006-1-Cylinder Balance Below Minimum Limit</li> <li>• 8001, 8002, 8003, 8004, 8005, 8006-0-Cylinder Balance Maximum Limit Exceeded</li> </ul>	1. Perform <b>EPA 2007 System Diagnostics</b> (below)
EPA 2004 DT466/ 570	<ul style="list-style-type: none"> <li>• 421-428-High Side to Low Side Open</li> <li>• 431-436-Hgh Side Shorted to Low Side</li> <li>• 451-456-High Side Shorted to Ground or Vbat</li> <li>• 513-Low Side to Bank 1 Open</li> <li>• 514-Low Side to Bank 2 Open</li> <li>• 515-Bank 1 Low Side Short to Ground</li> <li>• 521-Bank 2 Low side Short to Ground</li> </ul>	1. Perform Injector Misfire Detection
EPA 2004 DT466/ 570	Misfire/ Rough Running	1. Perform <b>EPA 2004 System Diagnostics</b> (below)

**EPA 2004 System Diagnostics:**

- Outline of diagnostics in [EGED290-1](#)
  1. Perform KOEO Standard Test
  2. Perform KOEO Injector Test
  3. Verify Engine Oil Quality and Level
  4. Verify Fuel Quality and Level
  5. Verify Fuel Pressure and Aeration
  6. Relative Compression Test
  7. IPR Circuit Check: Wiggle IPR pigtail at engine idle and ensure NO engine stumble
  8. Perform CPA Injector Misfire Detection Test

**EPA 2007 System Diagnostics:**

- Outline of diagnostics in [EGED380](#)
  1. Visual Inspection
  2. Verify Fuel Quality and Level
  3. Verify Fuel Pressure and Aeration
  4. Sensor Compare Check
  5. Verify Engine Oil Quality and Level
  6. IPR Circuit Check: Wiggle IPR pigtail at engine idle and ensure NO engine stumble
  7. Perform CPA Injector Misfire Detection Test

**SPECIAL TOOL(s):**

- Tools required for component removal: Refer to appropriate engine service manual
- To perform CPA Injector Misfire Detection Tests properly, the following tools are required

Tool Description	Tool Number	Comments
EZ-Tech or Computer		ServiceMaxx/ NED and CPA software must be installed
RP1210		NavCom or Nexiq
CPA Module	OE-1178/ 12-999-01-01	


CPA CAM harness (Yellow)		OE11178-2/ 12-999-01-02	
CPA CRANK harness (Black)		12-999-01-03	
CPA Extension Harness			2 required for Cam and Crank harnesses

[Tools Resource Center](#)

**CPA Injector Misfire Detection Descriptions:**

**Learning Management System (LMS):**

Instruction Course is available on Navistar Service Portal



**Training Videos:**

Training Video Coming Soon to this article but available to download through the CPA software:  
Click: [CPA Video Download](#)

**Test Descriptions:**


CPA Injector Misfire Detection Test	Detailed Analysis
<p style="text-align: center;"><b>Signal Check</b></p>	<ul style="list-style-type: none"> <li>• Ensures engine can safely reach 2200rpm</li> <li>• WAC is not issued</li> </ul>

Cold Idle	<ul style="list-style-type: none"> <li>• 60 second test</li> <li>• Measures engine rpm oscillations</li> </ul>
Hot Idle	<ul style="list-style-type: none"> <li>• 60 second test</li> <li>• Perform test at engine operating temperature</li> <li>• Measures engine rpm oscillations</li> </ul>
Full Load to Highway Speed	<ul style="list-style-type: none"> <li>• Signal Check test must be performed prior</li> <li>• Measures engine rpm oscillations at various gear shifts</li> <li>• Note: 2013 disclaimer</li> </ul>
User Defined	<ul style="list-style-type: none"> <li>• Open 5min test</li> <li>• No conclusions given</li> </ul>


**Signal Descriptions:**




Result	Description
High Vibration	<ul style="list-style-type: none"> <li>• High engine oscillation not associated to an injector misfire</li> <li>• BLUE X indicator</li> <li>• Possible ICP adaptation/ ECM calibration error</li> <li>• Possible under valve cover (UVC) leak</li> </ul>
Defect Found	<ul style="list-style-type: none"> <li>• Engine oscillation associated to an injector misfire</li> <li>• RED indicator</li> </ul>
No Defect	<ul style="list-style-type: none"> <li>• No abnormal engine oscillation detected</li> </ul>



Speed History Graph: For most accurate results, ensure CPA captures engine speed throughout all gear shifts






CAM Signal: Sample of good CAM signal



CRANK Signal: Sample of good CRANK signal

**CAM Signal Diagnostics:**

Step	Action: <u>Turn Key On Engine Off</u>	Decision
1	Ensure connection between CPA Extension cable and CPA Module is secured 	If connection is tight then proceed to step 2
2	1. Disconnect CPA Extension cable from CPA Module CAM Sensor Port 2. With a DMM measure resistance at the CPA Extension center terminal and outer grounding shell  Does the DMM read between 300 - 400 Ohms?	Yes: Inspect the CPA Module for possible defect or loose connection  No: Proceed to step 3
3	1. Disconnect CPA Extension cable from CAM Sensor Breakout Harness 2. With a DMM measure resistance at the 2-pin connection  Does the DMM read between 300- 400 Ohms?	Yes: Possible defect in CPA Extension cable. Replace and Retest as needed  No: Proceed to CAM circuit and synchronization diagnostics in the appropriate engine diagnostic manual 28

**Additional Diagnostics:**

[Air Gap Specifications](#)

**WARRANTY INFORMATION:**

CPA Module	WAC can be issued for components listed	Navistar Engine Model	Example WAC	Related Articles
Injector Misfire Detection	1 or 2 Fuel Injectors	<ul style="list-style-type: none"> <li>EPA 2004-2006 DT 466/570</li> <li>EPA 2007-2009 MF DT/ 9/10</li> <li>EPA 2010-2013 MF DT/ 9/10</li> <li>EPA 2014-2017 N9/ N10</li> </ul>	XXXX	

- All Component Replacement Requirements are covered under policy letter: [WPL2800126](#)
- Reference the Warranty Resource Center for the most recent iApproval/ Warranty Authorization Code (WAC) requirements letter
- Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.


**Standard Repair Time(s):**

Description	SRT Link
12 - CYLINDER PERFORMANCE ANALYZER (CPA) TOOL, DIAGNOSIS	<a href="#">CPA Diagnostics</a>

---

**OTHER RESOURCES**

[Master Service Information Site](#)

 Hide Details	<b>Feedback Information</b>								
<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 40%;"></td> <td style="text-align: right; padding-right: 20px;">Viewed: 411</td> </tr> <tr> <td></td> <td style="text-align: right; padding-right: 20px;">Helpful: 5</td> </tr> <tr> <td></td> <td style="text-align: right; padding-right: 20px;">Not Helpful: 1</td> </tr> <tr> <td colspan="2" style="padding-top: 10px;"> <div style="border: 1px solid #ccc; padding: 2px;">No Feedback Found</div> </td> </tr> </table>			Viewed: 411		Helpful: 5		Not Helpful: 1	<div style="border: 1px solid #ccc; padding: 2px;">No Feedback Found</div>	
	Viewed: 411								
	Helpful: 5								
	Not Helpful: 1								
<div style="border: 1px solid #ccc; padding: 2px;">No Feedback Found</div>									

Copyright © 2017 Navistar, Inc.