

Reference	SSM73634
Models	F-PACE / X761 F-TYPE / X152 XE / X760 XF / X260 XJ / X351
Title	Unable to complete PDI - Telematics fails to activate
Category	Electrical
Last modified	30-Nov-2017 00:00:00
Symptom	205000 Electrical Accessories
Content	<p>Models Affected: F Pace (X761) - 18MY F Type (X152) - 18MY XE (X760) - 18MY XF (X260) - 18MY XJ (X351) - 18MY</p> <p>Issue Vehicle fails PDI routine due to telematics will not activate – e-Call button fails to illuminate</p> <p>Cause Communication error between Telematics Control Unit (TCU) and Server</p> <p>Action Attempt to manually activate TCU BEFORE attempting PDI:</p> <p>IMPORTANT: Note timestamps for ALL TCU activation attempts to be included with any TA requests needed to complete activation.</p> <ul style="list-style-type: none"> • Move vehicle outside to known area of good reception. • Attempt manual activation with 10 second bCall button press. (note timestamp) • 2 or 3 attempts should be made, waiting about 3 minutes between each attempt to allow for delays in data exchange with connected car servers. <p>If manual TCU activation is not successful, proceed with normal PDI processing applying the following care points:</p> <ul style="list-style-type: none"> • Only use Pathfinder 120 onwards. • Verify WiFi, Mobile Data, and hotspot settings are turned off. (where fitted) • Verify SIM card is removed from vehicle.(where fitted) • Perform PDI (Note timestamp of TCU activation process within PDI routine.)

- If unsuccessful, if allowable, disconnect the TCU back up battery for one hour and then reconnect, leave the vehicle overnight and repeat the PDI routine

If unsuccessful:

- Run Telematics server check (Note timestamp)
 - 1. *CAUTION: This procedure requires Pathfinder version 120 loaded or a later version.*
 - 2. *Connect the JLR approved diagnostic tool and the JLR approved battery support unit to the vehicle and begin a new diagnostic session.*
 - *The JLR approved diagnostic tool will read the correct VIN for the current vehicle and automatically take the vehicle out of 'Transportation mode' if required.*
 - 3. *Follow the JLR approved diagnostic tool prompts.*
 - 4. *Select 'ECU Diagnostics'.*
 - 5. *Select 'Telematic control unit module' [TCU].*
 - 6. *Select 'ECU Functions'*
 - 7. *Select 'Telematics server communication check'.*
 - 8. *Follow all on-screen instructions to complete this task.*
- Run Activation routine (Note timestamp)
 - 1. *Select 'ECU Diagnostics'.*
 - 2. *Select 'Telematic control unit module' [TCU].*
 - 3. *Select 'ECU Functions'*
 - 4. *Select 'Activate telematics control module'.*
 - 5. *Follow all on-screen instructions to complete this task.*
- Repeat PDI routine. (Note timestamp of TCU activation process within PDI routine.)

If still unsuccessful:

- Run the TCU "New Module Programming" function. (Note: there is no need to physically replace the module).
 - 1. *Select 'ECU Diagnostics'.*
 - 2. *Select 'Telematic control unit module' [TCU].*
 - 3. *Select 'Replace ECU'.*
 - 4. *Follow all on-screen instructions to complete this task.*
 - 5. *When the task is completed, exit the current session.*
 - 6. *Disconnect the JLR approved diagnostic tool and the JLR approved battery support unit.*

IMPORTANT: Extract session files immediately after exiting the current diagnostic session to include with a TA case if required.

Vehicles that cannot successfully activate TCU Connected Car services following these steps must open a VIN specific TA request including the following details.

- Session files
- Confirmation of process followed and SSM number.

- Date/Time of all manual activation attempts.
- TCU serial number

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.