



# Service Bulletin

File in Section: -

Bulletin No.: PI0373B

Date: June, 2014

## PRELIMINARY INFORMATION

**Subject:** Power Foldaway Mirror Glass Shakes, Flutters at Normal Driving Speeds

**Models:** 2015 and Prior GM Passenger Cars and Light Duty Trucks  
Equipped with Power Foldaway Mirrors

This PI has been revised to add the 2014 and 2015 model years and update the Labor Operation to the Global Labor Code (GLC). Please discard PI0373A.

### Condition/Concern

Some customers may comment that the outside power foldaway mirror glass shakes or flutters while driving at normal speeds. Customer may also comment that the mirror(s) will not stay in the unfolded position.

This condition may be caused by the mirror(s) being manually folded and/or unfolded or the mirror(s) being obstructed while (power) folding.

### Recommendation/Instructions

**Note:** For full size trucks, refer to the latest version of Corporate Bulletin Number 06-08-64-027 for additional vehicle specific information.

Follow the procedure below to correct this condition:

Fold and unfold the mirrors one time using the mirror controls to reset them to their normal position. A popping noise may be heard during the resetting of the power foldaway mirrors. This sound is normal after a manual folding operation.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2080298*	Relearn Power Folding Mirrors and Road Test	0.3 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		