

Solution K11065398 Tuesday, December 5, 2017 9:10:10 PM CET

Solution

Title (customer effect)

Mack Chassis - Crankcase Venilation (CCV) Oil Leaks - US14 Emissions And Newer

Cause

Mack Trucks has received reports from the aftermarket regarding oil leaks at the CCV housing inlet tube and at the split line between the upper and lower housings on chassis


builds between **January 1, 2014 and January 26, 2016** with MP7, MP8, and MP10 engines. It has been determined that the O-ring installed on the inlet tube is the source of the leak and oil may leak down the back of the housing giving the impression that the housing split line is also leaking.

impression that the housing split line is also leaking

Solution

Should there be a report of this nature on a chassis built after January 1, 2014, do not disassemble the CCV. Remove the inlet tube assembly and carefully replace the O-ring at the quick connect fitting with part 85148758 using an O-ring pick. Be careful to not scratch the plastic quick connect housing with the O-ring pick during this procedure as this may cause an oil leak. Return the parts through normal warranty procedures if requested. If it is determined that there is a leak at the housing other than the inlet O-ring, the complete assembly will need to be replaced as this is a non-serviceable part. Do not attempt to tighten the split line screws on the housing or disassemble the assembly as seals and repair parts are no longer available for this component as they were on the older version of this component. *NEW - If the quick connect fitting is cracked or breaks on disassembly, replace the complete tube assembly. If the collar on the CCV inlet is worn or broken at the locking lip, replace the complete CCV assembly.*

This bulletin is temporary in nature and will be replaced with an updated publication once a permanent correction has been created.



Solution visibility

Dealer distribution

Function(s)/component(s) affected

Function affected	Documentation, SNM, engine
Function Group	
Function Group	21 engine
Customer effect	
Main customer effect	fluid
Fluid problem	leak
Fluid implicated	oil
Fluid pressure	normal pressure
Conditions	
Vehicle operating mode	when driving, when stationary
Frequency of occurrence of problem	always
Administration	
Author	A241298
Last modified by	RU4469V
Creation date	18-01-2017 16:01
Date of last update	05-12-2017 17:12
Status	Published
NA_MACK_Vehicle_R	ange
NA_MACK_Vehicle_Ran ge	Cabover, LR, LEU, MRU, Conventional, CHU, CXU, GU
Engine family	
Engine family	Mack, MP7, MP8, MP10
Emission Standard	
Emission Standard	US14 CNG, US16, US15, US14 GHG