

Solution K38445549 Thursday, January 4, 2018 5:26:18 PM CET

Solution

| Title (customer effect) | Volvo Chassis - Logging Diagnostic Trouble Code (DTC) P026D - Fuel Injection Quantity Higher Than Expected - US15 Emissions, Model Year (MY) 2016 |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Cause | P026D00 - Fuel Injection Quantity Higher Than Expected may log on a US15 emissions level chassis with no fault found at the conclusion of Guided Diagnostics. |
| Solution | Overview |
| | The Engine Control Module (EMS) monitors fuel/air mixture via the NOx sensors. P026D is logged by the EMS when the oxygen level detected by the NOx sensors is too low when compared to the fuel flow rate. |
| | In addition to the items covered in Guided Diagnostics, boost reading, fuel injectors, and EGR flow can cause this code to set. |
| | Repair |
| | If Guided Diagnostics results in No Fault Found or Unclear Test Results: |
| | Inspect the Intake Manifold Pressure (Boost Pressure) sensor Verify that the sensor is reading correctly |
| | Check the EGR Differential Pressure (Delta-P) Sensor In addition to verifying that the sensor and Venturi Tube are not clogged, the sensor value should be verified to be zero with key on, engine off |
| | Physically verify that the EGR valve is operating correctly There should be no more than a trickle of flow out of the valve when it is closed The valve should be verified to move through its full range without binding at any point in travel |
| | Verify that the correct injectors are installed This is especially relevant for chassis that have just had the injectors replaced. Injectors intended for a larger displacement engine will dose an excessive amount of fuel Part numbers should be visually verified from the injector tags |
| | Confirm that the turbocharger is functioning correctly The VGT Function Test located in Premium Tech Tool (PTT) should be used |

to verify function

- Review the CBR Solution for the VGT Function Test for more information and test result interpretation

• Ensure that there are no leaks in the intake system

- Review the CBR solution for smoke testing intake and exhaust systems as

| recessiv | |
|------------|--|
| Jucossal y | |

| | necessary |
|--------------------------------------|-----------------------------------------------------------------------------------|
| Solution visibility | Dealer distribution |
| Function(s)/componer | nt(s) affected |
| Function affected | fuel system, exhaust, Diagnostic tool |
| Function Group | |
| Function Group | 237 injector and delivery pipe , 255 turbocharger , 258 emissions after-treatment |
| Customer effect | |
| Main customer effect | diagnostics/methodology, fault code/display |
| Fluid implicated | fuel |
| Fault code(s) | |
| OBD 2013 Diagnostic Trouble Codes | P026D |
| Administration | |
| Author | a175606 |
| Last modified by | RU4469V |
| Creation date | 08-04-2016 15:04 |
| Date of last update | 18-12-2017 17:12 |
| Status | Published |
| NA_VOLVO_Vehicle_I | Range |
| NA_VOLVO_Vehicle_Ra nge | Conventional, VNX, VNL, VNM, VHD, VAH |
| Engine family | |
| Engine family | Volvo, 11L Engine, 13L Engine, 16L Engine |
| Emission Standard | |
| Emission Standard | US15 |