



Technical Service Bulletin

01 MIL on (DTCs P200400, P200500, P200600 and/or P200700) stored in ECM

01 17 27 2048411/2 July 19, 2017. Supersedes Technical Service Bulletin Group 01 number 17-26 dated July 19, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS 7	2014 - 2017	All	4.0 liter engine
S8 +, RS 6+, and RS 7+	2016 - 2017	All	4.0 liter engine
A8, S6, S7, S8, and RS 6	2013 - 2017	All	4.0 liter engine

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Warranty</i> (Added Claim Types and updated Damage Code)
1	07/19/2017	Initial publication

Customer statement:

- MIL on
- Engine maybe limited to 4,000rpm

Workshop findings:

The following DTC's about the intake manifold flap adjustment are logged individually or in combination:

- **DTC P2004** (intake manifold flap for air flow control bank 1 stuck open)
- **DTC P2005** (intake manifold flap for air flow control bank 2 stuck open)
- **DTC P2006** (intake manifold flap for air flow control bank 1 stuck closed)
- **DTC P2007** (intake manifold flap for air flow control bank 2 stuck closed)

Technical Background

Moisture ingress into potentiometer.



Technical Service Bulletin

Production Solution

Sealant on micro-encapsulated screw.

Service

If the DTC is logged due to a fault of the vacuum regulator (bank 1 or 2) or the potentiometer for the intake manifold flap adjustment (bank 1 or 2, G336 or G512) and the vacuum supply of the intake manifold flap adjustment is not the cause, fit the repair kit 079198135 on both banks. The repair kit consists of one vacuum regulator, one potentiometer, and one micro-encapsulated bolt.

When fitting the repair kits, proceed according to the Repair Manual, *Engine >> 24 Multiport Fuel Injection >> Vacuum System >> Intake Flap Vacuum Actuator, Removing and Installing >> Intake Flap Vacuum Actuator, Removing and Installing, cylinder bank 1 (right)* and *Engine >> 24 Multiport Fuel Injection >> Vacuum System >> Intake Flap Vacuum Actuator, Removing and Installing >> Intake Flap Vacuum Actuator, Removing and installing, cylinder bank 2 (left)*.

Also proceed according to the Repair Manual, *Engine >> 24 Multiport Fuel Injection >> Intake Manifold >> Intake Manifold Runner Position Sensor G336, Removing and Installing* and *Engine >> 24 Multiport Fuel Injection >> Intake Manifold >> Intake Manifold Runner Position Sensor 2 G512, Removing and Installing*.



Technical Service Bulletin

When replacing the potentiometer, the micro-encapsulated bolt of the potentiometer (Figure 1) must be replaced. The micro-encapsulated bolt is included in repair kit 079198135.



Tip: The engine does not have to be removed.




Figure 1. Micro-encapsulated bolt (A24-11860 of repair manual).

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2465		
Damage Code:	0040		
Labor Operations:	S6 and S7		
	Air intake distributor remove + reinstall	2446 1921	600 TU
	Install repair kits both Banks 1&2	2465 2099	980 TU



Technical Service Bulletin

	Additional labor for adjustment of ACC, top view camera, and night vision, if necessary based on vehicle equipment	See Elsa	See Elsa
	RS 7		
	Air intake distributor remove + reinstall	2446 1923	690 TU
	Install repair kits both Banks 1&2	2465 2099	920 TU
	Additional labor for adjustment of ACC, top view camera, and night vision, if necessary based on vehicle equipment	See Elsa	See Elsa
	A8 and S8		
	Air intake distributor remove + reinstall	2446 1921	470 TU
	Install repair kits both Banks 1&2	2465 2099	600 TU
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 30 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB# 2048411/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
079198135	Repair Kit (vacuum regulator, one potentiometer, screws)	2
079129717J	Gasket intercooler left	1
079129717K	Gasket intercooler right	1



Technical Service Bulletin

079145818	Gasket throttle body	1
079145417B	Gasket recirculation valves	2
WHT 001011	O-ring	1
N 91115401	Spring clip	2
N 90442501	Retaining clip	2
N 90489801	Retaining clip	2
N 90409501	Hose clamp	2
4G0253115D	Gasket converter	2
8K0253115K	Gasket downpipe	2
N 91130802	Shouldered hex nut (converter and downpipe)	16
G 013A8J1G	Coolant additive	1
Outside material	Distilled water (obtain locally)	1

Additional Information

All parts and service references provided in this TSB (2048411) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.