



Technical Service Bulletin

20 MIL on (DTC P046100 - Fuel level sensor, circuit range/performance)

20 17 94 2043357/7 July 20, 2017. Supersedes Technical Service Bulletin Group 20 number 17-88 dated March 24, 2017 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A5, A5 Cabriolet, and Q5	2013 - 2016	All	2.0 TFSI
Q5	2013 - 2016	All	Hybrid
A8	2015	All	3.0 TFSI
A6, A7, Q5, and SQ5	2014 - 2015	All	3.0 TFSI
S4, S5, and S5 Cabriolet	2014 - 2015	All	3.0 TFSI
S8	2013 - 2017	All	4.0 TFSI
RS 7	2014 - 2016	All	4.0 TFSI
S6, S7	2013 - 2016	All	4.0 TFSI
RS 5, RS 5 Cabriolet	2013 - 2015	All	4.2 TFSI
A8	2013 - 2017	All	4.0 TFSI

Condition

REVISION HISTORY		
Revision	Date	Purpose
7	-	Revised <i>Service</i> (Updated SVM table)
6	03/24/2017	Revised header data (Added model years)
5	01/25/2017	Revised <i>Warranty</i> (Updated Warranty description)

- MIL on.

The following DTC may be present in the engine control module (ECM), J623 (address word 0001):

- **DTC P046100** (Fuel level sensor, circuit range/performance)



Technical Service Bulletin

Technical Background

DTC P046100 can be caused by miscalculations within the ECM software when the vehicle is being filled with gasoline while the ignition is on.

Production Solution

New ECM software implemented to correct the condition.

Service

IMPORTANT: Check the vehicle ECM software part number/version prior to the SVM update.

SVM Update Instructions

1. Follow all instructions in TSB 2011732, *00 Software Version Management (SVM), operating instructions*.
2. Update the ECM, J623 (address word 0001) using the SVM action code as listed in the table below.
3. After SVM update, cycle the ignition.
4. Start the engine. If engine runs rough and then surges, cycle the ignition once again.
5. Reset TPMS.

Model	Engine	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version	SVM Code Input
A4,A5,A5 cabriolet	2.0 TFSI	8K5907115N	0001 / 0002 / 0003	8K5907115N	0004	01A203
A4,A5,A5 cabriolet	2.0 TFSI	8K5907115J	0001 / 0002	8K5907115N	0004	
A4,A5,A5 cabriolet	2.0 TFSI	8K5907115P	0001	8K5907115P	0002	
A4,A5,A5 cabriolet	2.0 TFSI	8K5907115M	0001 / 0002 / 0003	8K5907115M	0004	
A4,A5,A5 cabriolet	2.0 TFSI	8K5907115Q	0001	8K5907115Q	0002	
Q5	2.0 TFSI	8R1907115N	0001	8R1907115N	0002	



Technical Service Bulletin

Q5	2.0 TFSI	8R1907115P	0001	8R1907115P	0002
Q5	2.0 TFSI H	8R1907115L	0001 / 0002 / 0003	8R1907115L	0004
Q5	2.0 TFSI H	8R1907115M	0001 / 0002	8R1907115M	0003
Q5	2.0 TFSI	8R1907115F	0001	8R1907115L	0004
S4,S5,S5 cabriolet	3.0 TFSI	8K5907551G	0001 / 0002 / 0003 / 0004 / 0005	8K5907551G	0006
S5,RS5,RS5 cabriolet	4.2 TFSI	8T2907560F	0002 / 0003 / 0004	8T2907560F	0005
Q5	3.0 TFSI	8R0907551F	0001 / 0002 / 0003 / 0004 / 0005	8R0907551F	0006
SQ5	3.0 TFSI	8R0907551G	0001 / 0002 / 0003 / 0004 / 0005	8R0907551G	0006
A8	3.0 TFSI	4H2907551A	0001 / 0003 / 0004	4H2907551A	0008
S6,S7	4.0 TFSI CEUC	4G0906014	0011	4G0906014	0012
S6,S7	4.0 TFSI CEUC	4G0906014A	0007	4G0906014A	0008
S6,S7	4.0 TFSI CEUC	4G0906014B	0008	4G0906014B	0009
S6,S7	4.0 TFSI CEUC	4G0906014E	0005	4G0906014E	0006
S6,S7	4.0 TFSI CTGE	4G0906014C	0005	4G0906014C	0006
S6,S7	4.0 TFSI CTGE	4G0906014D	0001	4G0906014D	0002
RS7	4.0 TFSI CRDB	4G0906560A	0005	4G0906560A	0006



Technical Service Bulletin

RS7	4.0 TFSI CRDB	4G0906560	0011	4G0906560	0012
RS7	4.0 TFSI CRDB	4G0906560B	0007	4G0906560B	0008
RS7	4.0 TFSI CWUB	4G0906560D	0001	4G0906560G	0002
RS7	4.0 TFSI CWUB	4G0906560F	0002	4G0906560F	0003
RS7	4.0 TFSI CWUB	4G0906560G	0001	4G0906560G	0002
RS7 Performance	4.0 TFSI CWUC	4G0906560G	0001	4G0906560G	0002
A8	4.0 TFSI CEUA	4H0906014	0007	4H0906014	0008
A8	4.0 TFSI CEUA	4H0906014A	0005	4H0906014A	0006
A8	4.0 TFSI CEUA	4H0906014B	0004	4H0906014B	0005
A8	4.0 TFSI CEUA	4H0906014C	0004	4H0906014C	0005
A8	4.0 TFSI CEUA	4H0906014D	0004	4H0906014D	0005
A8	4.0 TFSI CEUA	4H0906014H	0005	4H0906014H	0006
A8	4.0 TFSI CEUA	4H0906014L	0004	4H0906014L	0005
A8	4.0 TFSI CTGA	4H0906014G	0007	4H0906014G	0008
A8	4.0 TFSI CTGA	4H0906014J	0005	4H0906014J	0006
A8	4.0 TFSI CTGA	4H0906014K	0004	4H0906014K	0005



Technical Service Bulletin

A8 S	4.0 TFSI CTGF	4H0906014N	0001	4H0906014N	0002	
S8	4.0 TFSI CGTA	4H0907557	0009	4H0907557	0010	
S8	4.0 TFSI CGTA	4H0907557A	0005	4H0907557A	0006	
S8	4.0 TFSI CGTA	4H0907557B	0004	4H0907557E	0004	
S8	4.0 TFSI CTFA	4H0907557E	0003	4H0907557E	0004	
S8	4.0 TFSI CTFA	4H0907557C	0005	4H0907557C	0006	
S8	4.0 TFSI CTFA	4H0907557D	0005	4H0907557D	0006	
S8	4.0 TFSI CTFA	4H0907557F	0002	4H0907557F	0003	
S8 +	4.0 TFSI DDTA	4H0907557G	0003	4H0907557G	0004	
S8 +	4.0 TFSI DDTA	4H0907557H	0001	4H0907557H	0002	
A6,A7	3.0 TFSI	4G0907551J	0001 / 0002 / 0003	4G0907551J	0004	02A210

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • 1E1 up to 8 Years/80,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	2470
Damage Code:	0039



Technical Service Bulletin

Diagnostic Time:	Check software level in ECM (with no update needed)	2470 0199	Max. 10 TU
	GFF –Perform update through GFF and clear faults	0150 0000	Time stated on diagnostic protocol (Max 50 TU)
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2043357/7		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2011732 *00 Software Version Management (SVM), operating instructions.*

All part and service references provided in this TSB (2043357) are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.

©2017 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.