Preliminary Information

PIP5472D Short Duration Misfire - Rough Idle - MIL On During Cold Start - P050D

Models

Brand:	Model:		Model Years:	VIN:		Engine:	Transmissions:	
				from	to	Engine.	mansinissions.	
Buick	Encore		2016 - 2018	All	AII	1.4L (RPO LE2)	All	
Chevrolet	Cruze		2016 - 2018	All	All	1.4L (RPO LE2)	All	
Chevrolet	Equinox		2018	All	AII	1.5L (RPO LYX)	All	
Chevrolet	Malibu		2016 - 2018	All	AII	1.5L (RPO LFV)	All	
Chevrolet	Spark		2016 - 2018	All	AII	1.4L (RPO LV7)	All	
Chevrolet	Volt		2016 - 2018	All	AII	1.5L (RPO L3A)	All	
GMC	Terrain		2018	All	AII	1.5L (RPO LYX)	All	
Involved Region or Country No			America					
Condition			nort duration cold start rough idle, MIL on, P050D with or without P0300 at ambient temperatures etween -10C and +5C (14F to 41F).					
Cause (Si		(Statio	If the SI diagnostic fails to isolate a fuel system component concern, then one or more exhaust SHLA's (Stationary Hydraulic Lash Adjuster) may not bleed off the cold, thick engine oil, causing the exhaust valve not to seal the cylinder for a short duration during cold starts.					

Correction:

If you encounter the P050D with misfires that occur only during the first 15 to 30 seconds of cold start, perform the P050D diagnostic in SI.

If the diagnostic fails to isolate a fuel system component concern, then replace all Exhaust SHLA's. (Stationary Hydraulic Lash Adjuster)

Do not replace the intake side SHLA's as a slow leak rate on the intake side will not cause this issue.

Repair Verification requires a cold start.

After SHLA replacement, following a cold soak at ambient temperatures between -10C and +5C (14F to 41F) start the engine and retest for short duration misfires or the P050D.

Warranty Information

Labo	r Operation	Description	Labor Time
4	061270	Hydraulic Valve Lash Adjuster Replacement	Use Published Labor Operation Time

Version History

	5		
	2/23/2017 - to add 2016-2017 Chevrolet Volt to models list.		
Version	3/09/2017 - to add 2018 to all models.		
	12/11/2017 - to add 2018 GMC TERRAIN.		
	12/26/17 - to advise tech to perform P050D diagnostic prior to following this Pl.		

















