

Solution K24400052 Tuesday, March 6, 2018 7:50:44 PM CET

Solution

Title (customer effect)	Volvo Chassis - Equipped With An Automated Manual Transmission (AMT, I-Shift) - Error Code 126 Displayed In Premium Tech Tool (PTT) While Performing The Calibration Procedure After The Shift Control Housing Has Been Removed And Installed
Cause	Error Code 126 may be displayed in PTT while trying to perform the Calibration procedure after the Shift Control Housing has been removed and installed.
Solution	If the Volvo Chassis - I-Shift - Shift control housing has been removed and installed and during the Calibration procedure - GRADE-X ERROR - Message screen appears with Code 126 displayed with -
	R1AAA - Calibration of Clutch Stroke
	R1AAB - Calibration of Split Cylinder
	R1AAC - Calibration of Main box Cylinders
	R1AAD - Calibration of Range Cylinder
	R1AAE - Calibration of Clutch Cylinder Stroke
	R1AAF - Calibration of Clutch Cylinder Slip Point
	R1AJS - Calibration of Cylinder Sleeve Ultra Low Crawler (ULC)
	listed in the Detailed Information as seen <u>here</u> indicates that a shift fork position was possibly missed during the Shift Control Housing installation.
Solution visibility	Dealer distribution
Function(s)/compon	ent(s) affected
Function affected	transmission, MID 130 – TECU, Diagnostic tool
Function Group	
Function Group	431 gearbox, manual
Customer effect	
Main customer effect	calibration/programming/pairing/missing operation, diagnostics/methodology
Fault code(s)	
OBD 2013 Diagnostic Trouble Codes	error

Conditions

Frequency of occurrence of problem	random
Administration	
Author	ut01793
Last modified by	RU4469V
Creation date	12-02-2016 16:02
Date of last update	20-02-2018 21:02
Status	Published
NA_VOLVO_Vehicle_F	Range
NA_VOLVO_Vehicle_Ra nge	Conventional, VNX, VNL, VNM, VHD, VAH
Engine family	
Engine family	Volvo, D12, 11L Engine, 13L Engine, 16L Engine
Emission Standard	
Emission Standard	US16, US15, US07, US10, US13 OBD, US14 GHG