

Solution K58557784 Tuesday, March 6, 2018 10:14:58 PM CET

Solution

Title (customer effect)	Fuel Injector Offset Learning Diagnostic Trouble Codes (DTC) / Fault Codes Logged In Engine Control Module (EMS); Possible Rough / Uneven Idle - OBD15 Chassis
Cause	OBD15 chassis may set codes for injector offset learning minimum and maximum values. The codes may be accompanied by rough idle, with no other performance complaints or symptoms of injector failure.
 Solution	

Overview

Cylinder balancing is only active at idle speeds, between 500 and 750 RPM. The balancing monitor does not run outside of this speed range, which means the codes do not set under high idle or driving conditions. Offset codes generated with no other injector-related codes and no symptoms aside from a possible rough idle may not indicate a physical injector problem, and diagnosing the codes will in many cases lead lead to no fault found. It has been determined that software may contribute to the problem. Software improvements have been implemented to better control cylinder balancing logic.

Relevant DTCs

The list of all applicable DTCs for this issue is included in the Fault Codes section below.

Repair

If any of the fault codes in the section below are set on an OBD15 engine:

A. Check the EMS Main Software (MSW) part number.

- If the EMS MSW part number is lower than 23167877.P01:

- 1. Update the EMS software
- 2. Reset Cylinder Balance from Premium Tech Tool (PTT) Operation 2387-08-03-01 Cylinder Balancing, located in the Test tab.

3. Run a Cylinder Balance test from the same screen following the reset. Start the test at minimum temperature (140 °F, 60 °C) and monitor balancing until coolant temperature reaches approximately 177 °F (81 °C). This will allow observation of performance during multiple engine modes that are entered during warm-up.

4. If the Cylinder Balance test still shows an issue and/or there are one or more Learning Offset codes that return following the update, follow Guided Diagnostics for the applicable code or codes.

- If the EMS MSW is part number 23167877.P01 or newer, proceed with Guided Diagnostics for the applicable code or codes.

Solution visibility	Dealer distribution
Function(s)/compone	nt(s) affected
Function affected	injectors, regulation (cruise control/engine speed), 110 EMS
Function Group	
Function Group	23 fuel system, excluding gas propulsion, 284 control system, fuel supply
Customer effect	
Main customer effect	calibration/programming/pairing/missing operation, efficiency/abnormal behavior, faul t code/display
Fluid implicated	fuel
Fault code(s)	
OBD 2013 Diagnostic Trouble Codes	P02CC00, P02CD00, P02CE00, P02CF00, P02D000, P02D100, P02D200, P02 D300, P02D400, P02D500, P02D600, P02D700, P101200, P101400, P102300 , P102500, P102700, P102900
Conditions	
Vehicle operating mode	when stationary
Frequency of occurrence of problem	random
Engine speed	500 - 1000 rpm
Administration	
Author	UT0455H
Dealer ID	UT0455H
Last modified by	RU4469V
Creation date	29-01-2018 19:01
Date of last update	20-02-2018 21:02
Review date	10-12-2018 00:12
Status	Published
NA_Reviewer	UT0455H
NA_Author_Group	GTT
NA_MACK_Vehicle_R	ange
NA_MACK_Vehicle_Ran ge	Cabover, Conventional
NA_VOLVO_Vehicle_I	Range
NA_VOLVO_Vehicle_Ra nge	Conventional
Engine family	

Engine family	Volvo, Mack
Emission Standard	
Emission Standard	US15