

SE

Outside Door Handle Sticking

Service Category	Vehicle Exterior		
Section	Door/Hatch	Market USA	Toyota Supports

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION	
2008 - 2015	Sequoia		
2007 - 2015	Tundra		

Introduction

Some 2007 – 2015 Tundra and 2008 – 2015 model year Sequoia vehicles may exhibit an abnormal feeling, dragging or sticking when using the outside door handle. Use the following procedure to address this condition.

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	DRIVETRAIN	BODY	ENGINE	TRIM LEVEL	PRODUCTION CHANGE EFFECTIVE VIN
			4.6L	SR/SR5/TRD	5TFEM5F1#FX090270
				Limited	5TFFY5F1#FX184867
			5.7L	Platinum/1794	5TFGY5F1#FX184882
		Crew Max		Initial Initial STFEM5F1#FX090270 I.6L SR/SR5/TRD 5TFEM5F1#FX184867 5.7L Platinum/1794 5TFGY5F1#FX184882 SR/SR5/TRD 5TFEY5F1#FX184882 SR/SR5/TRD 5TFEY5F1#FX184885 Limited 5TFEY5F1#FX184885 Limited 5TFEY5F1#FX192356 LFFV Platinum/1794 5TFGW5F1#FX192373 5.7L Platinum/1794 5TFEW5F1#FX192376 5.7L SR/SR5/TRD 5TFFW5F1#FX192376 5.7L SR/SR5/TRD 5TFTY5F1#FX008900 5.7L SR/SR5/TRD 5TFTW5F1#FX008975 6.6L 5TFRM5F1#FX008975 5.7L Limited 5TFSY5F1#FX184908 5.7L SR/SR5/TRD 5TFRY5F1#FX184908 5.7L Limited 5TFSY5F1#FX184908 5.7L Limited 5TFRY5F1#FX184897 LFFV Limited 5TFSW5F1#FX192060	
			5.7L FFV Platinum/1794 5TFGW5F1#FX192373	Limited	5TFFW5F1#FX192356
				5TFGW5F1#FX192373	
Tundro		2WD			5TFEW5F1#FX192376
Tundra	2000	Double Cab	5.7L		5TFTY5F1#FX008900
		Long Box	5.7L FFV	5TFTW5F1#FX008975	
			4.6L		5TFRM5F1#FX090284
			5 71	Limited	5TFSY5F1#FX184908
		Double Cab Regular Box	5.7L	SR/SR5/TRD	5TFRY5F1#FX184897
		-	5.7L FFV	Limited	5TFSW5F1#FX192060
				SR/SR5/TRD	5TFRW5F1#FX192357

Production Change Information (Continued)

MODEL	DRIVETRAIN	BODY	ENGINE	TRIM LEVEL	PRODUCTION CHANGE EFFECTIVE VIN
	2WD	Regular Cab	5.7 FFV		5TFNW5F1#FX192403
	2000	Long Box	5.7L	SR/SR5/TRD	5TFNY5F1#FX185010
			4.6L		5TFDM5F1#FX062409
				Limited	5TFHY5F1#FX462270
			5.7L	Platinum/1794	5TFAY5F1#FX462211
		Crew Max		SR/SR5/TRD	5TFDY5F1#FX462318
				Limited	5TFHW5F1#FX462440
			5.7L FFV	Platinum/1794	5TFAW5F1#FX462209
Tundra					5TFDW5F1#FX462128
Tunara	4WD	Double Cab	5.7L	SR/SR5/TRD	5TFCY5F1#FX018744
	400 D	Long Box	5.7L FFV	5R/5R5/1RD	5TFCW5F1#FX018739
			4.6L		5TFUM5F1#FX062406
			c 71	Limited	5TFBY5F1#FX462376
		Double Cab Regular Box	5.7L	SR/SR5/TRD	5TFUY5F1#FX462362
		rtogular Dox	5.7L FFV	Limited 5TFBW5F1#FX4	5TFBW5F1#FX462391
			5.7L FF V		5TFUW5F1#FX474914
		Regular Cab Long Box	5.7L	SR/SR5/TRD	5TFPY5F1#FX462367
			5.7L FFV		5TFPW5F1#FX463212
				Limited	5TDKY5G1#FS059139
	2WD	SUV	5.7L	Platinum	5TDYY5G1#FS059138
				SR5	5TDZY5G1#FS059131
Sequoia	4WD			Limited	5TDJY5G1#FS121016
				Platinum	5TDDY5G1#FS126934
				SR5	5TDBY5G1#FS121013
			5.7L FFV	Limited	5TDJW5G1#FS120886
				Platinum	5TDDW5G1#FS120802
				SR5	5TDBW5G1#FS120996

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
BD1626	R & R Outside Door Handle No. 2, 1 Door	0.2			
BD1626A	R & R Outside Door Handle No. 2, 2 Doors	0.3	69210-0C010 69210-0C020	97	83
BD1626B	R & R Outside Door Handle No. 2, 3 Doors	0.4	69210-0C030-##	97	00
BD1626C	R & R Outside Door Handle No. 2, 4 Doors	0.5]		

APPLICABLE WARRANTY

• This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

• Warranty application is limited to occurrence of the specified condition described in this bulletin.

Parts Information

PART NUMBER		PART NAME	QTY	
PREVIOUS	NEW		QTT	
69210-0C010				
69210-0C020	69210-0C010	Handle Assy, Door, Outside	1 per affected door	
69210-0C030-##				

Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Plastic Pry Tool Kit*	<u>00002-06020-01</u>	1

REQUIRED TOOLS & MATERIAL	QUANTITY
#2 Phillips Screwdriver	1
T30 Torx Driver	1
Thread Locking Compound (Permatex High Strength Threadlocker Red or Similar)	1

* Essential SST.


NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

Repair Procedure


- 1. Remove the outside door handle cover.
 - A. Remove the hole plug.
 - B. Using a T30 torx wrench, loosen the screw and remove the front door outside handle cover and the door lock key cylinder (if equipped) as a unit.

Figure 1. WITH Lock Cylinder




1 Hole Plug

Figure 2. WITHOUT Lock Cylinder



2. Remove the Outside Door Handle Assembly by sliding and pulling it in the direction indicated by the arrow as shown.

Figure 3




Repair Procedure (Continued)

- 3. Disassemble the outside door handle.
 - A. Remove the screw from the Outside Door Handle Assembly previously removed from the vehicle.

NOTICE

- The screw is secured using thread locking compound. When attempting to remove the screw, use a high quality, #2 Philips screwdriver, with an undamaged tip.
- To minimize slipping and to reduce the risk of stripping the screw head, apply firm inward pressure while turning the screw.
- B. Remove the door handle inner from the outside door handle outer cover by rotating it in the direction indicated by the arrow as shown and discard the outside door handle inner.

Figure 4.







Repair Procedure (Continued)

- 4. Disassemble the NEW outside door handle.
 - A. Remove the screw from the NEW Outside Door Handle Assembly.

NOTICE


- The screw is secured using thread locking compound. When attempting to remove screw, use a high quality, #2 Philips screwdriver, with an undamaged tip.
- To minimize slipping and to reduce the risk of stripping the screw head, apply firm inward pressure while turning the screw.
- B. Remove the door handle inner from the outside door handle outer cover by rotating it in the direction indicated by the arrow as shown and discard the outside door handle outer cover.

5. Reassemble the outside door handle.

engaging the 2 tabs.

A. Install the NEW door handle inner to the OLD outside door handle cover by

Figure 6.











Repair Procedure (Continued)

B. Seat the cover by rotating in the direction indicated by the arrow as shown.


Figure 9.




- C. Apply thread locking compound to the threads of the screw.
- D. Install screw in the outside door handle.

Torque: 2.6 N*m (26.5 kgf*cm, 23 in*lbf)

6. Install the Outside Door Handle Assembly by pushing it in the direction of the arrow as shown. Figure 10.




- 7. Install the outside handle cover.
 - A. Using a T30 torx socket, install the outside handle cover and the door lock key cylinder (if equipped) as a unit.
 Torque: 4.0 N*m (41 kgf*cm, 35 in*lbf)



Repair Procedure (Continued)

B. Install the hole plug.





8. Confirm repair and proper vehicle operation.