

Service

Category Drivetrain

Section

Drive Shaft/Propeller Shaft

Market USA



### **Applicability**

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2005 – 2014	Tacoma	Transmission(s): 5AT VDS(s): JU4GN, JU62N, KU4HN, KU72N, LU42N, LU4EN, MU4FN, MU52N, TU4GN, TU62N, UU42N, UU4EN

#### Introduction

Some 2005 – 2014 model year Tacoma vehicles equipped with automatic transmission may exhibit a vibration felt in the seat, floorboard, and steering wheel between 15 – 25 mph caused by a second order drivetrain vibration under acceleration. The following Repair Procedure may improve this condition.

#### Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG8032	R & R Engine Mount	1.0	12371-0P030 12371-0P040 12371-0P041	9B	57
SU1301	Measure Joint Angle and R & R Leaf Springs	1.7	48210-04380 48210-04550 48210-04551 48210-04620 48210-04650 48210-04660 48210-35A20 48210-35A40 48210-35A90 48210-35A90 48220-04170 48220-04190 48220-0490 48220-0490 48220-0490 48220-0490 48220-35020 48220-35040 48220-35060 48220-35070	9B	57
ST1202	Install Steering Wheel Damper	0.6	45713-35050 45713-60030	9B	57



#### Warranty Information (Continued)

#### APPLICABLE WARRANTY

- EG8032 (R & R Engine Mount): This repair is covered under the Toyota Powertrain Warranty. This warranty is in effect for 60 months or 60,000 miles, whichever occurs first, from the vehicle's in-service date.
- SU1301 (R & R Leaf Springs) and ST1202 (Install Steering Wheel Damper): This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this

#### **Required Tools & Equipment**

REQUIRED TOOLS	SUPPLIER	PART NUMBER
Mini-Mag Protractor (or equivalent)	Snap-on®	FFL74422450



#### **Parts Information**

### NOTE

BEFORE ordering parts, please refer to Repair Procedure and Part Number Selection Tables on pages 17 – 19 to order the correct parts for each vehicle.

MODEL VEAR	PART N	UMBER		
MODEL YEAR	PREVIOUS	NEW	PART NAME	QTY
	12371-0P030	12371-31240	RR Engine Mount Insulator (2WD V6)	1
	12371-0P040 12371-0P041	12371-31250	RR Engine Mount Insulator (4WD V6)	1
2005 – 2014	48210-04380 48210-04550 48210-04551 48210-04620 48210-04650 48210-35A20 48210-35A40 48210-35A80 48210-35A90	48210-04580 48210-04590 48210-04650 48210-04660 48210-04670 48210-04680	RR RH Spring Assy	1
	48220-04170 48220-04190 48220-04191 48220-04260 48220-04290 48220-04300 48220-35020 48220-35040 48220-35060 48220-35070	48220-04220 48220-04230 48220-04290 48220-04300 48220-04310 48220-04320	RR LH Spring Assy	1
2005 – 2011	45713-	60030		1
2012 – 2014	45713-	35050	Steering Wheel Damper	1
2005 - 2014	90080-	15079	Screw, w/Washer (for Steering Wheel Damper)	2
Additional Designation of the Control of the Contro	90117-A0001	90117-A0005	U-Bolt	_4_
	90178-A0050		Flange Nut	-8-
2005 – 2014	94622-	51400	Plain Washer	8
	48341-04070 48341-04080	48341-04090	RR Spring Bumper	2

## **TOYOTA**

### **Driveline Vibration**

#### Parts Information (Continued)

#### NOTE

- If the vehicle was built October 2013 or earlier, replace the RR Spring Bumper, U-bolts, Flange Nuts, and washers with new parts listed in the table above.
- If the vehicle was built November 2013 or later, no additional parts need to be replaced.

#### Repair Procedure

- 1. Some level of driveline vibration is normal in all vehicles. However, if vehicle exhibits vibration under the following conditions, proceed to step 2:
  - · 10% throttle input or slow run up.
  - 30% or greater throttle input:

#### HINT

On 4WD trucks the following method can be used to confirm if this bulletin applies to the vehicle:

- · Remove the rear driveshaft.
- Shift into 4WD HI.
- · Test drive the vehicle.
- If the vibration is gone, then this bulletin applies. If the vibration is still present, this bulletin does NOT apply.

#### NOTE

If the vehicle has an aftermarket suspension/body lift or leveling kit installed, this bulletin does NOT apply.

Verify in vehicle history if the vehicle has had Service Bulletin No. T-SB-0249-12 performed.

Has the vehicle had T-SB-0249-12 performed?

YES —

2005 - 2011 MY: Go to step 4.

2012 - 2014 MY: Go to step 5.

NO — Go to step 3.



#### Repair Procedure (Continued)

Replace the Rear Engine Insulator (Rear Transmission Mount).

Refer to the Technical Information System (TIS), applicable model and model year Repair Manual:

- 2005 Tacoma: Drivetrain – Automatic Transmission/Transaxle – "Automatic Transmission Assy (A750E): Replacement"
- 2006 2014 Tacoma: Drivetrain – Automatic Transmission/Transaxle – "A750E / A750F Automatic Transmission: Automatic Transmission Assembly: Removal / Installation"
  - 2006 Tacoma (A750E): Removal / Installation
  - 2007 Tacoma (A750E): Removal / Installation
  - 2008 Tacoma (A750E): Removal / Installation
  - 2009 Tacoma (A750E): Removal / Installation
  - 2010 Tacoma (A750E): Removal / Installation
  - 2011 Tacoma (A750E): <u>Removal / Installation</u>
  - 2011 Tacoma (A750F): Removal / Installation
  - 2012 Tacoma (A750E): Removal / Installation
  - 2012 Tacoma (A750F): Removal / Installation
  - 2013 Tacoma (A750E): Removal / Installation
  - 2013 Tacoma (A750F): Removal / Installation
  - 2014 Tacoma (A750E): Removal / Installation
  - 2014 Tacoma (A750F): Removal / Installation




### Repair Procedure (Continued)

### HINT

Refer to Figures 1 and 2 to confirm the proper part identification by examining the label on the part, and for the proper positioning of the new engine mount in ATM equipped trucks.


Figure 1. 2WD Rear Engine Insulator



1	Front of Vehicle
2	Label

ENGINE	I.D. ON LABEL	LABEL COLOR
1GR	VA	Green

Figure 2. 4WD Rear Engine Insulator



1	Front of Vehicle
2	Label

ENGINE	I.D. ON LABEL	LABEL COLOR
1GR	VA	Green



#### Repair Procedure (Continued)

- 4. Install the Steering Wheel Damper.
  - Remove the steering wheel pad.

#### NOTICE

Wait at LEAST 90 seconds after the ignition switch is turned to the LOCK position and the negative (–) terminal cable is disconnected from the battery before performing this procedure.

Refer to TIS, applicable model and model year Repair Manual:

- 2005 Tacoma: Vehicle Interior – Supplemental Restraint Systems – "Horn Button Assy: <u>Replacement"</u>
- 2006 2014 Tacoma: Vehicle Interior – Supplemental Restraint Systems – "Supplemental Restraint System: Steering Pad: Removal"
  - 2006 Tacoma: Removal
  - 2007 Tacoma: Removal
  - 2008 Tacoma: Removal
  - 2009 Tacoma: Removal
  - 2010 Tacoma: Removal
  - 2011 Tacoma: Removal (06/2010 12/2010) / (12/2010 )
  - 2012 Tacoma: Removal
  - 2013 Tacoma: Removal
  - 2014 Tacoma: Removal



### Repair Procedure (Continued)

B. Remove the steering wheel switch wire harness retainer bracket (only for vehicles with steering wheel mounted switches).


Is the steering wheel switch wire harness retainer bracket present? (See Figure 4.)

- YES Proceed with removal of the bracket.
- NO Proceed to step C.

Figure 3. 2005 - 2011 MY Steering Wheel



Figure 4. 2012 - 2014 MY Steering Wheel



Steering Wheel Switch Wire Harness Retainer Bracket



### Repair Procedure (Continued)


C. Install the Steering Wheel Damper with 2 new screws in the location shown in Figures 5 and 6.

### **CAUTION**

Use care when handling the driver side airbag wire harness during steering wheel damper installation.


Torque: 2.35 N\*m (24 kgf\*cm, 20.8 in\*lbf)

Figure 5. 2005 - 2011 MY Steering Wheel



1	Damper
2	Cruise Control Wire Harness
3	Wire Retainer Hooks

4	Screw
5	Driver Side Airbag Wire Harness



### Repair Procedure (Continued)

Figure 6. 2012 - 2014 MY Steering Wheel



1	Damper
2	Steering Wheel Switch Wire Harness
3	Wire Retainer Hooks

4	Screw
5	Driver Side Airbag Wire Harness

### NOTE

Secure the steering wheel switch wires to the steering wheel damper bracket hooks as seen in Figures 5 and 6.



### Repair Procedure (Continued)

D. Install the steering wheel pad.

Refer to TIS, applicable model and model year Repair Manual:

- 2005 Tacoma: Vehicle Interior – Supplemental Restraint Systems – "Horn Button Assy: <u>Replacement"</u>
- 2006 2014 Tacoma:
   Vehicle Interior Supplemental Restraint Systems "Supplemental Restraint System: Steering Pad: Installation"
  - 2006 Tacoma: <u>Installation</u>
  - 2007 Tacoma: Installation
  - 2008 Tacoma: Installation
  - 2009 Tacoma: Installation
  - 2010 Tacoma: Installation
  - 2011 Tacoma: Installation (06/2010 12/2010) / (12/2010 )
  - 2012 Tacoma: <u>Installation</u>
  - 2013 Tacoma: Installation
  - 2014 Tacoma: Installation
- 5. Raise the vehicle using a drive-on hoist or wheel alignment rack.

### NOTE

Suspension of vehicle MUST be at ride height.



### Repair Procedure (Continued)


6. Measure Propeller Shaft to Pinion Joint Angle (J/A).

#### NOTE

All measurements must be taken from the passenger side of vehicle facing the driver side. Refer to Figure 7 below to ensure that the angles measured have the correct positive (+) or negative (-) values assigned.

- Arrow pointing up indicates a positive angle. In the example on the left, the angle measured is a positive 1.15 (+1.15).
- Arrow pointing down indicates a negative angle. In the example on the right, the angle measured is a negative 0.95 (-0.95).

Figure 7.






### Repair Procedure (Continued)

- A. Measure the Propeller Shaft Angle (P/A).
  - (1) Rotate pinion flange to the correct position as shown in Figure 8.

Figure 8.



1	Up
2	Front
3	Pinion Flange

(2) Use the protractor and measure the angle of the rear section of the 2-piece propeller shaft. Ensure protractor is placed along the centerline of the propeller shaft as shown in Figure 9.

Figure 9. CORRECT Placement of Protractor




Figure 10. INCORRECT Placement of Protractor






### Repair Procedure (Continued)

(3) Record the Propeller Shaft Angle (P/A).

Figure 11.



- B. Measure the Pinion Flange Angle (F/A).
  - (1) Place protractor against flange surface.

Ensure protractor is firmly against the flange to obtain an accurate Pinion Flange Angle as shown in Figure 12.

Figure 12. CORRECT Placement of Protractor



Figure 13. INCORRECT Placement of Protractor





#### Repair Procedure (Continued)

(2) Record the Pinion Flange Angle (F/A).

Figure 14.



C. Obtain the Propeller Shaft to Pinion Joint Angle (J/A).

#### Joint Angle Worksheet

PINION FLANGE ANGLE		PROPELLER SHAFT ANGLE	=	JOINT ANGLE
F/A	_	P/A	=	J/A
	_		=	

#### NOTE

Joint Angle (J/A) can be a negative value.

- 7. Using the Pinion Joint Angle (J/A) value obtained in step 6, select the appropriate leaf spring part numbers from one of the tables below.
  - A. Verify if the vehicle is equipped with Standard or Firm Ride suspension. Look up the factory option codes (accessories) in vehicle history on TIS.

Does the vehicle have option codes CW, OF, OC, or PY?

- YES Vehicle has Firm Ride Suspension. Refer to Table 2 or 4.
- NO Vehicle has Standard Suspension. Refer to Table 1 or 3.
- B. Verify if the vehicle has had T-SB-0249-12 previously performed through vehicle history on TIS.

Has the vehicle had T-SB-0249-12 previously performed?

- YES Refer to Table 1 or 2.
- NO Refer to Table 3 or 4.



### Repair Procedure (Continued)

#### NOTE

Be sure to reference the correct table.

Table 1. Part Number Selection for Vehicles WITH T-SB-0249-12 Performed: Standard Suspension

			STAND	ARD SUSPENSION			
MODEL TYPE	VDS	JOINT ANGLE GREATER THAN 0.9"	JOINT ANGLE BETWEEN -0.3° & 0.8°	JOINT ANGLE LESS THAN -0.4"	JOINT ANGLE GREATER THAN 0.4°	JOINT ANGLE BETWEEN -0.8° & 0.3°	JOINT ANGLE LESS THAN -0.9"
4X2	JU4GN	48220-04290 LH	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH	N/A	N/A	N/A
Double Cab PreRunner	JU62N	48210-04650 RH					
4X2 Double Cab	KU4HN		N/A	N/A	48220-04290 LH 48210-04650 RH	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH
PreRunner S-Long	KU72N	N/A					
	LU42N	48220-04290 LH 48210-04650 RH	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH	N/A	N/A	N/A
4X4 Double Cab	LU4EN						
	MUFN						
4X4 Double Cab S-Long	MU52N	N/A	N/A	N/A	48220-04290 LH 48210-04650 RH	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH
4X2 Access Cab	TU4GN	48220-04290 LH	48220-04220 LH	48220-04230 LH	N/A	N/A	N/A
PreRunner	TU62N	48210-04650 RH	48210-04580 RH	48210-04590 RH	10/2	1974	10//
4X4 Access Cab	UU42N	48220-04290 LH	48220-04220 LH	48220-04230 LH	N/A	N/A	N/A
	UU4EN	48210-04650 RH	48210-04580 RH	48210-04590 RH	1410	1417	NIA
CASTER WEDGE		No Wedge	2 Caster Wedge	3º Caster Wedge	No Wedge	2" Caster Wedge	3" Caster Wedge



## Repair Procedure (Continued)

Table 2. Part Number Selection for Vehicles WITH T-SB-0249-12 Performed: Firm Ride Suspension

			FIRM	RIDE SUSPENSION			
MODEL TYPE	VDS	JOINT ANGLE GREATER THAN 0.9°	JOINT ANGLE BETWEEN -0.3° & 0.8°	JOINT ANGLE LESS THAN -0.4°	JOINT ANGLE GREATER THAN 0.4°	JOINT ANGLE BETWEEN -0.8° & 0.3°	JOINT ANGLE LESS THAN -0.9"
4X2 Double Cab	JU4GN	48220-04300 LH	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH	N/A	N/A	N/A
PreRunner	JU62N	48210-04660 RH					
4X2 Double Cab PreRunner S-Long	KU4HN	N/A	N/A	N/A	48220-04300 LH 48210-04660 RH	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH
	KU72N						
	LU42N	48220-04300 LH 48210-04660 RH	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH	N/A	N/A	N/A
4X4 Double Cab	LU4EN						
	MUFN						
4X4 Double Cab S-Long	MU52N	N/A	N/A	N/A	48220-04300 LH 48210-04660 RH	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH
4X2 Access Cab PreRunner	TU4GN	48220-04300 LH 48210-04660 RH	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH	N/A	N/A	N/A
	TU62N						
4X4 Access Cab	UU42N	48220-04300 LH	48220+04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH	N/A	N/A	N/A
	UU4EN	48210-04660 RH					
CASTER WEDGE		No Wedge	2° Caster Wedge	3° Caster Wedge	No Wedge	2 Caster Wedge	3 Caster Wedge

# **TOYOTA**

## **Driveline Vibration**

### Repair Procedure (Continued)

Table 3. Part Number Selection for Vehicles WITHOUT T-SB-0249-12 Performed: Standard Suspension

STANDARD SUSPENSION										
MODEL TYPE	VDS	JOINT ANGLE GREATER THAN 1.6°	JOINT ANGLE GREATER THAN 1.2°	JOINT ANGLE BETWEEN 0.3° & 1.5°	JOINT ANGLE LESS THAN 0.2°	JOINT ANGLE BETWEEN -0.1° & 1.1°	JOINT ANGLE LESS THAN -0.2°			
4X2 Double Cab	JU4GN	48220-04290 LH	N/A	48220-04220 LH 48210-04580 RH	48220-04230 LH	N/A	N/A			
PreRunner	JU62N	48210-04650 RH			48210-04590 RH					
4X2 Double Cab	KU4HN	N/A	48220-04290 LH 48210-04650 RH	N/A	N/A	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH			
PreRunner S-Long	KU72N									
	LU42N	48220-04290 LH 48210-04650 RH	N/A	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH	. N/A	N/A			
4X4 Double Çab	LU4EN									
	MUFN									
4X4 Double Cab S-Long	MU52N	N/A	48220-04290 LH 48210-04650 RH	N/A	N/A	48220-04220 LH 48210-04580 RH	48220-04230 LH 48210-04590 RH			
4X2 Access Cab	TU4GN	48220-04290 LH 48210-04650 RH	48220-04290 LH	48220-04290 LH	48220-04290 LH	N/A	48220-04220 LH	48220-04230 LH	N/A	N/A
PreRunner	TU62N		N/A	48210-04580 RH	48210-04590 RH	131/1	1375			
4X4	UU42N	48220-04290 LH	N/A	48220-04220 LH	48220-04230 LH	N/A	N/A			
Access Cab	UU4EN	48210-04650 RH	IWA	48210-04580 RH	48210-04590 RH	1973	1977			
CASTER WEDGE		No Wedge	No Wedge	2° Caster Wedge	3° Caster Wedge	2º Caster Wedge	3° Caster Wedge			

Table 4. Part Number Selection for Vehicles WITHOUT T-SB-0249-12 Performed: Firm Ride Suspension

FIRM RIDE SUSPENSION									
MODEL TYPE	VDS	JOINT ANGLE GREATER THAN 1.6°	JOINT ANGLE GREATER THAN 1.2°	JOINT ANGLE BETWEEN 0.3" & 1.5"	JOINT ANGLE LESS THAN 0.2	JOINT ANGLE BETWEEN -0.1° & 1.1°	JOINT ANGLE LESS THAN -0.2"		
4X2 Double Cab	JU4GN	48220-04300 LH	N/A	48220-04310 LH	48220-04320 LH	N/A	N/A		
PreRunner	JU62N	48210-04660 RH		48210-04670 RH	48210-04680 RH				
4X2 Double Cab	KU4HN	N/A	48220-04300 LH 48210-04660 RH	N/A	N/A	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH		
PreRunner S-Long	KU72N								
	LU42N	48220-04300 LH 48210-04660 RH	N/A	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH	N/A	N/A		
4X4 Double Cab	LU4EN								
	MUFN								
4X4 Double Cab S-Long	MU52N	N/A	48220-04300 LH 48210-04660 RH	N/A	N/A	48220-04310 LH 48210-04670 RH	48220-04320 LH 48210-04680 RH		
4X2	TU4GN	48220-04300 LH 48210-04660 RH	N/A	48220-04310 LH 48210-04670 RH	48220-04320 LHJ 48210-04680 RH	N/A	N/A		
Access Cab PreRunner	TU62N		IV/A						
4X4 Access Cab	UU42N	48220-04300 LH	N/A	48220-04310 LH	48220-04320 LH	N/A	N/A		
	UU4EN	48210-04660 RH	1417	48210-04670 RH	48210-04680 RH	,,,,,	1,477		
CASTER V	VEDGE	No Wedge	No Wedge	2° Caster Wedge	3º Caster Wedge	2 Caster Wedge	3° Caster Wedge		




#### Repair Procedure (Continued)

8. Replace the leaf springs with the applicable part numbers from one of the tables above.

#### NOTE

When tightening U-bolt nuts, be sure to set to the following torque:

Torque: 60 N\*m (610 kgf\*cm, 44 ft\*lbf)



#### NOTE

- If the vehicle was built October 2013 or earlier, replace the RR Spring Bumper, U-bolts, Flange Nuts, and washers with parts listed in the Parts Information table.
- If the vehicle was built November 2013 or later, no additional parts need to be replaced.

Refer to TIS, applicable model and model year Repair Manual:

- 2005 Tacoma: Suspension – Rear Suspension – "Rear LH Spring Assy: Overhaul"
- 2006 2014 Tacoma: Suspension – Rear Suspension – "Suspension: Rear Leaf Spring: Removal / Installation"
  - 2006 Tacoma: Removal / Installation
  - 2007 Tacoma: Removal / Installation
  - 2008 Tacoma: Removal / Installation
  - 2009 Tacoma: Removal / Installation
  - · 2010 Tacoma: Removal / Installation
  - 2011 Tacoma: Removal / Installation
  - 2012 Tacoma: Removal / Installation
  - 2013 Tacoma: Removal / Installation
  - 2014 Tacoma: Removal / Installation

#### Repair Procedure (Continued)

#### NOTE

Fasteners for shocks and leaf spring bushings should be tightened. Then torque for these joints should be set while vehicle is on the ground.

9. Test drive vehicle and confirm the vibration has been eliminated. Ensure that there is no vibration under deceleration.

Is vibration still felt between 15 – 25 mph?

- YES If vibration is still present, confirm that repair was performed correctly following the Repair Procedure in this bulletin.
- NO Repair is complete.

T-SB-0008-14