

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan)	2014-2018	All	All	All	All

Condition

46 17 03 November 21, 2017 **2015173** Supersedes Technical Bulletin 46-16-07 (V461607) dated August 23, 2016 to include model year 2018 applicability.

Brake Disc Pulsation or Vibration (U.S. Only)

When applying brakes at highway speeds the following symptoms may occur:

- Brake pedal pulsation
- Vibration felt in vehicle body
- Steering wheel shakes

Technical Background

For brake vibration or pulsation concerns, brake disc machining is allowed between 6 and 12 months or 6,000 and 12,000 miles (whichever comes first) from the warranty in service date.

Production Solution

No production change required.

Service



All policies and procedures outlined in this technical bulletin also apply to sublet brake disc machining. Improperly machined brake discs may cause brake pulsation/vibration after several months in service. The servicing facility will be responsible for these failures.



Procedure:


Remove wheels and separate brake calipers from carrier as outlined in Repair Manual Group 44 – Wheels,
 Tires, Vehicle Alignment and Group 46 – Brakes – Mechanical components in Elsa.

Brake Disc Inspection

A detailed brake disc inspection is needed to determine if the brake disc should be machined or replaced.

- Inspect brake disc friction surfaces on both sides of the brake disc for:
- Severe discoloration (bluing)
- High heat surface damage (raised hard spots)
- Visible cracks

Brake discs showing any of the above described conditions are **NOT** serviceable. Parts must be replaced in accordance with the Volkswagen Warranty Policy and Procedure Manual.



Disc Thickness Measuring

Technician must record the beginning thickness measurements on the back of the repair order.

Each brake disc has the minimum allowed thickness cast, stamped or laser-etched into the disc hub.

Measure the brake disc thickness in 4 locations using either the Pro Cut International™ disc thickness
measuring tool Part No. 50-902 or the Hunter Engineering Company disc thickness measuring tool Part No. 2599-2. Measurements MUST be taken at the same distance from the brake disc outer circumference to ensure
consistency.





(I) Note

The brake disc thickness measurement must exceed the minimum specification after the machining process is completed in order to be re-used. If the brake disc thickness measurement does not meet this requirement, then replace the brake disc

Brake Disc Machining



All brake discs must be machined.


Recommended on-car brake lathes are either the PRO-CUT International ™ PFM 9.0, or the Hunter Engineering Company model OCL 400. This design of brake lathe will produce a surface quality which will provide proper brake performance without a brake pad to brake disc break-in period.

To ensure that a high quality brake disc finish is produced, brake lathe cutting tools must be maintained as directed by the lathe or tool manufacturer.





- Follow the brake lathe manufacturer's instructions for set-up and machining.
- Wash the brake disc with a soap and water solution upon completion of resurfacing to remove all machining particles.



Technician must record the final thickness measurements on the back of the repair order.

Re-measure brake disc thickness in 4 locations using either the Pro Cut International™ disc thickness measuring tool Part No. 50-902 or the Hunter Engineering Company disc thickness measuring tool Part No. 25-99-2. If recorded brake disc measurement is less than the minimum thickness, the brake disc MUST be replaced.



Always replace brake discs in pairs (front axle or rear axle). Do not replace all 4 brake discs unless it is required.





- Measure brake disc lateral run out using Pro Cut Disc Lateral run out measuring kit Part No. 50-700FC or the Hunter Disc Lateral run out measuring kit Part No. 25-128-2 with a dial indicator.
- Run out must not exceed 0.1mm.
- If brake disc exceed the 0.1mm specification replace the applicable brake discs.



Warranty

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To	
All (except Routan)	2014-20	18 AII	All	Ali	All	
Claim Type: Use applicable Claim Type		pplicable Claim Type ¹)			
		SAG	A Coding			
Damage		_	Damage Location (Depends on Service No.)			
4650		0013		Use applicable when indicated in Elsa (L/R)		
			ruan/Eos/ WWO ²⁾ R/e Golf and MY14) 2)	
Parts Manufacturer		Jetta SportWag Golf SportWagen/ <mark>/</mark>	Jetta/Beetle/Beetle Cabrio, MY14 Jetta SportWagen and MY15-18 Golf/Golf SportWagen/Alltrack/Tiguan LWB		3ME ²⁾	
		On Car Lathe is a	vailable (All vehic	les)		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels		44052004 = 50 TU				
Labor Operation 3): Front and Rear Disc Resurfacing – On Vehicle		46504699 = 120 TU				
-		And 46534699 = 120 TU				



Or		
If On Car Lathe is u	navailable:	
CC/Tiguan/l	Eos	
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = 50 TU	
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	46142050 = 90 TU And 46152050 = 90 TU	
Labor Operation 3): Remove and Reinstall Front and Rear Discs	46502050 = 10 TU And 46532050 = 10 TU	
Labor Operation 3): Front and Rear Discs Machining	46504699 = 160 TU And 46534699 = 160 TU	
OR		
Tiguan LW	<mark>/B</mark>	
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = 50 TU	
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	46142050 = 80 TU And 46152050 = 80 TU	
Labor Operation 3): Remove and Reinstall Front and Rear Discs	46502050 = 10 TU And 46532050 = 10 TU	
Labor Operation 3): Front and Rear Discs Machining	46504699 = 160 TU And 46534699 = 160 TU	



OR				
Atlas Atlas				
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = 50 TU			
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	46142050 = 80 TU And 46152050 = 80 TU			
Labor Operation 3): Remove and Reinstall Front and Rear Discs	46502050 = 10 TU And 46532050 = 10 TU			
Labor Operation 3): Front and Rear Discs Machining 46504699 = 160 TU And 46534699 = 160 TU				
Or				
Passat				
Labor Operation 3): Remove and Reinstall Front and Rear Wheels 44052004 = 50 TU				
Labor Operation 3): Remove and Reinstall Front and Rear Discs 46502050 = 70 TU And 46532050 = 70 TU				
Labor Operation 3): Front and Rear Discs Machining 46504699 = 160 TU And 46534699 = 160 TU				
Or				
Jetta/Beetle/Beetle Carbio	and MY14 Jetta SportWagen			
Labor Operation 3): Remove and Reinstall Front and Rear Wheels				



Labor Operation 3): Remove and Reinstall Front	46142050 = 90 TU		
and Rear Brake Carriers	And		
	46152050 = 90 TU		
	46502050 = 10 TU		
Labor Operation 3): Remove and Reinstall Front and Rear Discs	And		
and Real Blood	46532050 = 10 TU		
	46504699 = 160 TU		
Labor Operation 3): Front and Rear Discs Machining	And		
Macining	46534699 = 160 TU		
	Or		
To	puareg		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = 50 TU		
	46502050 = 110 TU		
Labor Operation 3): Remove and Reinstall Front and Rear Discs	And		
and Real Dises	46532050 = 90 TU		
	46504699 = 160 TU		
Labor Operation 3): Front and Rear Discs Machining	And		
	46534699 = 160 TU		
	Or		
MY15- <mark>18</mark> Golf S	portWagen, <mark>Alltrack</mark>		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = 50 TU		
Labor Operation 3): Remove and Reinstall Front Carrier	46142050 = 80 TU		
	46502050 = 10 TU		
Labor Operation 3): Remove and Reinstall Front and Rear Discs	And		
	46532050 = 90 TU (includes carrier)		



Labor Operation 3): Front and Rear Discs Machining	46504699 = 160 TU And				
Macming	46534699 = 160 TU				
Or					
MY14 Golf					
Labor Operation 3): Remove and Reinstall Front and Rear Wheels 44052004 = 50 TU					
	46142050 = 90 TU				
Labor Operation 3): Remove and Reinstall Front and Rear Carrier	And				
and Real Garrier	46152050 = 80 TU				
	46502050 = 10 TU				
Labor Operation 3): Remove and Reinstall Front and Rear Discs	And				
and Rear Discs	46532050 = 10 TU				
	46504699 = 160 TU				
Labor Operation 3): Front and Rear Discs Machining	And				
Macining	46534699 = 160 TU				
	Or				
MY15-18 G	olf/Golf R/eGolf				
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = 50 TU				
Labor Operation 3): Remove and Reinstall Front Carrier	46142050 = 80 TU				
	46502050 = 10 TU				
Labor Operation 3): Remove and Reinstall Front and Rear Discs	And				
and Roal Dioco	46532050 = 90 TU (carrier included)				
	46504699 = 160 TU				
Labor Operation 3): Front and Rear Discs Machining	And				
	46534699 = 160 TU				



Outside Labor: Sublet Machining		Sublet Machining not to exceed Elsa SRT		
Causal Part:		Select Labor		
Diagnostic Time 4)				
GFF Time expenditure	01500000 = 00 T	U max.	NO	
Road Test	01210002 = 10 T		YES	
	01210004 = 10 T			
Technical Diagnosis 01320000 = 00 To		U max.	NO	

Claim Comment: Input "As per Technical Bulletin 2015173" in comment section of Warranty Claim.

Required Parts and Tools

No Special Parts required.

Description	Part No:	Quantity
Pro Cut ™ Disc Thickness Measuring Tool	50-902	1
Hunter Disc Thickness Measuring Tool	25-99-2	1
Pro Cut Disc Lateral Run out Measuring Tool	50-700FC	1
Hunter Disc Lateral Run out Measuring Tool	25-128-2	1
PRO-CUT International ™PFM 9.0	PCIPFM90VW	1
Hunter Engineering Company Model OCL 400	HUNOCL400VW	1

¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with Elsa updates.

⁴⁾ Documentation required per Warranty Policy Procedures Manual.



Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

Document Control Revision Table				
Instance Number	Published Date	Version Number	Reason For Update	
2015173/25	11/21/2017	V461703	To include model year 2018 applicability.	
2015173/24	8/23/16	V461607	To include model year 2017 applicability.	
2015173/23	5/4/16	V461605	Update warranty labor operation for Jetta, Beetle Beetle Convertible and Jetta SportWagen.	
2015173/1	6/11/07	V460701	Original publication.	