

Additional poly-V belt for roof air conditioning or front power take-off torn

Topic number	LI13.20-N-054722
Version	2
Design group	13.20 Belt drive, general
Date	03-26-2013
Validity	Model 906 with OM642 and high-performance A/C in passenger compartment (H08) or front engine power take-off with carrier for additional refrigerant compressor (N63)
Reason for change	The new brackets received in stock are Q02 and no longer have the color dot.
Reason for block	

Complaint:

Poly-V belt for roof air conditioning (H08) or front power take-off (N63) torn

Cause:

Guide pulley on the carrier misaligned

Remedy:

Replace carrier of guide pulley and poly-V belt.

The new brackets are Q02 and no longer have the color dot!

There still might be some stock with carriers with a green or blue dot and they may still be installed.

Symptoms
Body / Air conditioning / Air conditioning / Insufficient cooling output
Power generation / Mechanical engine components / Belt drive / V-belt / Torn/cracked
Power generation / Mechanical engine components / Belt drive / V-belt / Noise

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A 642 230 06 42			Carrier	1	Only install carriers marked with a green or blue dot!	X	

Attachments	
File	Designation
1.jpg	Color dot

WIS-References			
Document number	Title	Note	Allocation
AR13.21-D-0160SF	Remove/install air conditioning refrigerant compressor V-belt		Remedy

Validity		
Vehicle	Engine	Transmission
Sprinter III	642	*

Attachments

1.jpg:

