



SERVICE ACTION H059: BAI ANCER SHAFT WHINE

SFRVICE BULLETIN

29-MAR-18 No.: 6-379NAS SEC.: GENERAL MKT.: CAN / USA INFORMATION

DESCRIPTION OF ISSUE

An issue has been identified on a limited number of Jaguar vehicles within the listed Affected Vehicle Range which may exhibit an audible engine whine noise within the cabin. Investigations have highlighted that the noise is related to the engine balance shaft which requires remedial action with the least amount of delay.

AFFECTED VEHICLE RANGE

F-PACE (X761; INGENIUM I4 2.0	L Diesel)
Model Year:	2017-2018
VIN:	045080-099999; 494996-499964; 880002-899997; 240049-273746
XE (X760; INGENIUM I4 2.0L Die	
Model Year:	2017-2018
VIN:	923882-978627; P10168-P30540
XF (X260; INGENIUM I4 2.0L Dies	
Model Year:	2017-2018
VIN:	Y11889-Y61825

SERVICE PROGRAM / REWORK ACTION

Retailers will replace the engine balance shaft assembly. There will be no charge to owners for this action under this program.

ACTION TO BE TAKEN

Affected vehicles will not be flagged in the Jaguar Land Rover claims submission system or TOPIx until the following steps are complete:

- If a vehicle is suspected of having this issue, submit a Technical Assistance (TA) request for assistance with the diagnosis.
- If investigations confirm a balance shaft concern is present, the VIN will be added to this program.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin H059NAS, Service Action: Balancer Shaft Whine, for detailed repair instructions.

PARTS

NOTE: only order the expected percentage demand of parts identified after the diagnosis has been completed and balance shaft noise issue confirmed.

F-PACE (X761) VEHICLES:

DESCRIPTION	PART NO. / QTY. / VALUE SUNDRY CODE		EXPECTED PERCENTAGE DEMAND	
A/C O-ring	T2R4991	2	100	
A/C O-ring	C2P24809	4	100	

DESCRIPTION	PART NO. / SUNDRY CODE	QTY. / VALUE	EXPECTED PERCENTAGE DEMAND
Balancer Shaft	JDE36994	2	100
Brake Caliper bolt and Washers	T4A16359	4	100
Crankshaft damper bolt	JDE39146	4	100
Damper bracket bolt	T2H17786	2	100
Damper bracket bolt	C2P11385	2	100
Differential oil drain plug	T2H13851	1	100
Differential oil fill plug	T2H13852	1	100
Differential Support bracket to sump seal	T4A18130	1	100
DPF to EGR inlet gasket	AJ813345	1	100
DPF to intermediate exhaust gasket	T2H14088	1	100
DPF to intermediate exhaust nuts	T2H2804	2	100
Drive plate bolt	T2R15200	8	100
Gasket - High Pressure EGR to exhaust manifold	AJ813342	2	100
Halfshaft bolt	T2H9243	4	100
Halfshaft circlip	C2D23748	2	100
Kit - Element & Gasket - Oil Filter	JDE37128	1	100
Lower suspension arm Ball joint nut	T2H3159 2		100
Plug - Oil Drain	AJ813202 1		100
Seal - Crankshaft Oil - Front	JDE38485	1	100
Seal - Crankshaft Oil - Rear	JDE39481	1	100
Sealer - Adhesive - Oil Pan/Engine	STC50550	1	100
Stabilizer link nut, Front arm bush nut, wheel knuckle nut	XR848057	6	100
Torque converter to drive plate	C2D25075	4	100
Track rod end to vertical link Nut	T4N8037	2	100
Turbocharger to Catalyst Gasket	T2H11760	1	100
Wheel hub nut	C2P12731	2	100
Wheel knuckle bolt	T2H6322	2	100
Engine Oil	ZZZ999	*6.25L	*\$102.82
Differential Oil	ZZZ999	**1.0L	**40.00

^{* -} an allowance of \$102.83 USD (or local equivalent) has been provided to cover the cost of the engine oil (6.25L). Claim using Sundry Code 'ZZZ999'.

^{** -} an allowance of \$40.00 USD (or local equivalent) has been provided to cover the cost of the differential oil (1L). Claim using Sundry Code 'ZZZ999'.

XE (X760), XF (X260) VEHICLES:

DESCRIPTION	PART NO. / SUNDRY CODE	QTY. / VALUE	EXPECTED PERCENTAGE DEMAND	
A/C O-ring	T2R4991	2	100	
A/C O-ring	C2P24809	4	100	
Balancer Shaft	JDE36994	2	100	
Bolt shock absorber yoke	T2H17786	2	100	
Bolt shock absorber yoke	C2P11385	2	100	
Brake Caliper bolt and Washers (17" wheels)	T2H18669	4	100	
Crankshaft damper bolt	JDE39146	4 100		
Differential Support bracket to oil pan seal	C2D27326	1	100	
DPF to EGR inlet gasket	AJ813345	1	100	
DPF to intermediate exhaust gasket	T2H14088	1	100	
DPF to intermediate exhaust nuts	T2H2804	2	100	
Drive plate bolt	T2R15200	8	100	
Gasket - HP EGR exhaust manifold	AJ813342	2	100	
Halfshaft bolt	T2H9243	4	100	
Halfshaft circlip	C2D23748	2	100	
Kit - Element & Gasket - Oil Filter	JDE37128	1	100	
Lower suspension arm ball joint nut	T2H3159	2	100	
Plug - Oil drain	AJ813202	1	100	
Seal - Crankshaft Oil - Front	JDE38485	1	100	
Seal - Crankshaft Oil - Rear	JDE39481	1	100	
Sealer - Oil Pan/Engine	STC50550	1	100	
Stabilizer link nut, Front arm bush nut, wheel knuckle nut	XR848057	6	100	
Torque converter to drive plate	C2D25075	4	100	
Track rod end to vertical link nut	T4N8037	2	100	
Turbocharger to Catalyst Gasket	T2H11760	1	100	
Wheel hub nut	C2P12731	2	100	
Wheel knuckle bolt	T2H6322	2	100	
Engine Oil	ZZZ999	*6.25L	*\$102.82	

^{* -} an allowance of \$102.82 USD (or local equivalent) has been provided to cover the cost of the engine oil (6.25L). Claim using Sundry Code 'ZZZ999'.

TOOLS

Refer to the Technical Bulletin referenced above for any required special tools.

WARRANTY

NOTE: an allowance of \$102.82 USD (or local equivalent) has been provided to cover the cost of the engine oil (6.25L). Claim using Sundry Code 'ZZZ999'.

NOTE: an allowance of \$40.00 USD (or local equivalent) has been provided to cover the cost of the differential oil (1L). Claim using Sundry Code 'ZZZ999'.No parts required.

At the time of confirming a booking for vehicle repair, make sure that all outstanding Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

Warranty claims must be submitted quoting the Program Code 'H059', Option Code 'X', and the relevant SRO and parts information. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Use the Jaguar Land Rover claims submission system to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the 31 January 2020 closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)
H059	x	Balance shaft assembly - Renew - F-PACE (X761)	12.49.16	9.1
H059	x	Balance shaft assembly - Renew - XE (X760; AWD)	12.49.16	9.2
H059	x	Balance shaft assembly - Renew - XE (X760; RWD)	12.49.16	7.9
H059	×	Balance shaft assembly - Renew - XF (X260; AWD)	12.49.16	9.3
H059	Х	Balance shaft assembly - Renew - XF (X260; RWD)	12.49.16	7.9
H059	X	Drive in/drive out	10.10.10	0.2

Normal Warranty policies and procedures apply.