

# Solution K95422063 Thursday, May 3, 2018 10:49:56 PM CEST

# NA\_MACK\_Vehicle\_Range

NA_MACK_Vehicle_Ran ge	LR, LEU, MRU, CHU, CXU, GU, TD
Engine family	
Engine family	MP7, MP8, MP10
Emission Standard	
Emission Standard	US16, US15
** SOLUTION **	
Title (customer effect)	Mack Chassis - Diagnostic Trouble Code ( DTC ) P2459 Lighting The Malfunction Indicator Lamp ( MIL ); Possible Frequent Regeneration Requests - OBD15 And US14+OBD16 (Non-Common Rail) Chassis
Cause	OBD15 And US14+OBD16 (Non-Common Rail) Chassis may log DTC P2459 - Diesel Particulate Filter Regeneration Frequency (Bank 1). P2459 may log with or without frequent regeneration requests. Guided Diagnostic steps may complete with No Fault Found.

Solution Overview

OBD15 And US14+OBD16 (Non-Common Rail) Chassis may log DTC P2459 during operation. The diagnostic process that this DTC sets for is the monitor of how often regenerations are requested by the Engine Control Module (EMS), and is intended to determine when the Diesel Particulate Filter (DPF) needs to be serviced or indicate a problem causing rapid soot accumulation. Chassis experiencing repeat occurrences of P2459 are most commonly units operating in applications that involve any of the below:

- Frequent stop-and-go operation (food service deliveries, for example)
- Local operation with little to no drive time at stable highway speeds or short overall distance traveled at one time
  - Passive regeneration only occurs when exhaust temperatures are able to reach the
    correct level and are sustained at that level while the chassis is in motion. These
    conditions are normally only seen during highway operation.
- Operation requiring an extended amount of idling or operation at low speeds (Paving and construction; mining)

## Repair

Verify the chassis emissions level

• Details can be found in the Product Details box on the Product tab in PTT as seen below:



Review the Detailed Status Information for the relevant code on the DTC Readout.



### For US14+OBD15

- Software improvements have been released to address this code. Refer to the table below:

Action Required			
ECM	Main Software	Action Required	
MP7 / MP8	Equal or Less Than 22741784	Update to Latest Software	
MP10	Equal or Less Than 22644017	Update to Latest Software	
ACM	Main Software	Action Required	
MP7 / MP8 / MP10	Equal or Less Than 22741796	Update to Latest Software	

- **Note:** Premium Tech Tool (PTT) may display a message stating that the current software is the latest edition. Follow the option to reload the current software if this occurs.

### For US14+OBD16

- Refer to FSB 284-065 Engine Control Module (EMS) and Aftertreatment Control Module (ACM), Reprogramming.
  - This bulletin is current as of 17 April 2018.

**If software is current and the code is present,** the Confirmed DTC status should be verified to be TRUE as shown above before continuing diagnosis.

	- Codes and symptoms related to P2459 should be diagnosed prior to P2459 itself.		
Solution visibility	Dealer distribution		
Function(s)/compone	nt(s) affected		
Function affected	DPF, 110 EMS, Diagnostic tool		
Function Group			
Function Group	254 catalytic converter; exhaust emission control equipment , 258 emissions after-treatment		
Customer effect			
Main customer effect	regeneration, calibration/programming/pairing/missing operation, diagnostics /methodology, efficiency/abnormal behavior, fault code/display		
Lights/Messages on information display	⚠Driver's information warning pictogram		
Fault code(s)			
OBD 2013 Diagnostic Trouble Codes	P2459		
Conditions			
Vehicle operating mode	when driving, when stationary		
Frequency of occurrence of problem	always		
Road conditions	city driving		
Administration			
Author	RU4469V		
Dealer ID	RU4469V		
Last modified by	RU4469V		
Creation date	12-01-2018 17:01		
Date of last update	23-04-2018 16:04		
Review date	30-04-2017 00:04		
Status	Published		
NA_Reviewer	ut0031h		
NA_Author_Group	GTT		