DISTRIBUTE TO: ☑ Service Manager ☑ Warranty Administrator

# Warranty Procedures Bulletin

## SUBJECT: CLAIM FILING FOR MIS-BUILT FRAMES

#### FRAME PROGRAMS:

ZH6 - Certain 2005 – 2010 Model Year Tacoma Vehicles ZH7 - Certain 2007 – 2008 Model Year Tundra Vehicles ZH8 - Certain 2005 – 2007 Model Year Sequoia Vehicles ZH9 - Certain 2008 Model Year Sequoia Vehicles ZTH – Certain 2001 – 2004 Model Year Tacoma Vehicles BXD/BZD: Certain 2000 – 2003 Model Year Tundra Vehicles Extension of Warranty Coverage for Frame Corrosion/Frame Replacement

### Mis-Built

For frames that are suspected to have been mis-built, dealers should:

- 1. Contact the Parts Technical Support Group (PTSG) at <a href="mailto:prasupport@toyota.com">prasupport@toyota.com</a> with information on the condition and status of repair.
  - a. Include the original part order reference number.
- 2. A Field Product Quality Report (FPQR) should be generated and attached to the communication.
  - a. The report should include photos of the condition and of all labels and stampings on the frame.
  - b. This report can be submitted by region staff (FTS) or dealership personnel.
- 3. Dealership will receive communication back with next direction(s) from PTSG.
  - a. Response will include confirmation of mis-built condition and if applicable, instructions on mis-built frame disposition.

## Warranty Claim Filing for Confirmed Mis-Built Frames

Once the condition is identified, the technician should:

- 1. Time-Punch OFF the Frame Campaign repair
- 2. Open a new RO for the Service Part repair
- 3. Time-Punch **ON** the **Service Part repair**
- 4. Disassemble the mis-built frame and begin reassembling the new frame up to the point where the mis-built condition was discovered
- 5. Time-Punch **OFF** the **Service Part repair**
- 6. Time-Punch back **ON** the **Frame Campaign** and complete the frame replacement

Please ensure this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.

#### Warranty Claim Filing for Confirmed Mis-Built Frames (Continued)

In these instances, 3 claims will need to be submitted:

Claim 1: Normal Frame Campaign claim (as if a mis-built frame was not found) Claim 2 (frame part only): Parts claim through facing PDC

Claim 3 (labor only): Service Part Claim (numbered Items below correspond with the numbering on the illustration below)

- 1. Entitlement Type Service Part (complete Original RO No. section)
- 2. **OFP** Mis-built frame Part Number (starts with 0400-)
- 3. CCR Include what was mis-built
- 4. **Parts** No parts are associated with these claims
- 5. **DSPM Authorization** Required
- 6. **Op Code** 511991
- 7. Labor Time Actual time (per time-punches) within reason

Sublet Authorization Info Opcode Summary Comments Fe	ees Employee
Repair Additional Information Replacement Parts	Alt CCR
Claim Type REGULAR Entitiement Type SERVICE PART	Condition FRAME DOES NOT LINE UP WITH MOUNTS ON BODY
VIN XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Cause MISBUILT FRAME
1 Jo XXXXXX Date XX/XX/XX Miles XX,XXX Auth 5 XXXXXX	Remedy REPLACED FRAME ASSY.
OFP No. 0400 XXX FRAME UB-ASSY Auth Type G - DSP	M Replacement Parts Description Qty
Main Opcode 511994 WWC OTHERS Labor Tax %	
Combo Codes 6 Total (7 po Hrs 0.0 Z Hrs	
Tot Labor Hrs. X Labor Rate XX Hrs X T1 Code XX T2 Code	
Open RO Date XXXXXX	
Original RO No. XXXXX Date XX/XX/XX Miles XX,XXX Service Part Indicate	or 🗸 Installation Failure 🔹 OFP Installer
Judgment Condition Approved Not Approved Return Reas	Manual Warrantori
	Assignment
	Reason/Comment
	✓
Total Labor \$XXX.XX Total Parts Cost \$0.00 Red	quested Amount \$xxx.xx Tax Amount \$0.00
Total Sublet \$0.00 Total Parts Mark-up \$0.00 App	proved Amount Total Fees \$0.
Eind Summary History Related Recovery Related Claimant	Errors ENGLISH Return Print

Note: Documentation may be required (e.g. time punches, Tech Notes, etc.)

Please ensure that this electronic bulletin is printed and distributed to those designated as well as any other appropriate personnel.