

## Technical product information

<b>Topic</b>	Ticking noise from engine bay
<b>Market area</b>	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2050334/3
<b>Level</b>	EH
<b>Status</b>	Draft
<b>Release date</b>	

### New customer code

Object of complaint	Complaint type	Position
engine -> induction system, charging systems, vacuum systems	noise, vibration	

### New workshop code

Object of complaint	Complaint type	Position
engine -> induction system, charging systems, vacuum systems -> central feed vacuum pump	noise, vibration -> noise	

## Vehicle data

### W12 TSI engine vehicles

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
4V14A9	2017	E	SUV BY636 447/W128AG	DDBB	RGQ	QUS
4V14A9	2017	E	SUV BY636 447/W128AG	DDBB	SHT	QUS
4V14A9	2017	E	SUV BY636 447/W128AG	DDBB	QTZ	QUS
4V14A9	2018	E	SUV BY636 447/W128AG	DDBB	SHT	QUS
4V14A9	2018	E	SUV BY636 447/W128AG	DDBB	QTZ	QUS
4V14A9	2018	E	SUV BY636 447/W128AG	DDBB	RGQ	QUS

## Documents

Document name
<a href="#">master.xml</a>

Ticking noise from engine bay

## Customer statement / workshop findings

Ticking noise emanating from rear of Bank 1 cylinder head

## Technical background

Noise from failed vacuum pump

## Production change

N/A

## Measure

A specific vacuum pump failure is known to create a ticking noise.

This ticking noise, on initial inspection, is easily misinterpreted as a fault in the valve train or fuel injector, when in reality it is more likely to be produced by a defective vacuum pump. Therefore always ensure that this type of noise is identified precisely using a stethoscope. Specifically use the stethoscope to check the vacuum pump located at the rear of Bank 1 cylinder head, when this is found to be the origin of the noise then change the vacuum pump and retest.

Note: Typically no Diagnostic Trouble Codes (DTCs) or other symptoms are experienced by the customer with this failure