

**Mack Models**

---

**Mack Model** LR , LEU , MRU , CHU , CXU , GU

---

**Volvo Models**

---

**Volvo Model** VNX , VNL , VNM , VHD , VAH

---

**Engine family**

---

Engine family 11L Engine , 13L Engine , MP7 , MP8

---

**Emission Standard**

---

Emission Standard US16 , US15 , US14 GHG

---

**\*\* SOLUTION \*\***

---

**Title** Diagnostic Trouble Codes ( DTC ) P2080, P2084, P242B Lighting The Malfunction Indicator Lamp ( MIL ) - **US14+OBD13 And OBD15 Emissions (Commonly Model Years 2015 And 2016)**

---

**Cause** Diagnostic Trouble Codes ( DTC ) P2080, P2084, P242B can set due to incorrect calculation of " soak " time of ambient temperature after key off.

---

**Solution****Overview**

Vehicles may exhibit the MIL lamp and one or any combination of the following fault codes and symptoms:

**ECM - Engine Control Module**

P2080 - Exhaust Gas Temperature Sensor Circuit Range/Performance ( Bank 1 Sensor 1 )

P2084 - Exhaust Gas Temperature Sensor Circuit Range/Performance ( Bank 1 Sensor 2 )

P242B - Exhaust Gas Temperature Sensor Circuit Range/Performance ( Bank 1 Sensor 3 )

Failure Mode Identifier ( FMI ) 64 - Signal plausibility failure

**No Diesel Exhaust Fluid ( DEF ) Dosing**

DEF will not be injected with these faults active.

**Unable To Complete A Parked Regeneration**

Aftertreatment Hydrocarbon Injector ( AHI ) injection will not take place with these faults active.


**Parked Regeneration Runs Too Long, And Does Not Complete**

**NO PARTS SHOULD BE REPLACED for these DTCs unless a sensor failure is confirmed.**

## Repair

- Verify the chassis emissions level

- Details can be found in the Product Details box on the Product tab in PTT as seen below:



### For US14+OBD13 (Commonly Model Year 2015) Chassis:

- Software improvements have been released to address this code. If any of these codes are present, the following items should be checked and updated as necessary.

- Engine Control Module (EMS) Main Software (MSW) part number should be 22489791 or later.
- Parameter CWW should be set to 10.

If CWW is not set to 10, the Vehicle Electronic Control Unit (VECU) needs to be programmed after the EMS.

### For OBD15 (Commonly Model Year 2016) Chassis:

- Software improvements have been released to address this code. If any of these codes are present, Engine Control Module (EMS) software should be checked and updated as necessary.

- Main Software (MSW) part number should be 22644015 or later.

### If Software is current:

- Review the Detailed Status Information for the relevant code on the DTC Readout.

Control Unit	DTC	Status
Brake ECU (MD 130)	SID 60 Axel load sensor FM 2 Data erratic, intermittent, or incorrect	Active
Engine Control Module (EMS)	P229F6 NOx Sensor Gas Outlet Removed, Signal Plausibility Failure	Active

Title	Value
Confirmed DTC	True
Pending DTC	False
Test failed	True
Test failed since last clear	True
Test failed this operation cycle	True
Test not completed since last clear	False
Test not completed this operation cycle	False
Warning indicator requested	False

- If Confirmed DTC is **TRUE**: Proceed with diagnostics
- If Confirmed DTC is **FALSE**: Disregard and focus on other symptoms or DTCs relevant to the complaint.

Internal comments (BO) No parts should be replaced for these fault codes, unless a definite sensor failure is found.

Solution visibility **Dealer distribution**

### Function(s)/component(s) affected

Function affected engine , exhaust , DEF Dosing , CV electronic control unit , 1 1 0 EMS , 2 1 0 ACM , EECU , Diagnostic tool

### Function Group



Function Group 254 catalytic converter; exhaust emission control equipment , 258 emissions after-treatment

### Customer effect

Main customer effect regeneration , temperature , calibration/programming/pairing/missing operation , diagnostics/methodology , efficiency/abnormal behavior , fault code/display

Fluid implicated AdBlue

Temperature does not rise in temperature

Lights/Messages on information display  other ,  Engine equipment fault warning pictogram , message on display , - - - , - / - -

### Fault code(s)

OB2013 Diagnostic Trouble Codes POWERTRAIN , P2080 , P2084 , P242B

### Conditions

Vehicle operating mode on start-up , when stationary

Frequency of occurrence of problem always

### Administration

Author RU4469V

Dealer ID RU4469V

Last modified by RU4469V

Creation date	03-07-2018 18:07
Date of last update	03-07-2018 19:07
Review date	15-06-2017 00:06
Status	Published
NA_Reviewer	Jeremy Newton
NA_Author_Group	GTT