

June 2018 Technical Service

THE INSTRUMENT CLUSTER DISPLAYS VARIOUS CHECK CONTROL MESSAGES

New information provided by this revision is preceded by this symbol

This Service Information bulletin replaces SI B61 21 15 dated August 2017

What's New:

· Warranty Information section updated

MODEL

F25 (X3)	F26 (X4)	
Produced up to July 31, 2016		

SITUATION

The instrument cluster displays various check control messages. This includes messages for the PDC (Park Distance Control), DSC (Dynamic Stability Control) and windshield washer system.

There can be many different fault codes stored in the vehicle, including:

Control Module	Fault Code	Fault Description
ICM_25	4827BA	ICM: Procedure error detected
ACSM4	C9542D	Signal (driving speed, 0x19F) invalid, transmitter ICM
DSC_25	480715	Wheel speed sensor: Voltage supply, short circuit, front right
ICM_25	D017C6	Signal (actual wheel speed, 46.0.1) undefined, transmitter DSC
MEVD172Y	1B0A60	Driving speed, plausibility: Minimum speed under load implausible
IHKA25	E71442	Interface instrument panel (distance travelled, kilometer's, 0x330): Signal invalid
DSC_25	480AA3	Wheel speed sensor: Wrong variant, front right
MEVD172Y	1B0A21	Rough road detection: No wheel speed signal received
		DSC interface (actual number of sensor

ICM_25	D017A3	edges wheel, 64.1.2): Signal invalid
DSC_25	48068C	Transfer box: Temporary fault, temperature
MEVD172Y	1B0A67	Vehicle speed, front/right wheel speed sensor, signal change: Not plausible
ICM_25	D017C5	Interface DSC (actual speed, wheel, 46.0.1): Signal invalid
MEVD172Y	1B0A61	Driving speed, plausibility: Minimum speed in coasting/overrun mode implausible
EMF_10	D3AC8D	DSC interface (status, hydraulic function, 25D): Signal invalid
ICM_25	48002C	ICM, ACC: Interface DSC
DSC_25	480AA6	Wheel speed sensor: Plausibility, signal fault, front right
DSC_25	D36D44	Signal (longitudinal torque distribution, front axle/rear axle, 19.3.4) invalid, transmitter VTG
MEVD172Y	1B0A62	Driving speed, plausibility: Road speed signal implausible
HUD_01	D86C07	Interface INSTR. CL. (kilometer reading, 0x330): signal invalid
DSC_25	480AA5	Wheel speed sensor: Plausibility, signal spike, front right
DSC_25	480713	Wheel speed sensor: Plausibility, direction of rotation, front right
PDC_01	E2170C	Interface INSTR. CL. (outside temperature, 0x2CA): signal invalid
ICM_25	D0142C	Instrument panel interface (ambient temperature, 252.1.4): Signal invalid
MEVD172Y	10B101	Outside temperature sensor, electrical: Short circuit to B+
MEVD172Y	10BA41	Outside temperature sensor, plausibility: Ambient temperature less than model temperature
KOMB01	B7F655	Instrument panel: Outside temperature sensor Short circuit to B+
DSC_25	D3542C	KOMBI interface (outside temperature, ID: 0X2CA): Signal invalid
TRSVC01	CAAC0F	Interface INSTR. CL. (outside temperature, 0x2CA): signal invalid
IHKA25	E71417	KOMBI interface (outside temperature, 0x2CA): Signal invalid

CAUSE

The wiring harness below the micro filter housing (right front area of the bulkhead) is damaged from washer fluid leaking into the harness.

CORRECTION

Check and replace the right front "repair" wiring harness (improved part) listed below.

PROCEDURE

- 1. Perform a vehicle test with ISTA and if the faults listed above are stored, proceed to the next step.
- 2. Inspect the wiring for damage.
- 3. Remove the right front wheel and wheel arch cover.
- 4. Remove the micro filter housing.
- 5. Inspect the harness coming though the bulkhead in the right front engine compartment area for any signs of swollen wires (remove the electrical tape to expose the wires).
- 6. If the wires are swollen, refer to the attached procedure to install a repair wiring harness and to check and correct the washer fluid line leak.

Always connect a BMW approved battery charger / power supply(SI B04 23 10).

PARTS INFORMATION

Part Number	Description	Quantity
Refer to ETK	Repair wiring harness section with foamed grommet for connection in vehicle interior	1
61 12 6 825 706	Cover	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	6111900100	
Labor Operation:	Labor	Description:
	Allowance:	
00 63 789	Refer to KSD2/AIR	Check wiring harness for engine compartment on the right and install repair wiring harness section with grommet (includes connecting an approved battery charger/power supply and performing a vehicle test) (Plus work)

Refer to KSD2/AIR for the corresponding flat rate unit (FRU) allowance.

Other Repairs

If the wiring is found **not** to be the cause and performing the ISTA diagnostics and related test plans results with other eligible and covered work, claim this work with the applicable defect code and labor operations listed in

KSD2.

Overlapping Labor Procedure – Other Repairs

If invoicing the KSD2 flat rate labor operation codes for other repair work results in overlapping labor, for those flat rate labor operations that are affected, you can now:

• Replace the stated KSD2 "FRU allowance" with a "reduced FRU value" to eliminate the overlapping labor.

For help in identifying the overlapping labor, please refer to the AIR FRU Plausibility Check (Overlapping Labor Tool) that is located in the AIR Client.

Eligible other repair work being claimed under a different defect code will require separate punch times.

On the repair order and in the claim comment section, please identify and itemize those labor operations being claimed with a "reduced FRU value."

Posted: Wednesday, June 20, 2018


ATTACHMENTS


View PDF attachment B612115 AttachmentV3.

[Copyright ©2018 BMW of North America, Inc.]

Preliminary Work:	
 Disconnect the battery – ISTA repair 	
instructions 61 20 900	
Remove the microfilter housing	
Remove the right front wheel	
 Remove the right front wheel arch cover 	
(front section) – repair instructions 51 71 038	
Remove the right front wheel arch cover (rear	
section) – repair instructions 51 71 039	
	Removal of existing wiring harness
	Behind Right Front Headlight
	• Open the brake line holder (1)
	where shown
	Remove the DSC hydraulic unit
	mount screw (2) where shown
1930 A 4 4 A	
98,	
	Right Side of Dash
	Remove the glove box – repair
	instructions 51 16 366
	Remove the blower motor for the
	heating and air conditioning –
	repair instructions 64 11 213
	Remove the vehicle interior fuse
	box – repair instructions 61 13 050
	Remove the side trim panel for the
	foot well at the A-pillar – repair
	instructions 51 43 075
	Lay the carpet carefully to one
	side
	• Secure the wiring harness (1) to
	the dashboard carrier (2) with a
	cable strap (3).

Remove the nut (4)
 Disconnect the wiring harness (5)
 Front of Right Front Wheel well Unplug all the wiring harness plug connections (red arrows). Based on the vehicle options there might be more connections to unplug Unfasten all the wiring harness mounting points (blue arrows) Guide the wiring harness up and out of the wheel arch area
 Rear of Right Front Wheel well Unplug all the wiring harness plug connections (red arrows). Pull the grommet out of the body (1) Guide the wiring harness through the opening (1) into the engine compartment
 Behind Right Front Headlight Remove the nut from the ground comb connector (1) and remove the ground comb






headlight	the	repair kit	at the vehicle			headlight	the	repair kit	at the vehicle					
E5*1B	X	344*2B	X844*2S	u	ntil 04/20)14	E5*1B X844*2B		344*2B	X844*2S	since 04/2014			
chamber		chamber	chamber	Halogen	AHL	Xenon	chamber		chamber	chamber	Halogen	AHL	Xenon	LED
in the plug		in the plug	in the plug	(BASIS)	(S524A)	(S522A)	in the plug		in the plug	in the plug	(BASIS)	(S524A)	(S522A)	(S552A)
1	SWGN	6	6	SWGN	BLBR	BLBR	1	SWGN	6	6	SWGN	BLBR	BLBR	BLBR
2	BR	-	-	-	-	-	2	BR	-	-	-	-	-	-
3	GEBL	7	7	GEBL	GEBL	GEBL	3	GEBL	7	7	GEBL	GEBL	GEBL	RTGE
4	BR	-	-	-	-	-	4	BR	-	-	-	-	-	-
5	GERT	8	8	GERT	GERT	GERT	5	GERT	8	8	GRRT	RTGN	GNSW	RTGN
6	WSSW	9	9	WSSW	WSSW	WSSW	6	WSSW	9	9	WSSW	-	GERT	-
7	BR	-	-	-	-	-	7	BR	-	-	-	-	-	-
8	GESW	11	11	GESW	GESW	GESW	8	GESW	11	11	GESW	WSRT	WSRT	WSRT
9	GEBR	12	12	GEBR	GNSW	GNSW	9	GEBR	12	12	GEBR	GEWS	-	GEWS
10	BLSW	13	13	BLSW	WSRT	WSRT	10	BLSW	13	13	BLSW	GESW	-	GESW
11	BLBR	14	14	BLBR	BR	BR	11	BLBR	14	14	BLBR	-	-	BR
12	BLBR	10	10	BLBR	BLBR	BLBR	12	BLBR	10	10	SWGN	-	-	GESW

conversion instruction swollen harness F25


At the vehicle with halogen headlight, are 2 lines with the same color (BLBR) at the vehicle. after separting the lines, check on passage and suitable connect

FRMFA A58*2B chamber 30, auf E5*1B chamber 11

FRMFA A58*2B chamber 8, auf E5*1B chamber 12







 Rear of Right Front Wheel well Guide the wiring harness through the opening (1) from the engine compartment Mount the grommet (1) in place Secure the wiring harness in place (blue arrows) Plug in all the wiring harness plug connections (red arrows).
 Front of Right Front Wheel well Guide the wiring harness down and into the wheel arch area Secure the wiring harness in place (blue arrows) Plug in all the wiring harness plug connections (red arrows). Based on the vehicle options there might be more connections to plug in

	 Behind Right Front Headlight Install the DSC hydraulic screw (2) Close the brake line holder (1) where shown
 After all the wiring harness connections are made, connect the battery and perform a functional check on the vehicle to make sure everything is working. Verify that the windshield washer system has no leaks 	
 Follow-up work Install the right front wheel arch cover (rear section) – repair instructions 51 71 039 Install the right front wheel arch cover (front section) – repair instructions 51 71 038 Install the right front wheel Install the microfilter housing Install the side trim panel for the foot well at the A-pillar – repair instructions 51 43 075 Install the vehicle interior fuse box – repair instructions 61 13 050 Install the blower motor for the heating and air condisitoning system – repair instructions 51 16 366 Reconnect the battery - repair instructions 61 20 900 Retest all functions and clear all faults 	