



Mack Models

Mack Model AN-Anthem , CHU-Pinnacle, Axle back , CXU-Pinnacle, Axel forward , GU-Granite , TD-Titan

Volvo Models

Volvo Model VNR , VNX , VNL , VNM , VHD , VAH

Engine family

Engine family 11L Engine , 13L Engine , 16L Engine , MP7 , MP8 , MP10

Emission Standard

Emission Standard 2018 , OBD2017 , US17 , US16 , US15 , US13 OBD , US14

**** SOLUTION ****

Title Diagnostic Trouble Code (DTC) P10AE Logged In TECU With ACTIVE Or INACTIVE Status, Fault Code Cannot Be Cleared; Possibly Accompanied By P105817 And P105818 - **US10+OBD13 And Newer Emissions (16-Pin Diagnostic Connector), Commonly Model Year 2014 And Newer**

Cause P10AE81 may be generated in OBD13 and newer chassis. The code may show to be in Active or Inactive status and cannot be cleared if Active. P10AE81 may or may not be accompanied by P105817 and P105818

This fault is intended to prevent unintended movement that could result from a related mechanical failure in the gearbox.

P10AE is generated when the Gearbox status is reported as Neutral, but the countershaft to mainshaft gear ratio results in speed signals that indicate that the transmission is NOT in neutral when the clutch is engaged. The active fault will cause the following symptoms:

- Red STOP Lamp will be illuminated
 - If the vehicle is running when the fault occurs, the gearbox will not shift and will keep the clutch disengaged.
 - If the vehicle is shut down with the fault active, a no crank / no start condition may be observed if gearbox air pressure is too low when trying to restart the unit.
-

Solution

DO NOT PROGRAM THE TECU TO TRY TO RESOLVE THIS FAULT

1. If P10AE is ACTIVE and the engine will Crank and Run

Main symptom: The clutch will remain disengaged if a gear is selected via the gear selector

- 1.1.** Allow the unit to idle for 30-45 seconds.

1.2. Check the status of P10AE81.

1.2.1. If the code is still **active** after idling: The gearbox should be investigated for possible mechanical issues

1.2.2. If the code is **inactive** after idling: The code in this case was a ghost or intermittent fault. Items in Section 3 should be reviewed to confirm there are no other issues that need to be addressed.

2. Operate the vehicle if possible to evaluate mechanical condition.

3. Review the DTC Readout and follow the appropriate steps below:

3.1. If P10AE81, P105817 and P105818 all appear on the DTC Readout and are setting at the same time: Replace the ribbon harness, proceed to Section E.

3.2. If P10AE81 is logged separately: Inspect for mechanical failure

3.2.1. If mechanical failure is noted: Repair as required. (A true mechanical cause for this fault will likely never pass the monitor and allow the fault to become inactive)

3.2.2. If there is no mechanical issue present: Replace the ribbon harness and proceed to Section 4.

- **NOTE:** High counts of P10AE81 with no indication of a mechanical issue make the internal transmission harness the likely cause.

4. Once the issue(s) has been corrected:

4.1. Start and idle the truck for 30-45 seconds.

4.2. Confirm P10AE81 is inactive.

4.3. Clear all of the inactive faults

4.4. Road test and release the vehicle to service.

Solution visibility

Dealer distribution

Support Area

Americas , CBR

Function(s)/component(s) affected

Function affected

automatic transmission , engagement , 3 1 0 TECU

Function Group

Function Group

43 gearbox , 47 gearbox and reverse gear (or forward gear) combined system

Customer effect

Main customer effect

calibration/programming/pairing/missing operation , diagnostics/methodology , stop /start , fault code/display , loss of drive

Fault code(s)

OBD 2013 Diagnostic
Trouble Codes P1058-17 , P1058-18 , P10AE

NA_MIDs MID 130 PSID 29 FMI 7 / P10AE81

Conditions

Vehicle operating mode on start-up , engagement

Frequency of occurrence of
problem random

Engine speed <500 rpm , 500 - 1000 rpm

Warning light/lamps
/pictograms red

Other conditions after a workshop procedure on the vehicle

Administration

Author UT9268H

Dealer ID UT9268H

Last modified by RU4469V

Creation date 02-05-2018 16:05

Date of last update 23-10-2018 22:10

Review date 02-05-2019 00:05

Status Published

NA_Reviewer ut9268h

NA_Author_Group GTT
