# **Technical product information**

Topic	Steering rack noise during extended city drive cycle
Market area	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
Brand	Bentley
Transaction No.	2046733/5
Level	EH
Status	Approval
Release date	

### New customer code

Object of complaint	Complaint type	Position
running gear -> steering, power-assisted steering -> steer	noise, vibration -> noise	

### New workshop code

Object of complaint	Complaint type	Position
running gear -> steering system -> steering gear -> electro-mechanical steering torque sensor	component / consumables -> incorrectly installed	

# Vehicle data

# **Bentayga**

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	Е		*	*	*
4V1*	2018	E		*	*	*

## Chasis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	То	Prod from	Prodto
SJA	***	**	*	*	*	000001	019889		

# **Documents**

Document name master.xml

#### **Technical product information**

Steering rack noise during extended city drive cycle

### **Customer statement / workshop findings**

Steering grinding noise after vehicle driven for extended period in city conditions

### **Technical background**

Steering rack internal torque sensor defective

### **Production change**

Redesigned torque sensor

### **Measure**

In order for this noise to be present, the steering must be in motion. The noise is only present after extended city driving. Please also refer to TPI 2048616 and listen to both videos to verify the correct TPI to be applied

Transaction No.: 2046733/5

Listen to the below video:

#### https://vimeo.com/291048094

In the event the customer complaint can be clearly assigned to the above video, please refer to the following instructions:

**Left hand drive prior to VIN** SJAAF14V1JC018474 (4N1) steering racks: If the symptom detailed in this TPI has been reported by the owner and confirmed please replace the steering rack – refer to workshop manual Rep. Gr 48 Steering rack and power steering control unit (J500) - To remove and fit

 $\textbf{Right hand drive prior to VIN} \, \text{SJAAE14V9JC019889 (4N2) steering racks: If the symptom detailed in this TPI has been reported by the owner and confirmed please replace the steering rack - refer to workshop manual Rep. Gr 48 Steering rack and power steering control unit (J500) - To remove and fit$