

Macan (95B) Leak Diagnosis Pressure Switch—Particular Replacement Parts May Be Faulty

Vehicles Affected

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan	2015-2018	95B	N/A	N/A

Revision History

Revision	Release Date	Changes
0	August 16, 2018	Original document

Condition

When part 9A7 906 253 00 (pressure switch, similar to figure 1) is ordered, the technician may receive one of two different versions of this part. These parts will be marked with either of these two auxiliary part numbers:

8K0 906 253 **K**
8K0 906 253 **L**

If the technician installs 8K0 906 253 **K**, DME fault P202400 (Tank leakage diagnosis module: signal line) will set and possibly illuminate the MIL.

If the technician installs 8K0 906 253 **L**, the system operates as designed.



Figure 1

Service Information

There was a parts supply error and incorrect parts were stocked. An order to correct this error has been initiated and the stock will be clean soon.

Upon receipt of the pressure switch, make sure to look for the auxiliary part number. Do not install parts with auxiliary part number 8K0 906 253 **K**. File a PTAR and request assistance from PCNA.

Search Items

Leak; leakage; pressure; switch P202400; P2024; MIL; breakdown

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.