



## Preliminary Information

### PIT4205B Adding RPO AU0 Remote Keyless Entry

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Rainier	2004 - 2007	All	All	All	All
Chevrolet	Trailblazer	2002 - 2009	All	All	All	All
GMC	Envoy	2002 - 2009	All	All	All	All
Oldsmobile	Bravada	2002 - 2004	All	All	All	All

#### Supersession Statement

This PI was superseded to update model years. Please discard PIT4205A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### Condition / Concern

**Vehicle does not have Remote Keyless Entry (RPO AU0) and customer would like to pay to have it added.**

#### Recommendations / Instructions

**It is possible to add RKE to a certified factory built vehicle. However, in doing so, the dealer/customer also assumes total responsibility for all costs associated with this add-on. To add this feature, it may be necessary to replace the LGM and will require the addition of key fobs the customer is requesting to have programmed. Once all the parts are obtained, it will be necessary to REPROGRAM the LGM and REPROGRAM the BCM with the calibration designed for keyless entry. These calibrations typically exist in TIS2WEB for each vehicle. If the calibration is not in TIS2WEB for the vin in question, it will be necessary to contact Techline for a VCI number or a change to this vehicles calibration files so this feature can be added. If a VCI number cannot be provided for the LGM in the customers vehicle, a replacement LGM will be required. Be sure the LGM is ordered with RPO AU0 Keyless Entry.**

#### Programming Procedures

- 1) Request Information from the vehicle. Make sure that ignition 1 voltage is at 12.5v. This can be verified by using the tech 2 and viewing the BCM data list.**
- 2) Connect the tech 2 to the Techline terminal. Select "Service Programming Systems".**
- 3) Next select "tech 2" as the "Diagnostic Tool" and for the "Programming Process" select "Replace and Program ECU".**
- 4) Next in the "Supported Controllers" select the "LGM".**
- 5) Next in the "Calibration Selection" this will give a view of the calibrations available for this controller. The calibration needed for RKE is located under the "Lift Gate Control" tab. Select the calibration that shows "Calibration For Vehicles With Remote Keyless Entry". Once selected, view the "Summary of the calibration and download to the vehicle.**
- 6) After the LGM programming is successful, it will be necessary to request information from the vehicle again. This time it will be necessary to reprogram the BCM.**
- 7) Connect the tech 2 to the Techline terminal. Select "Service Programming Systems".**
- 8) Next select "tech 2" as the "Diagnostic Tool" and for the "Programming Process" select "Reprogram ECU".**
- 9) Next in the "Supported Controllers" select the "BCM".**

**10) Next in the "Calibration Selection". The calibration needed for RKE is located under the "Locking" tab. Select the calibration that shows "Calibration For Vehicles With Remote Keyless Entry". Once selected, view the "Summary of the calibration and download to the vehicle.**

**11) Once programming has been completed and programming was successful for both modules, it will be necessary to program the key fobs. This is done with the tech 2. Follow SI2000 doc 665615 to complete the programming process.**

**Note: RKE (RPO AUO) is not standard equipment on 1SA or 1SB packaged Trailblazers and would have to ordered separately.**

**RKE is standard with 1SC, 1SD, 1SE or 1SF packages. For the GMC Envoy/Envoy XL/Envoy XUV, Oldsmobile Bravada and Buick Rainier, RKE is standard equipment.**

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



© 2018 General Motors. All Rights Reserved.