



ATU (Audi Technical Update)

Summer 2018



Powertrain
Summer 2018



ATU topic

4.0 TFSI – Camshaft Diagnosis

Table of Contents

01.

4.0 TFSI Camshaft Adjuster

1.1 Overview

02.

Camshaft Adjuster Repairs

03.

Optimized Components

04.

Published TSBs

TSB 2041097


TSB 2049153

TSB 2042071

01. 4.0 TFSI Camshaft Adjuster


1.1 Overview

Adjustment of **intake** and **exhaust** side on banks 1 & 2



01. 4.0 TFSI Camshaft Adjuster

1.1 Overview



Important:

There is a distinction between problems with actuators for COD, camshaft control valves and problems with camshaft adjuster!

1. Actuators for COD (cylinder on demand).
2. Hall sender (G40).
3. High-pressure fuel pump.
4. Camshaft control valve 1 (N205).
5. Exhaust camshaft control valve 1 (N318).
6. Hall sender 2 (G163).
7. Cylinder head cover.


02. 4.0 TFSI Camshaft Adjuster Repairs

- › Possible customer concern:
 - › Exhaust emissions warning lamp or EPC warning lamp is on.

- › Workshop findings:
 - › There are DTCs regarding the camshaft adjuster stored in the engine control module (single DTC or combination of DTCs):
 - › **DTC P0011** (Bank 1, retarded camshaft timing, spec. not achieved) intake with symptom 2795.
 - › **DTC P0021** (Bank 2, retarded camshaft timing, spec. not achieved) intake with symptom 9040.
 - › **DTC P052A** (Camshaft adjustment, intake, bank 1 specification not reached during cold-start) with symptom 10540.
 - › **DTC P052C** (Camshaft adjustment, intake, bank 2 specification not reached during cold-start) with symptom 10541.

02. 4.0 TFSI Camshaft Adjuster Repairs

- › Damage:
 - › Broken filter element on camshaft control valve.




Strainer missing

Strainer OK

02. 4.0 TFSI Camshaft Adjuster Repairs


Recommended repair procedure:

- › Check control valve for damage to filter element:
 - › Filter element OK → Recommendation: Clean oil passage between control valve and camshaft control valve with compressed air and replace camshaft adjuster on affected cylinder bank (as shown in DTC).
 - › Filter element not OK → Replace the control valve.
 - › **Important:** Identify optimized camshaft adjuster based on the production code on camshaft adjuster!
 - › **Important:** The chain drive glide rail part number 079109470A should be checked when replacing the camshaft adjuster. Replace the glide rail if it is not part number 079109470A.



03. Optimized Components

- › Identify optimized camshaft adjuster based on the production date of camshaft adjuster.



Example: 10.10.2015

Month Year Day

Optimized components manufactured from:

09T08 (09/08/2016)

| | |
|---|--------|
| T | → 2016 |
| S | → 2015 |
| R | → 2014 |
| Q | → 2013 |
| P | → 2012 |

03. Optimized Components

Optimized inlet camshaft adjuster:

- › Check control valve for damage to filter element. Dimensions of locking pin adjusted due to tolerances being too narrow, which may result in locking pin becoming stuck.
- › Part number 06E109083N has not changed. Identify optimized components based on the production date (camshaft adjuster production date from 09/08/2016 onwards).
- › Optimized components used in vehicle production since 09/29/2016 onwards.
- › The exhaust camshaft adjuster is not affected!

Optimized control valves:

- › Optimization of filter element.
- › Part number of optimized components: 06E109257T.
- › Optimized components used in vehicle production since July 2015 onwards.

Optimized chain drive glide rail:

- › Dimensions of glide rail changed to reduce stress on the glide.
- › Part number of optimized glide: 079109470A.
- › Optimized glides used in vehicle production since April 2017 onwards.

03. Optimized Components

TSB 2041097/* “01 MIL on (DTC P001100 and/or P002100 – camshaft position)”


- › Check control valve for deviations, especially in area of oil strainer.

TSB 2049153/* “01 MIL on, DTC P001100 and/or P002100 – camshaft position after completing TSB 2041097”

- › Check control valve for deviations, especially in area of oil strainer.
- › Replace relevant intake camshaft adjuster only and clean out oil passage with compressed air.
- › Check production date of camshaft adjuster.

TSB 2042071/* “01 MIL on, DTC entries about AVS adjustment”

- › Identify affected camshaft control valves through comparison with DTC in engine control module.



ATU topic

A3 e-tron refuelling issue

Table of Contents

01.


Refuelling e-tron – Tank Cap Actuator Defective

1.1 Overview

01. Refuelling e-tron – Tank Cap Actuator Defective

1.1 Overview

| | |
|--------------------------|--|
| <u>Models affected:</u> | A3 e-tron (8V). |
| <u>Customer concern:</u> | Vehicle cannot be refuelled. |
| <u>Tasks performed:</u> | Ventilation/bleeding of tank checked; borescope inspection of filler pipe performed. |
| <u>Cause:</u> | Tank flap could be opened without pressing button in driver door beforehand (locking element defective); gives impression that vehicle can be refuelled although tank has not yet been bled. |
| <u>Service solution:</u> | Press button in driver door and replace the tank cap actuator. |



As always, complete diagnosis before replacing any parts.

Fuel tank shut-off valve N288

Tank pressure sensor G400



Thank you!