

Preliminary Information

PIT5570B Tailgate and Cargo Loop Capacity

Models

| Brand: | Model: | Model Years: | VIN: | | Engine | Transmissions: |
|-----------|---------------------|--------------|------|-----|---------|----------------|
| | | | from | to | Engine: | Transmissions. |
| Chevrolet | Silverado | 2000 - 2018 | All | All | All | All |
| Chevrolet | Silverado 1500 LD | 2019 | All | All | All | All |
| Chevrolet | Silverado 2500/3500 | 2019 | All | All | All | All |
| GMC | Sierra | 2000 - 2018 | All | All | All | All |
| GMC | Sierra 1500 Limited | 2019 | All | All | All | All |
| GMC | Sierra 2500/3500 | 2019 | All | All | All | All |

<u>Supersession Statement</u>

This PI was superseded to update Model Years. Please discard PIT5570A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A Customer may ask how much weight the tailgate or cargo loops can handle.

Recommendations / Instructions

The tailgate can handle 1000 lbs. evenly spaced across the entire tailgate.

The cargo loops, located at each corner near the floor of the bed, can handle 250lbs each. (This is not the Cargo Management System).

Please note if using ramps (example: Loading ATV's, Lawn mowers, etc.) it may be necessary to remove the tailgate and place the ramps on the bed of the truck. Ramps do not evenly space the load across the entire tailgate and can overload the tailgate.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



© 2018 General Motors. All Rights Reserved.