



SI B13 05 12
Fuel Systems

September 2013
Technical Service

This Service Information bulletin supersedes SI B13 05 12 **dated November 2012.**

NEW designates changes to this revision

SUBJECT

N20 Engine: Ticking Noise from High-pressure Fuel Pump

MODEL

NEW F30

NEW From SOP to May 21, 2012

SITUATION

The customer complains of a high-frequency ticking noise from the engine compartment. The noise can be heard inside and outside the vehicle.

CAUSE

Mechanical vibrations inside the high-pressure fuel pump

CORRECTION

Install high-pressure fuel pump acoustic cover P/N 13 51 7 629 169. The plastic acoustic cover will snap onto the high-pressure fuel pump.

Do not remove the fuel lines or the high-pressure fuel pump to install the acoustic cover.

PARTS INFORMATION

Part Number	Description	Quantity
13 51 7 629 169	Acoustic cover, high-pressure fuel pump	1

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Defect Code:	13 53 15 39 00	
Labor Operation:	Labor Allowance:	Description:
13 99 000	3 FRUs	Work time for installing acoustic cover for high-pressure fuel pump (Main work)

or

Labor Operation:	Labor Allowance:	Description:
		Work time for installing acoustic cover for

13 99 000

1 FRU

high-pressure fuel pump (Plus work – Vehicle is already in the workshop)

[Copyright ©2013 BMW of North America, Inc.]