



Technical Service Bulletin

SUBJECT:			No: TSB-18-21-001
TORQUE UPDATES: UNITS OF TIGHTENING TORQUE & NUMERICAL VALUE FOR CLUTCH - SERVICE MANUAL REVISION			DATE: December 2018
			MODEL: 2008 -2014 Lancer Evolution
CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER

PURPOSE

This TSB updates the Clutch section of the affected Service Manuals to correct the tightening torque for the clutch fluid air bleeding nipple.

AFFECTED VEHICLES

- 2008 - 2014 Lancer Evolution

AFFECTED SERVICE MANUAL

- 2008-2014 Lancer Evolution Service Manual, Group 21 - Clutch



Please make the indicated changes to the 2008 - 2014 Lancer Evolution Service Manual, Group 21 - Clutch -> On-Vehicle Service -> Clutch Bleeding.


CLUTCH BLEEDING

CAUTION

Use the clutch fluid of the specified brand name. Do not mix the fluid with other products.

Specified fluid: DOT 3 or DOT 4

1. Remove the air cleaner element, air cleaner intake duct, and air cleaner body. (Refer to GROUP 15, Air Cleaner.)
2. Remove the cap. Then, connect the air bleeding hose to the air bleeding nipple.
3. Loosen the air bleeding nipple.
4. Perform the air bleeding by depressing the clutch pedal.
5. Remove the air bleeding hose. Tighten the air bleeding nipple to the specified torque. Then, install the cap.



Tightening torque: 11 ± 1 N·m (~~8 ± 1 ft·lb~~) <Incorrect>

6. Check that the brake fluid level is between "MAX" and "MIN" of the brake fluid reservoir.

97 ± 8 in·lb <Correct>