



Preliminary Information

PIC3074F Performance Of XM Radio System With Sunroof Fully Open

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro	2010 - 2015	All	All	All	All
Chevrolet	Monte Carlo	2003 - 2007	All	All	All	All
Pontiac	Grand Prix	2004 - 2008	All	All	All	All

Supersession Statement

This PI was superseded to update model years. Please discard PIC30745E.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

A customer may experience poor reception or no XM signal, with sunroof fully opened. Because the sunroof travels over the XM antenna at the rear of the roof, the signal may be blocked. This is a characteristic of this antenna and sunroof system. Please review the vehicle owner's manual for further details on system operation.

Recommendations / Instructions

If you experience signal performance issues on XM band only with the sunroof open, move the sunroof forward enough to allow the XM Radio a direct signal from a satellite or repeater to the antenna. If the signal performance issue is corrected, no further action is required.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS