

**Rear Wiper Arm Cover Falls Off**

**Vehicles Affected**

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	2019	9YA	N/A	N/A

**Revision History**

Revision	Release Date	Changes
0	February 1, 2019	Original document

**Customer Concern**

The rear wiper arm cover falls off of the vehicle.



**Technical Background**

The attachment tabs were insufficient to hold the cover on the wiper arm.

**Service Information**

Install new wiper arm cover with part number 974.955.435.B. Do not use the previous cover with index A. PET is accurate with this information.

5	974 955 435 A	Cover cap No longer use the part here
▶ 5	974 955 435 B	Cover cap
6	974 955 427 A	wiper blade

### Production Information

The new wiper arm cover was implemented in production on 11/20/2018.

### Warranty

Cause
92413 Wiper arm cov
1511 Broken into p

Labor operation: 92411900

The encoding of the cause of failure for the rear wiper arm cover is 92413.

### Search Items

wiper; wiper blade; wiper cover; blade cover; rear wiper; rear blade; rear cover

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

---