Reference	SSM74274
Models	I-PACE / X590
Title	I-Pace High Voltage System - TA Escalation Process
Category	Driveability
Last modified	12-Feb-2019 00:00:00
	12 1 65 26 16 66.66.66
Symptom	614000 Lack/Loss of Power

Content

Issue:

Recent visits to retailers to resolve concerns with the High Voltage (HV) Traction Battery have shown a number of concerns have been identified with the 12V system.

Some functions within the HV Traction Battery can be inhibited if concerns are detected with the 12V circuit.

The 12V circuit concerns must be addressed before any diagnosis is done with the HV Traction Battery.

Action:

As a result of the retailer visits, the PathFinder Guided Flow procedures for the HV Traction Battery are being revised. As an interim process to assist with accurate diagnosis, use the procedure below before raising a Technical Assistance (TA) for HV Traction Battery concerns.

Process:

This SSM is relevant to the Instrument Cluster warning messages listed below:

- Battery fault detected
- High Voltage system fault detected
- · High Voltage shut down not possible. System live.

Step 1. Connect PathFinder and check DTCs:

a) If DTC U3000-04 is present in the Battery Energy Control Module (BECM), the 12V system must be checked first - do Procedure A.

b) If the code U3000-04 is not present in the BECM continue with Step 2

Step 2. Refer to the DTC list in Appendix A:

If any of the DTCS in Appendix A are present in the BECM, do Procedure C, otherwise do Procedure B

Procedure A - Check 12V System

Test 12V system:

- 1. Put vehicle into 'Sleep mode':
 - · Open bonnet and latch the RH bonnet latch
 - Close all doors
 - · Lock the vehicle
 - Wait for vehicle networks to shut down (sleep mode). This is typically 20 minutes and the Hazard Light Switch illumination will be OFF
- 2. Test the 12V batteries. Use the procedure 'Determining Battery Condition' in TOPIx Section 414-00A / Battery Care Requirements / Diagnosis and Testing / Section 4.6.

NOTE: It is recommended to use the Midtronics GRX-3080 battery tester (GR8 - USA and Japan only). Where the GRX-3080 & GR8 are unavailable, use the EXP-1080.

3. When both the 12V batteries have passed, and the 12V system is operating correctly, continue with Step 2.

Procedure B - Check BECM data and raise TA

Connect PathFinder:

- Navigate to ECU Diagnostics > Battery Energy Control Module (BECM) > ECU Functions
- Select 'Display HV Battery Pack Voltage Information' and run the routine
- · Exit PathFinder session
- · Log out of PathFinder
- From the desktop, use the 'PathFinder Sessions Extractor' tool and save the session
- Create a TA
- State SSM 74274 in the Customer Comments field
- Select 'EV Electric Vehicle Warning message displayed' from the symptom list
- · Attach the saved session .zip file
- Describe Primary and Secondary diagnostics completed
- Submit the TA

Procedure C - Check BECM and BEM data and raise TA

Connect PathFinder:

- Navigate to ECU Diagnostics > Battery Energy Control Module (BECM) > ECU Functions
- Select 'Display HV Battery Pack Voltage Information'
- · When the routine is complete, select 'Exit'
- · Select 'Live Data'
- Using the search function, select each of the 9 DIDs listed below :
- DID 490F Electric Vehicle Battery Pack Voltage
- DID 4900 Electric Vehicle Traction Contactor Voltage
- DID 4901 Electric Vehicle Auxiliary Contactor Voltage
- DID 490D Electric Vehicle Front Inverter Fuse Voltage
- DID 490B Electric Vehicle Rear Inverter Fuse Voltage
- DID 490E Electric Vehicle Auxiliary Fuse Voltage
- DID 491F Electric Vehicle Traction Contactor Differential Voltage Measured
- DID 491E Electric Vehicle Auxiliary Contactor Differential Voltage Measured
- DID 4909 Electric Vehicle Negative Contactor Voltage
 - · Select 'Start Digital'
 - Press and release the Start/Stop button to turn ignition on and wait for the Live Data readings
 - Select 'Create PDF'
 - Press and release the Start/Stop button to turn ignition off
 - Press the footbrake firmly
 - Press and release the Start/Stop button to enter 'Ready' mode and wait for the Live Data readings
 - Select 'Create PDF'
 - · Press and release the Start/Stop button to turn off
 - · Exit PathFinder session
 - · Log out of PathFinder
 - From the desktop, use the 'PathFinder Sessions Extractor' tool and save the session
 - Raise a TA
 - State SSM 74274 in the Customer Comments field

- Select 'EV Electric Vehicle Warning message displayed' from the symptom list
- · Attach the saved session .zip file
- Describe Primary and Secondary diagnostics completed
- Submit the TA

APPENDIX A

HV Traction Batte	ery DTC List:
--------------------------	---------------

- P0A0A-xx High Voltage System Interlock Circuit
- P0A1F-xx Battery Energy Control Module
- P0A95-xx High Voltage Fuse "A"
- P0AA0-xx Hybrid/EV Battery Positive Contactor Circuit
- P0AA6-xx Hybrid/EV Battery Voltage System Isolation Fault
- P0ABA-xx Hybrid/EV Battery Pack Voltage Sense "A" Circuit
- P0ABF-xx Hybrid/EV Battery Pack Current Sensor "A" Circuit
- P0ADD-xx Hybrid/EV Battery Negative Contactor Control Circuit/Open
- P0AE1-xx Hybrid/EV Battery Precharge Contactor Circuit
- P0AF8-xx Hybrid/EV Battery System Voltage
- P0B0E-xx Hybrid/EV Battery Pack Current Sensor "B" Circuit
- P0B33-xx High Voltage Service Disconnect Circuit
- P0D34-xx Hybrid/EV Battery System Current
- P0D4C-xx Battery Charger Hybrid/EV Battery Output Voltage Sensor Circuit
- P0E2F-xx High Voltage Fuse "B"
- P0E30-xx High Voltage Fuse "C"
- P3035-xx Hybrid/EV Battery Traction Positive Contactor Control Circuit
- P3049-xx Hybrid/EV Battery Charger "A" High Voltage Supply Circuit
- P304A-xx Power Convertor A High Voltage Supply Circuit
- P304B-xx Electric Booster Heater (PTC Heater) High Voltage Supply Circuit
- P304C-xx Electric Air compressor High Voltage Supply Circuit
- P304D-xx Front Electric Motor Inverter High Voltage Supply Circuit
- P304E-xx Rear Electric Motor Inverter High Voltage Supply Circuit
- P304F-xx Hybrid\EV Battery Contactor A
- P3050-xx Hybrid\EV Battery Contactor B
- P3051-xx Hybrid\EV Battery Contactor C
- U3000-04 Control Module System Internal Failures
- U3000-47 Control Module Watchdog / Safety Microcontroller Failure
- U3000-48 Control Module Supervision Software Failure
- U3000-56 Control Module Invalid / Incomplete Configuration

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

- 1 = Poor Basic information provided The SSM does not help me resolve the customer concern.
- 3 = Average Adequate information provided The SSM partially helps me resolve the customer concern.
- 5 = Excellent All required information provided to resolve the customer concern.