OM651 Exhaust Bracket Cracking

Topic number LI49.10-N-060969

Version 6

Function group 49.10 Exhaust pipes, catalytic converter, mufflers

Date 08-10-2017

Validity Sprinter Model 906 with engine OM651

Reason for change Added inspect additional bracket to Remedy

Reason for block

Complaint:

Rattling noise from under vehicle

Cause:

Possible causes:

- 1 Exhaust bracket to transmission (DPF to Transmission) cracked / broken (Pic.1)
- 2 Transmission bell housing cracked / broken (Pic. 2)
- 3 Exhaust bracket to cylinder crankcase (DPF to Engine) cracked / broken (Pic. "EPC OM651" #217)

Attachments	
File	Description
Pic 1.jpg	Broken exhaust bracket to transmission
Pic 2.JPG	Transmission bell housing cracked

Remedy:

1 - Inspect and replace exhaust bracket to transmission (DPF to Transmission) as needed. (Pic. "EPC OM651" #550) & (Pic. 3)

Example pictures of new exhaust bracket to transmission (DPF to Transmission) (Pic. 4, 5, & 6)

Note: Mounting screw locations exhaust bracket to transmission (DPF to Transmission) (Pic. 7 & 8)

- 2 Inspect bell housing for damage and replace as needed. (Pic. 2)
- 3 Inspect and replace exhaust bracket at cylinder crankcase (DPF to Engine) as needed. (Pic. "EPC OM651" #217) Installation sequence of the new exhaust brackets are crucial.

Follow the exhaust bracket installation instructions below:

Positioning of the exhaust system - (Pic. "Positioning of the exhaust system")

- 1. Position and fit exhaust system in place
- 2. Push the exhaust system forward, mount the bracket and tighten screw lightly
- 3. Screw bolts in engine mount and V-mounting by hand (2 turns)

Tightening sequence of the exhaust system - (Pic. "Tightening sequence of the exhaust system)

- 1. Tighten screws at engine mounting (25Nm)
- 2. Tighten screws at V-mounting (25Nm)
- Tighten bracket (15Nm)

Attachments	
File	Description
EPC OM651 exhaust.JPG	EPC parts description
Pic 3.jpg	Location of DPF to Transmission bracket

XENTRY TIPS

Pic 4.JPG	DPF bracket to transmission has extra hole for mounting
Pic 5.JPG	DPF bracket to transmission has extra hole for mounting see part number
Pic 6.JPG	DPF bracket to transmission rear view
Pic 7.JPG	Location of mounting screws
Pic 8.JPG	Loaction of mounting screws view 2
Positioning of the exhaust system.JPG	Positioning of the exhaust system
Tightening sequence of the exhaust system.JPG	Tightening sequence of the exhaust system

Symptoms


Power generation / Exhaust system / Noises / Rattling

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 906 492 12 00			Exhaust bracket 4x2	1	New DPF Bracket to transmission	Х
A 906 492 13 00			Exhaust Bracket 4x4	1	New DPF Bracket to transmission	Х
N 000000 000276			Hex Bolt M8x20	1	Additional screw needed for New DPF bracket to transmission	Х
A 906 492 08 42			Bracket exhaust system at cylider crankcase	1	DPF to Engine	Х

Operation numbers/damage codes						
Op. no.	Operation text	Time	Damage Note code			
49-6960	REPLACE BRACKET		4901H 38			

Attachments

EPC OM651 exhaust. JPG:



Pic 1.jpg:



Pic 2.JPG:



Pic 3.jpg:



Pic 4.JPG:



Pic 5.JPG:




Pic 6.JPG:



Pic 7.JPG:




Pic 8.JPG:



Positioning of the exhaust system.JPG:

Positioning of exhaust system



- Position and lay down exhaust system
- Push exhaust system forward, mount bracket and tighten screw lightly
- Screw bolts in engine mounting and Vmounting by hand (2 turns)

Tightening sequence of the exhaust system.JPG:

Screwing the exhaust system

