



SERVICE BULLETIN

Classification:

EC19-009

Reference:

NTB19-023

Date:

March 5, 2019

2017-2018 VERSA; MIL ON WITH DTC P050B

APPLIED VEHICLES: 2017-2018 Versa (N17)

IF YOU CONFIRM

The Malfunction Indicator Light (MIL) is ON with Diagnostic Trouble Code (DTC) P050B (Cold Start Control) stored in the Engine Control Module (ECM).

ACTION

Reprogram the ECM, if applicable.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

Reprogram the ECM

IMPORTANT: Before starting the reprogramming procedure, make sure:

- ASSIST on the CONSULT PC has been synchronized (updated) to the current date.
- All CONSULT- III plus (C-III plus) software updates (if any) have been installed.
- The CONSULT PC is connected to the Internet (Wi-Fi or cable).

NOTE:

- If you are not familiar with the reprogramming procedure, *click here*. This will link to the "CONSULT- III PLUS (C-III PLUS) ECM Reprogramming" general procedure.
- Take the vehicle for a 10 minute drive in order to meet the following Idle Air Volume Learn (IAVL) conditions:
 - Engine coolant temperature: 70-100°C (158-212°F)
 - Battery voltage: More than 12.9V (At idle)
 - Transmission: Warmed up
- After reprogramming is complete, it is required to perform Throttle Valve Closed Position, Idle Air Volume Learn, Accelerator Closed Position, and DTC Erase.



Figure 1

CAUTION:

- Connect the GR8 to the 12V battery and select ECM Power Supply Mode. If the vehicle battery voltage drops below 12.0V or above 15.5V during reprogramming, the ECM may be damaged.
- Be sure to turn OFF all vehicle electrical loads. If a vehicle electrical load remains ON, the ECM may be damaged.
- Be sure to connect the AC Adapter. If the CONSULT PC battery voltage drops during reprogramming, the process will be interrupted and the ECM may be damaged.
- Turn OFF all external Bluetooth® devices (e.g., cell phones, printers, etc.) within range of the CONSULT PC and the plus VI. If Bluetooth® signal waves are within range of the CONSULT PC and the plus VI during reprogramming, reprogramming may be interrupted and the ECM may be damaged.

- Using C-III plus, confirm the current ECM part number and write it on the repair order.
 - If it matches one of the part numbers in **Table A**, reprogram the ECM.
 - If it does not match any of the part numbers in **Table A**, this bulletin does not apply. Go back to ASIST for further diagnostic and repair information.

Table A

MODEL	CURRENT ECM PART NUMBER: 23710-
2017 Versa	9KS1A, 9KS1B, 9KS1C, 9KS1D
	9KS2A, 9KS2B, 9KS2C, 9KS2D
	9KS3A, 9KS3B, 9KS3C, 9KS3D
2018 Versa	9KZ0B, 9KZ0C
	9KZ1B, 9KZ1C
	9KZ2B, 9KZ2C

- After completing Erase ALL DTCs, print a copy of the C-III plus screen showing the before and after part numbers of the control unit and attach it to the repair order.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Reprogram the ECM	(1)	DE97AA	ZE	32	(2)

- Reference the electronic parts catalog, and use the ECM part number (23703-*****) as the Primary Failed Part (PFP).
- Reference the current Nissan Warranty Flat Rate Manual and use the indicated Flat Rate Time (FRT).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
March 5, 2019	NTB19-023	Original bulletin published