



H188 UPS0519-2BNAS1

TECHNICAL BULLETIN

20 MAR 2019

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

501-10

SUBJECT/CONCERN:

Update Prior to Sale: Incorrect Function of Climate Seat Control from Touchscreen (TS)

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
I-PACE (X590)	2019	F60202-F67369	Graz (Austria)

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

A potential issue has been identified on certain Jaguar vehicles within the listed Affected Vehicle Range, with climate control seats, where after selecting the seat squab icon on the Touchscreen, the function turns ON and then OFF.

ACTION:

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the Diagnostic/Workshop Procedure detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

This program does not apply to any vehicle already registered and in use, either with the retailer or customer. Any vehicle already in use may continue to be driven and any repair instructions deemed necessary will be communicated through a separate bulletin.

PARTS:

No parts required.

SPECIAL TOOLS:

Jaguar Land Rover-approved Battery Power Supply

Jaguar Land Rover-approved diagnostic equipment with latest PATHFINDER software

WARRANTY:**NOTE:**

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all open Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code and the relevant Option Code; this will result in payment of the stated time. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times/prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the January 25, 2020, closure date must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER/SUNDRY CODE	QUANTITY/VALUE
H188	A	Car Configuration File - Update ECU	86.99.94	0.2	-	-
H188	B	Car Configuration File - Update ECU Drive in/drive out	86.99.94 10.10.10	0.2 0.2	- -	- -

Normal Warranty policies and procedures apply.

DIAGNOSTIC PROCEDURE:

CAUTIONS:

- A Jaguar Land Rover-approved battery power supply must be connected to the vehicle startup battery during diagnosis / module programming.
- All ignition ON/OFF requests MUST be performed; failure to do so may cause damage to vehicle control modules.

1 Connect the Jaguar Land Rover-approved battery power supply to the vehicle startup battery.

2

 **NOTE:**

The Jaguar Land Rover-approved diagnostic equipment must be loaded with PATHFINDER version 224 (or later).

Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

3

 **NOTE:**

The Jaguar Land Rover-approved diagnostic equipment will read the correct Vehicle Identification Number (VIN) for the current vehicle and automatically take the vehicle out of Transit mode (if required).

Follow the on-screen prompts.

4

Select **Service** .

5

Select **Select CCF**.

6

Select **Copy from AS BUILT**.

- 1 Follow the on-screen instructions until the application finishes successfully.
- 2 Go to the next Step.

7

Exit the current session.

- 1 If required, reset the vehicle to **Transit mode**.
- 2 Select the **Exit** icon.

8

Exit the current session.

- 1 If required, reset the vehicle to **Transit mode**.
- 2 Select the **Exit** icon.

9

 **CAUTION:**

After the CCF (Car Configuration File) update, the vehicle may display a 'Brake Pedal Reduced Feeling' warning message on the Instrument Cluster.

 **NOTE:**

The vehicle will take approximately 6 minutes to enter sleep mode.

Disconnect the diagnostic equipment and battery power supply from the vehicle.

- 1 If the message 'Brake Pedal Reduced Feeling' is not displayed, no further action is required. Return the vehicle to the customer.
- 2 If the message 'Brake Pedal Reduced Feeling' is displayed, perform a vehicle sleep cycle.
 - Switch the ignition OFF.
 - Close all doors, hood, and tailgate.
 - Lock the vehicle.
 - Wait for the hazard warning switch illumination to extinguish.
 - Unlock the vehicle.

10 Connect the Jaguar Land Rover-approved battery power supply to the vehicle startup battery.

11 Connect the Jaguar Land Rover-approved diagnostic equipment to the vehicle and begin a new session.

12 Follow all on-screen instructions.

13

 **NOTE:**

DTC (Diagnostic Trouble Code) U2012-87 may be stored in the Brake Booster Module (BBM).

Select **ECU Diagnostics**.

14 Select **All DTCs**.

15 Select **Clear all DTCs**.

1 Follow the on-screen instructions until the application finishes successfully.

16 Exit the current session.

1 If required, reset the vehicle to **Transit mode**.

2 Select the **Exit** icon.

17 Disconnect the diagnostic equipment and battery power supply from the vehicle.